

151 Chin Swee Road #10-03/05 Manhattan House Singapore 169876 T: +65 6955 8899 F: +65 6900 9899 E: enquiry@aplp.com.sg

We do not accept service of Court documents by fax

11374282

Our ref: AP/2020/002466/tat/jl

WITHOUT PREJUDICE

Your ref: SMJ 2024L

TAN KAIJUN KELVIN

12 Rivervale Link #05-23 Singapore 545045 BY POST

[for your information only]

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#24-01 AXA Tower Singapore 068811

Attn: Motor Claims

Date: 1 April 2020

Dear Sirs,

BY HAND

Secretary in charge: Seng Tat

Secretary's email: sengtat@aplp.com.sg

CLAIMANT: LUMENS AUTO PTE LTD
CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT INVOLVING VEHICLES NO. SMM 4109Y,
SMJ 2024L AND SGX 9071B ON 21 DECEMBER 2019 AT 1150 HOURS ALONG KPE

INSURANCE PTE

S 6 APR 2020

MAILROOM

We refer to the above matter.

We act for LUMENS AUTO PTE LTD, the owner of SMM 4109Y.

We are instructed by our clients to claim damages against you in connection to the above-mentioned road traffic accident involving our clients' vehicle and your vehicle bearing registration number **SMJ 2024L**.

We are instructed that the above-mentioned road traffic accident was caused by your negligence/ negligence of your authorised driver in the driving, management and/or control of your vehicle.

As a result of the abovementioned road traffic accident, our clients' vehicle was damaged and our clients has been put to loss and expense, particular of which are as follows:

Costs of repair

\$ 6,800.00

\$ 1,080.00

Loss of use

Pre-repair \$ 240.00 (2 days including intervening weekend x \$120.00 per day)

- Loss of use/rental During repair works \$ 840.00 (7 days including intervening weekend x \$120.00 per day)

\$ 1,500.00

Our Legal Costs



^ April 2020

Our ref: AP/2020/002466/tat

Disbursements (incurred to-date)

\$ 573.49

-	Survey report fees	\$ 437.00
-	GIA/LTA search/document fee	\$ 36.49
-	Other Incidentals	\$ 100.00

Total

\$ 9,953.49

A copy each of the following supporting documents is enclosed:

- (a) Singapore Accident Statement of SMM 4109Y;
- (b) Singapore Accident Statement of SMJ 2024L:
- (c) Repair bill from My Car Consultant Pte Ltd;
- (d) Motor surveyor's report by WG Appraisal Services;
- (e) Survey report invoice;
- (f) GIA/LTA searches invoices;

In compliance with the pre-action protocol under the State Courts' Practice Direction 37, we had notified your insurer, **AXA INSURANCE SINGAPORE PTE LTD**, of the above-mentioned road traffic accident and to the best of our knowledge, your insurer had arranged for the pre-repair inspection of our client's vehicle.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt to us within fourteen (14) days of your receipt of this letter, failing which, our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you a counterclaim against our client arising out of the above-mentioned accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully,

Charles Hook

My Car Consultant Pte Ltd

53, Ubi Avenue 1, Paya Ubi Industrial Park #01-33, Singapore 40934

HP:9888 8885 (Jeremy)

	LUMENS AUTO PTE LTD		Invoice No. Our Ref. Your Ref.	D. MYCAR/20/41 SMM4109Y 05 February 2020	
1	Description To supply labour and materials to repair below mentioned vehicle to its pre-accident condition. Vehicle: SMM4109Y Make/Model: TOYOTA NOAH HYBRID 1.8X CVT Accident Date: 21 December 2019	Qty	Unit Price	Total	
			Amount Due	\$6,800,00	

Authorised	Signatory	
------------	-----------	--

WG APPRAISAL SERVICES

Blk 224B, Compassvalve Walk, #07-647.Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063

Company Register No. 53326249J

Date 05 February 2020

Our Ref:

WG/TP/2020-41

Invoice No:

TP/MCC/2020-41

Vehicle No:

SMM4109Y

Attn:

LUMENS AUTO PTE LTD

Company:

MY CAR CONSULTANT PTE LTD

Address:

53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934

Invoice

Surveyor Fee:

S\$290

Re-inspection Fee:

S\$50

Transport:

S\$50

Photographs:

 S47/_{7}$ (@ \$1 per photo, total 47 photos)

Total:

S\$437

Surveyor:

Signature:

Date:

05 February 2020

WG APPRAISAL SERVICES

Blk 224B, Compassvalve Walk, #07-647. Singapore 542224 Email: winsongkk@hotmail.com Contact: 9747 0063 Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S: LUMENS AUTO PTE LTD

C/O MY CAR CONSULTANT PTE LTD 53 Ubi Ave 1, #01-33. Paya Ubi Industrial Park

Singapore 408934

Date Our Ref

: 05 February 2020

: WG/TP/2020-41

REFERENCE PARTICULARS

Date of Accident

21 December 2019

Date of Inspection

: 26 December 2019

Type of Inspection

Third Party Claim

Date of Re-Inspn

: 26 December 2019

VEHICLE PARTICULARS

Registration No.

= SMM4109Y

Make Model

TOYOTA

: NOAH HYBRID 1.8X CVT 1 2019

Engine No

2ZR0D57339

Chassis No

: ZWR800384293

Odometer

56969km

Colour

. Black

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condi ion

Good

Foot Brake

Front Near sice

Front Off Side

Rear Near Side

Rear off Side

: Serviceable

Hand Brake

: Serviceable

General Body Work

: Good

Steering

Serviceable

Lightings

: Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

Make : Goodyear : Goodyear

Goodyear

Goodyear

Size 195/65R15 195/65R15

Thread Balance 5 mm

5 mm

195/65R15

195/65R15

5 mm 5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portion.

For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was \$\$6,800.00 nett at lump sum basis.(Subject to GST if applicable)

Under normal circumstances, estimated period required for repairs : Seven (07) working days.

Enclosed Fourty-Seven (47) photographs depicting damage to the vehicle.

Inspection conducted at | MY CAR CONSULTANT PTE LTD 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park . Singapore 408934 In accordance to your instruction, we have **not authorise** repairs and inspection was conducted strictly on a "<u>WITHOUT PREJUDICE BASIS</u>".

NOAH HYBRID 1.8X CVT

Our Ref . WG/TP/2020-41

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS	AND NATURE OF REPAIRS
----------------------	-----------------------

	CRAPP PARTS	QTY	ASSESSED		ORIGINAL		REVISED
	SPARE PARTS	PC/SET	CONDITION		QUOTATION		QUOTATION
1	TAILGATE	1	DENTED	\$	2,530.10	S	2,530.10 1860
2	TAILGATE HINGE	2	NOT NECESSARY	\$	130.20	\$	Xnn
3	TAILGATE LOCK	1	JAMMED	S	488.75	\$	488.75 368 95
4	TAILGATE STRIKER	1	BENT	S	55.00	s	55.00
5	TAILGATE INNER TRIM	1	CRACKED	\$	690.00	s	690.00 495
6	TAILGATE WEATHERSTRIP	1	DEFORMED	\$	410.55	s	410.55 3 68
7	TAILGATE CHROME GANRISH - NOAH	1	CRACKED	\$	316.25	s	315.25
8	REAR BUMPER	1	DEFORMED	\$	672.75	s	672.75
9	REAR BUMPER RETAINER	2	NECESSARY	S	149.50	s	149.50
0	REAR BUMPER REFLECRTOR	2	NOT NECESSARY	\$	90.00	\$	- × ^ ^
1	REAR TAILAMP	2	NOT NECESSARY	S	1,037.30	\$	260
2	REAR LOCK SENSOR	1	MALFUNCTION	\$	319.40	s	- X A A
3	END PANEL - INNER	1	DENTED	S	402.50	s	319.40 /62.20 402.50 €×
4	END PANEL - OUTER	1	DENTED	S	442.75	\$	442.75
5	END PANEL INNER TRIM	1	DEFORMED	\$	238.05	s	
6	REAR WIDSCREEN MOULDING	4	NECESSARY	s	133.40	S	238.05 / 8 <u>2</u> 133.40
7	PEC SENSOR	4	MALFUNCTION	\$	540.00	s	270.00
				\$	8,646,50	<u>s</u>	7,118.00 549
			Les	s 25% \$	2,161.62	S	
				\$	6,484.88	5	1,779.50 5,338.50 4 06.
)	S/YETT ITEM						3,336.30
,	Water the second						
,)	TAILGATE INNER TRIM CLIP REAR BUMPER CLIP	1 SET	NECESSARY	S	30.00	\$	20.00
)		1 SET	NECESSARY	\$	30.00	\$	20.00
	WINDSCREEN SEALANT JOINT SEALANT	1	NECESSARY	\$	120.00	\$	100.00 60
	JOHNI SEALANI	1	NECESSARY	_\$	120.00	\$	100.00 50
				5	300.00	s	240.00
			Parts Total:	<u>s</u>	6,784.88	s	5,578.50
	LABOUR CHARGES & MISC						
	CHECK ALL WIRING AND LIGHTNING SYSTEM	30		H.a.	NOT THE		211
	REMOVE, REFIT TRIM AND GANRISH 60		E) HILL	. 40 -	mec- gl	·	to Con
	REMOVE AND RENEW RER REVERSE SENSOR	30					STATE OF THE STATE
	REMOVE AND STRAIGHTEN REAR EXHAUST A		11 4 418	674 6	- MCC +	TO.	NO LOS PROPERTIES

- 26 REMOVE AND REFIT REAR WINDSCREEN 120 100
- 27 TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW 60
- 28 PANEL BEATING ON AFFECTED AREAS
- 29 SPRAY PAINTING ON AFFECTED AREAS
- 30 APPLY ANTI RUST ON AFFECTED AREAS

JF # (3	1.40-	MCC - 9	672	75 Lon	,
A) \$41	1.60	- MCC#	1540		
		1,200.00			700
				1,000.00	
	3	1,400.00	\$	1,200.00	800
	\$	120.00	\$	100.00	40
r Total :	<u>s</u>	3,490.00	s	2,950.00	1846

A contract of the contract of						
Total Parts and Laboure a	5	10,274.88	5	8,528.50		

FINAL LUMP SUM ADJUSTMENT

8,528.50 6096.10 6,800.00 L/S\$4900 06 days

Labou

Automobile Consultants, Insurance Loss Assessors/Adjusters, Inspection and Evaluation

POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.

The damages appeared to be consistent as per the accident report statement.

Please refer the attached schedule and photographs for details.

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$6,800.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfull

Winson Goh

Automotive Appraiser







































































