To: AXA INSURANCE PTE LTD

C/O: SEAH ONG & PARTNERS LLP

Our Ref.: SVY190200157

Date: 08/03/2019

36 ROBINSON ROAD #12-03 CITY HOUSE SINGAPORE 068877

AUTOMOBILE INSPECTION REPORT

1. SURVEY TYPE: THIRD PARTY

Vehicle Inspected: SLB-2366-D Your Reference: 19.26452 PD-O

Insured Vehicle: YP -7947-S Policy Excess:

Assigned by: MR TAN CHEE KIONG Assignment Date: 21/02/2019

Date of Accident: 15/10/2018 Surveyed / Assessed Date: 25/02/2019

Repairer / Survey at: KUM CHEW MOTOR

2. VEHICLE PARTICULARS:

Make & Model: SUBARU XV 1.6I-S General Condition: **FAIR** Registration Date: 31/03/2016 Colour: **GREY** Odometer (km): Engine Capacity: 1600 76077 Chassis No.: JF1GP3KC5GG167385 Steering: **IN ORDER**

Engine No.: FB16Y172919 Brake: IN ORDER

3. TYRE CONDITION:

	Size	Make	Thread Depth (%)
FRONT LEFT	225/55R17	YOKOHAMA	20
FRONT RIGHT	225/55R17	YOKOHAMA	20
REAR LEFT	225/55R17	YOKOHAMA	30
REAR RIGHT	225/55R17	YOKOHAMA	30

4. DESCRIPTION OF DAMAGES:

The vehicle sustained damages mainly at the rear left portion.

Your Ref.: 19.26452 PD-O Vehicle No.: SLB-2366-D

Our Ref.: SVY190200157 Date of Accident: 15/10/2018

5. ADJUSTMENT SUMMARY:

Original Estimate: \$8,721.04 Revised: \$4,731.44

Final Adjustment: \$3,800.00 (Lump Sum)
Estimated Repair Duration: 5.00 Working Days

6. ESTIMATED VALUE (at time of accident):

Market Value: \$70,000.00

LTA Rebate: \$44,975.00 (as at 18/10/2018)

Nett: \$25,025.00

7. SPECIAL REMARKS

- Pre-repair inspection conducted on 18/10/2018.
- Post-repair inspection conducted on 24/10/2018.

The Inspection was conducted on a "Without Prejudice" basis.

Assessor: TAY BH

 Your Ref.: 19.26452 PD-O
 Vehicle No.: SLB-2366-D

 Our Ref.: SVY190200157
 Date of Accident: 15/10/2018

ADJUSTMENT DETAILS

QTY	DESCRIPTION (PARTS)	CONDITION	ESTIMATE	REVISED
1	TAILGATE	REPAIR	\$1,523.00 L	- L
1	TAILGATE EMBLEM (SUBARU)	NECESSARY	\$79.20 L	\$79.20 L
1	TAILGATE EMBLEM (AWD)	NECESSARY	\$64.80 L	\$64.80 L
1	TAILGATE EMBLEM (XV)	NECESSARY	\$64.80 L	\$64.80 L
1	TAILGATE OUTER MOULDING	AFFECTED	\$260.00 L	\$260.00 L
1	TAILGATE EMBLEM (LOGO)	NECESSARY	\$80.00 L	\$80.00 L
1	TAILGATE INNER TRIM	REUSE	\$353.00 L	- L
1	TAILGATE INNER TRIM CLIPS (SET)	NECESSARY	\$35.20 L	\$35.20 L
1	TAILGATE LOCK	REUSE	\$270.00 L	- L
1	TAILGATE W/STRIP	AFFECTED	\$111.60 L	\$111.60 L
1	TAILGATE LOCK ANTENNA	AFFECTED	\$177.00 L	\$177.00 L
2	TAILLAMP R/L	RH SERVICEABLE	\$964.00 L	\$482.00 L
1	RR BUMPER	DEFORMED	\$863.00 L	\$863.00 L
1	RR BUMPER FOG LAMP	AFFECTED	\$92.20 L	\$92.20 L
1	RR BUMPER TOW HOOK COVER	DEFORMED	\$14.60 L	\$14.60 L
1	RR BUMPER REINFORCEMENT	BENT	\$320.00 L	\$320.00 L
1	RR BUMPER CLIPS (SET)	NECESSARY	\$21.60 L	\$21.60 L
2	RR BUMPER RETAINERS	NECESSARY	\$36.00 L	\$36.00 L
2	RR BUMPER BRACKETS	NECESSARY	\$32.80 L	\$32.80 L
1	RR END PANEL	DENTED	\$672.80 L	\$672.80 L
1	RR END PANEL GARNISH	REUSE	\$164.00 L	- L
1	RR END PANEL GARNISH CLIPS (SET)	NECESSARY	\$19.20 L	\$19.20 L
1	RR TOOL SPONGE	SERVICEABLE	\$265.00 L	- L
1	EXHAUST MUFFLER	REUSE	\$880.00 L	- L
1	TAILGATE GLASS INNER SEAL	NECESSARY	\$20.00 S	\$20.00 S
1	TAILGATE GLASS SEALANT	NECESSARY	\$40.00 S	\$40.00 S
1	REVERSE SENSORS (SET)	DAMAGED	\$220.00 S	\$220.00 S
1	RR END PANEL SEALANT	NECESSARY	\$40.00 S	\$40.00 S
		 Subtotal	\$7,683.80	\$3,746.80
	List Item Discount on L Items 20.00% / 20.00%		(\$1,472.76)	(\$685.36)
		 Total Parts	\$6,211.04	\$3,061.44

 Your Ref.: 19.26452 PD-O
 Vehicle No.: SLB-2366-D

 Our Ref.: SVY190200157
 Date of Accident: 15/10/2018

DESCRIPTION (LABOUR & MISC.)	ESTIMATE	REVISED
TO CHECK REAR ELECTRICAL WIRING SYSTEM.	\$50.00	\$30.00
TO TRANSFER REAR W/SCREEN TO NEW TAILGATE.	\$120.00	-
TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE.	\$100.00	-
TO REMOVE & REFIT REAR REVERSE CAMERA.	\$50.00	\$50.00
TO REMOVE, REPLACE & REINSTALL REAR REVERSE SENSORS & CONTROL UNIT.	\$50.00	\$50.00
TO SPRAY ANTI-RUST COATING ON NEW & AFFECTED PANELS.	\$60.00	\$60.00
TO REMOVE & REINSTALL REAR INTERIOR TRIMS, GARNISH, ETC FOR NECESSARY REPAIRS.	\$120.00	\$80.00
TO STRAIGHTEN, REPAIR, REALIGN CENTER EXHAUST PIPE & REPLACE EXHAUST SILENCER.	\$80.00	-
TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA & REPLACE DAMAGED PARTS	\$880.00	\$750.00
TO SPRAY PAINTING.	\$1,000.00	\$650.00
Subtotal	\$2,510.00	\$1,670.00
Total Labour	\$2,510.00	\$1,670.00
<u>Total</u>	<u>\$8,721.04</u>	<u>\$4,731.44</u>