




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SEAH ONG & PARTNERS LLP			Ref : CS/LAW20005623/Kqf3e2	
36 ROBINSON ROAD #12-03 CITY HOUSE SINGAPORE 068877			Date : 20-05-2020	
			Code : L004	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	YP 7947S	Veh. Inspected	SLB 2366D	
Policy No.		Coverage (\$)	0.00	
Claim No.	19.26452	Excess (\$)	0.00	
Assign From	CHEE KIONG	Assign Date	05/05/2020	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU XV (A)	c.c	1600	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JF1GP3KC5GG167385	Colour	METALLIC GREY	
Odometer	131810	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	CONTINENTAL	7 mm	
L/H Front Tyre	225/55 R17	CONTINENTAL	7 mm	
R/H Rear Tyre	225/55 R17	CONTINENTAL	7 mm	
L/H Rear Tyre	225/55 R17	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	15/10/2018	Inspection Date	11/05/2020	
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	