

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005639/BGA3Q2

Date: 19/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070991

Claimant
Vehicle No : GBG7556G **Insured Vehicle No :** GBD3266K

Date of Loss: 08/05/2020 Nature of Claim: TP Claim No: 1587215759SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG7556G	Engine No:	D4CBG053233
Make & Model:	HYUNDAI H-1 STAREX, 2.5 D CRDi (A)	Chassis No:	KMFWBX7KLHU847613
Reg. Date:	24/10/2017 (Man. Year: 2016)	Odometer:	36702 km
Colour:	Silver		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Poor	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/70 R16	Rear Tyre Size:	215/70 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,483.24	14,232.44	11,250.80	44.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,030.00	5,110.00	3,920.00	43.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,513.24	19,342.44	15,170.80	43.96
Approved Total (Overridden) (\$\$)		9,362.00		
Nett Amount (\$\$)	34,513.24	9,362.00	25,151.24	72.87
+ Car Rental (16.0 x S\$80.00/day) (\$\$)		1,280.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		100.00		
Nett Liability (\$\$)		10,749.45		
Global Sum Settlement (\$\$)		10,780.00		

INSPECTION

Date of Assignment: 11/05/2020

Date Inspected: 11/05/2020 Inspected At:

Team Autopro Pte Ltd (Sin Ming)
385 Sin Ming Drive, #01-02 Vicom
Inspection Centre
Singapore 575718

Estimated Period of Repair: 14.0 days

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$48,000.00 - LTA REIMBURSEMENT VALUE: \$38,638.00 = NETT VALUE: \$9,362.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LH	Dented	2,108.30 FL	*2,108.30 FL
2	1		*TAILGATE EMBLEM HYUNDAI	Necessary	78.20 FL	*54.00 FL
3	1		*TAILGATE OUTER GARNISH	Cut	132.50 FL	*132.50 FL
4	1		*TAILGATE INNER TRIM BOARD	Not Damaged	253.10 FL	*- FL
5	1		*TAILGATE INNER HANDLE	Jammed	45.00 FL	*45.00 FL
6	1		*TAILGATE LOCK ASSY	Jammed	128.30 FL	*128.30 FL
7	1		*TAILGATE LOWER LOCK	Jammed	104.80 FL	*104.80 FL
8	1		*TAILGATE LOCK HANDLE	No such part	325.60 FL	*- FL
9	1		*TAILGATE CHECKER	N/s Bent	280.00 FL	*80.00 FL
10	2		*TAILGATE HINGE	Bent	367.80 FL	*187.00 FL
11	1		*TAILGATE STICKER	Necessary	65.00 FL	*20.00 FL
12	1		*TAILGATE WEATHERSTRIP (LEFT HAND DOOR TAILGATE)	Cut	385.30 FL	*145.00 FL
13	1		*REAR WINDSCREEN	Broken	842.30 FL	*842.30 FL
14	1		*REAR WINDSCREEN MOULDING	Necessary	214.00 FL	*214.00 FL
15	1		*WEATHERSTRIP TAILGATE	Cut	415.30 FL	*187.50 FL
16	2		*REAR NO PLATE LAMP	Not Damaged	148.60 FL	*- FL
17	1		*REAR BUMPER	Broken	388.30 FL	*388.30 FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	130.60 FL	*130.60 FL
19	1		*REAR BUMPER BRACKET 3pcs	Broken 1pc Only	255.75 FL	*85.25 FL
20	2		*REAR BUMPER REFLECTOR	Broken 1pc Only	567.20 FL	*58.50 FL
21	1		*REAR BUMPER REINFORCEMENT	Dented	652.30 FL	*347.80 FL
22	1		*REAR BUMPER INNER SPONGE	Broken	204.30 FL	*114.30 FL
23	1		*REAR FENDER LH	Dented	1,873.60 FL	*1,433.00 FL
24	1		*REAR FENDER INNER TRIM BOARD	No such part	214.30 FL	*- FL
25	1		*REAR FENDER INNER COWLING LH	Torn	385.00 FL	*198.00 FL
26	1		*REAR AIR VENT LH	Broken	250.00 FL	*150.00 FL
27	1		*REAR END PANEL	Dented	842.60 FL	*680.00 FL
28	1		*REAR END PANEL TOP GARNISH	Distorted	210.50 FL	*210.50 FL
29	1		*TAILLAMP LH	Broken	488.50 FL	*488.50 FL
30	1		*TAILLAMP BASE PANEL (OUTER) LH	Broken	652.00 FL	*652.00 FL
31	1		*TAILLAMP BASE PANEL (INNER) LH	Dented	458.60 FL	*458.60 FL
32	1		*TAILLAMP LOWER GARNISH LH	No such part	71.90 FL	*- FL
33	1		*TAILLAMP BRACKET LH	Broken	64.80 FL	*64.80 FL
34	1		*TAILLAMP LOWER GARNISH RETAINER	Necessary	68.00 FL	*68.00 FL
35	1		*REAR SIDE PANEL (OUTER) LH	Broken	691.20 FL	*691.20 FL
36	1		*REAR SIDE PANEL (INNER) LH	Dented	874.30 FL	*874.30 FL
37	1		*REAR SIDE PANEL INNER TRIMBOARD LH	No such part	1,352.60 FL	*- FL
38	1		*REAR SIDE INNER LOWER PANEL LH	Not Damaged	652.30 FL	*- FL
39	1		*REAR SIDE LOWER CORNER INNER PANEL LH	Dented	384.60 FL	*384.60 FL
40	1		*FRONT BUMPER	Broken	953.60 FL	*423.00 FL
41	1		*FRONT BUMPER LOWER	Broken	753.90 FL	*355.00 FL
42	2		*FRONT BUMPER SIDE RETAINER	Necessary	175.80 FL	*175.80 FL
43	1		*FRONT BUMPER REINFORCEMENT	Bent	428.70 FL	*320.00 FL
44	1		*FRONT BUMPER INNER SPONGE	Broken	210.50 FL	*175.00 FL
45	1		*FRONT GRILLE	Dislodged	472.30 FL	*424.00 FL
46	1		*FRONT GRILLE LOGO	Cut	85.00 FL	*35.00 FL
47	1		*FRONT GRILLE OUTER CHROME GARNISH	Cut	241.00 FL	*241.00 FL
48	1		*FRONT FOG LAMP LH	Cut	250.00 FL	*250.00 FL
49	1		*FRONT FOG LAMP OUTER GARNISH	No such part	581.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*HEADLAMP LH	Broken	1,182.30 FL	*1,182.30 FL
51	1		*BONNET	Dented	1,402.50 FL	*1,345.00 FL
52	1		*BONNET INNER LOCK	Not Damaged	357.60 FL	*- FL
53	1		*BONNET INNER RUBBER	Not Damaged	210.00 FL	*- FL
54	1		*FRONT SUPPORT PANEL	Not Damaged	1,472.50 FL	*- FL
55	1		*FRONT FENDER LH	Serviceable	987.20 FL	*- FL
56	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
57	1		*TAILGATE SEALANT	Necessary	80.00 FS	*30.00 FS
58	1		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*TAILGATE STICKER 70KM/H	Necessary	30.00 FS	*20.00 FS
61	1		*REAR WINDSCREEN INNER SEAL	Necessary	180.00 FS	*80.00 FS
62	1		*REAR WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
63	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
64	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
65	2		*REAR BUMPER REVERSE SENSOR	Short Circuit	500.00 FS	*200.00 FS
66	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
67	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
68	1		*REAR FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
69	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
70	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
71	1		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS
72	1		*TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
73	1		*REAR SIDE PANEL (OUTER) SEALANT LH	Not Necessary	80.00 FS	*- FS
74	1		*REAR SIDE PANEL (INNER) SEALANT LH	Necessary	80.00 FS	*30.00 FS
75	1		*REAR SIDE PANEL INNER TRIMBOARD SEALANT LH	Not Necessary	80.00 FS	*- FS
76	1		*REAR SIDE INNER LOWER PANEL SEALANT LH	Necessary	80.00 FS	*30.00 FS
77	1		*REAR SIDE LOWER CORNER INNER PANEL SEALANT LH	Necessary	80.00 FS	*30.00 FS
78	1		*REAR NO PLATE W/COWLING	Bent	80.00 FS	*50.00 FS
79	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
80	1		*FRONT BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
81	1		*FRONT NO PLATE W/COWLING	Dented	80.00 FS	*50.00 FS
82	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
83	1		*FRONT FOG LAMP OUTER GARNISH CLIPS	No such part	50.00 FS	*- FS
84	1		*BONNET SEALANT	Necessary	80.00 FS	*30.00 FS
85	1		*BONNET INNER RUBBER CLIPS	Not Necessary	50.00 FS	*- FS
86	1		*FRONT FENDER SEALANT	Necessary	80.00 FS	*30.00 FS
87	1		*REAR FLOOR BOARD	Not Necessary	800.00 FS	*- FS
88	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
89	1		*A/C FLUID	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 30,961.55 17,563.05
- List Item Discount on L Items 20.00/20.00% (\$\$) 5,478.31 3,330.61

Total Parts (\$\$) 25,483.24 14,232.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R REAR WINDSCREEN.	New	200.00	100.00
2	R&R REVERSE SENSOR.	New	100.00	60.00
3	R&R TAILGATE COMPONENT.	New	150.00	80.00
4	R&R REAR FLOOR BOARD.	New	100.00	0.00
5	R&R REAR FUEL TANK PIPE.	New	150.00	80.00
6	CHECK WIRING.	New	100.00	50.00
7	PANEL BEAT REAR.	New	2,400.00	2,000.00
8	SPRAY PAINT REAR.	New	2,000.00	1,000.00
9	RUST PROOFING.	New	200.00	60.00
10	R&R UPHOLSTERY.	New	200.00	0.00
11	R&R REAR SLIDING DOOR.	New	150.00	80.00
12	PANEL BEAT FRONT.	New	1,400.00	800.00
13	SPRAY PAINT FRONT.	New	1,400.00	800.00
14	R&R RADIATOR.	New	150.00	0.00
15	R&R A/C CONDENSER.	New	150.00	0.00
16	DIAGNOSTIC RESET FAULT CODE.	New	180.00	0.00
Gross Labour Cost (\$\$)			9,030.00	5,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >