



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2004066  
INV Date 21/05/2020  
Reference CS/SMO20005640/Evf3n2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. SML 7179E  
Insured Veh. SML 996J  
Claim No. CMTD2001563/AGC  
Policy No.  
Accident Date 06/05/2020  
Inspection Date 18/05/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20005640/Evf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 21-05-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SML 996J	Veh. Inspected	SML 7179E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2001563/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	11/05/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ CLA180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WDD1173422N759874	Colour	RED	
Odometer	17951	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/05/2020	Inspection Date	18/05/2020	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 7179E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	1,376.00	1,376.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	330.00	-
1	FRONT BUMPER SIDE RETAINER RH	BROKEN	53.00	53.00
1	FRONT BUMPER LOWER LIP CHROME CENTER	NOT NECESSARY	310.00	-
1	FRONT BUMPER LOWER LIP CHROME RH	NOT NECESSARY	139.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	139.00	-
1	FRONT BUMPER LOWER GRILLE	CUT	125.00	125.00
2	FRONT BUMPER SENSOR @\$300.00	CUT (1 PC ONLY)	600.00	250.00
1	FRONT BUMPER TOW COVER	TO REPAIR SEE LABOUR	60.00	-
1	FRONT BUMPER LOGO	NECESSARY	65.00	65.00
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	119.00	-
1	FRONT SUPPORT LOWER GARNISH	NOT NECESSARY	178.00	-
1	FRONT GRILLE	BROKEN	248.00	248.00
2	FRONT GRILLE CHROME	CUT	156.00	156.00
1	FRONT GRILLE OUTER GARNISH	NOT NECESSARY	146.00	-
1	RH FRONT HEADLAMP	BROKEN	2,978.00	2,663.00
1	FRONT GRILLE LOGO	CUT	142.00	142.00
1	FRONT GRILLE LOGO BASE	NOT NECESSARY	76.00	-
	LESS 10% DISCOUNT		-724.00	-507.80
			6,516.00	4,570.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT NUMBER PLATE (SN)	BROKEN	150.00	120.00
1	MISCELLANEOUS (SN)	NOT NECESSARY	200.00	-
			350.00	120.00
<b><u>LABOUR</u></b>				
	TO CHECK ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT FRONT BUMPER SENSOR.		150.00	30.00
	CHECK AND RESET FAULT CODE LIGHT ON.		150.00	80.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	150.00	-

Report Ref No. CS/SMO20005640/Evf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY ANTI RUST ON AFFECTED AREAS.		200.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	250.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER TOW COVER.		800.00	300.00
			2,130.00	720.00
GRAND TOTAL			8,996.00	5,410.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,350.00

Report Ref No. CS/SMO20005640/Evf3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.