



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM20005642/Qga3q2 Date: 03/02/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PA 7038B	Veh. Inspected	SJQ 1136C
	Policy No.	P0219856	Coverage (\$)	0.00
	Claim No.	S0M02NQL	Excess (\$)	0.00
	Assign From		Assign Date	08/05/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT 1.3G A	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	GE61138054	Colour	BLACK
	Odometer	217465 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	ROADMARCH	6 mm
	L/H Front Tyre	185/60 R15	ROADMARCH	6 mm
	R/H Rear Tyre	185/60 R15	ROADMARCH	6 mm
	L/H Rear Tyre	185/60 R15	ROADMARCH	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/05/2020	Inspection Date	11/05/2020
	Survey held at	YT AUTOMOBILE PTE LTD 60 JALAN LAM HUAT #03-35 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	