

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 5549C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR LID (ALUMINIUM) (CONSISTENT)	BENT	1,171.00	1,171.00
1	REAR LID LOGO EMBLEM (CONSISTENT)	NECESSARY	49.68	49.68
1	REAR LID 'C180' EMBLEM (CONSISTENT)	NECESSARY	88.27	88.27
1	REAR LID 'KOMPRESSOR' EMBLEM (CONSISTENT)	NECESSARY	112.33	112.33
1	REAR BUMPER (CONSISTENT)	BUCKLED / CRACKED	1,360.35	1,360.35
1	REAR BUMPER MOULDING -CENTRE (CONSISTENT)	NECESSARY	197.74	197.74
1	REAR BUMPER MOULDING -LH (CONSISTENT)	NECESSARY	176.63	110.00
1	REAR BUMPER MOULDING -R/H (CONSISTENT)	NECESSARY	176.63	110.00
1	REAR BUMPER LOWER LIP (CONSISTENT)	NOT NECESSARY	357.45	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	832.42	620.00
2	REAR BUMPER LOWER BRACKET @\$81.22 (CONSISTENT)	CRACKED	162.44	162.44
	LESS 10% DISCOUNT		-468.49	-398.18
			4,216.45	3,583.63
	SPECIAL NETT ITEMS			
4	REVERSE SENSOR (SN) (CONSISTENT)	SHORTED (2 PCS ONLY)	990.92	410.00
			990.92	410.00
	<u>LABOUR</u>			
	TO ANTI-RUST N/S AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO CHECK & REWIRING.		40.00	20.00
	TO PULL ,KNOCK ,REPAIR ON ACCIDENT PORTION & REPLACE THE ABOVE PART.		480.00	420.00
	TO SPRAY & PAINT ON ACCIDENT PORTION .		850.00	650.00
			-	-
			-	-
			-	-
			1,450.00	1,090.00
	GRAND TOTAL		6,657.37	5,083.63

Report Ref No. CC4/ASM20005648/Kea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,050.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM20005648/Kea3q2

KONG SENG CHEONG

Licensed Appraiser