

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/FWD20005650/QKA3Q2**Date:** 11/09/2020REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00016534
Claimant
Vehicle No : SLQ4906D **Insured Vehicle No :** SJT6509Y
Date of Loss: 28/04/2020 Nature of Claim: TP Claim No: 1202000017479

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ4906D**
Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A) Engine No: 1NZR449263
Reg. Date: 12/07/2017 (Man. Year: 2016) Chassis No: NHP1707063305
Colour: Silver Odometer: 151542 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,875.61	7,051.32	1,824.29	20.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,780.00	440.00	19.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,095.61	8,831.32	2,264.29	20.41
Approved Total (Overridden) (S\$)		7,050.00		
(S\$)	11,095.61	7,050.00	4,045.61	36.46
+ GST 7.00/7.00% (S\$)	776.69	493.50	283.19	36.46
Nett Amount (S\$)	11,872.30	7,543.50	4,328.80	36.46
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 11/05/2020
Date Inspected: 12/05/2020 Inspected At: Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-01 Carros
Centre
Singapore 737869
Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2020)
Parts: M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ4906D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,879.00 FL	*1,879.00 FL
2	1		*REAR TAILGATE WEATHERSTRIP	Crumpled	432.00 FL	*432.00 FL
3	1		*REAR TAILGATE LOCK	Jammed	504.00 FL	*504.00 FL
4	1		*REAR TAILGATE LOCK CATCH	Serviceable	64.80 FL	*- FL
5	1		*R/R TAIL LAMP	Missing	550.00 FL	*550.00 FL
6	1		*R/R TAIL LAMP REFLECTOR	Serviceable	380.00 FL	*- FL
7	1		*R/L TAIL LAMP REFLECTOR	Cracked	380.00 FL	*380.00 FL
8	1		*REAR TAILGATE CENTER GARNISH	Serviceable	342.00 FL	*- FL
9	1		*REAR TAILGATE HYBRID LOGO	Necessary	60.00 FL	*60.00 FL
10	1		*REAR END PANEL	Dented	828.00 FL	*828.00 FL
11	1		*REAR END PANEL LOWER	Dented	633.60 FL	*633.60 FL
12	1		*REAR END PANEL TOP GARNISH	Crumpled	250.00 FL	*250.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	338.10 FL	*- FL
14	1		*REAR BUMPER SPONGE	Not Necessary	157.50 FL	*- FL
15	1		*REAR BUMPER	Scratched	1,257.83 FL	*1,257.83 FL
16	1		*REAR BUMPER RH RETAINER	Serviceable	67.05 FL	*- FL
17	1		*REAR BUMPER LH EXTENSION PAD	Repair	216.00 FL	*- FL
18	1		*REAR BUMPER RH EXTENSION PAD	Deformed	216.00 FL	*216.00 FL
19	1		*REAR BUMPER CENTER PAD	Crumpled	288.00 FL	*288.00 FL
20	1		*REAR BUMPER LH REFLECTOR	Serviceable	93.60 FL	*- FL
21	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*SET REVERSE SENSOR	Necessary	260.00 FS	*200.00 FS
23	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
24	1		*BODY SEALANT	Necessary	300.00 FS	*40.00 FS
25	1		*R/L TAILLAMP	Crumpled	550.00 FL	*550.00 FL
26	1		*R/R TAILLAMP LED COMBINATION SOCKET	Cut	280.00 FL	*280.00 FL
27	1		*R/R TAILLAMP LED WIRING	Serviceable	200.00 FL	*- FL
28	1		*REAR TAILGATE HOLDER HAND GRIP	Deformed	180.00 FL	*180.00 FL
29	1		*REAR TAILGATE TRAY BOX	Crumpled	580.00 FL	*580.00 FL
30	1		*REAR ANTENA SENSOR	Cracked	120.00 FL	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,587.48	9,298.43
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,711.87	2,247.11
Total Parts (\$\$)	8,875.61	7,051.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	120.00	120.00
2	TRANSFER TAILGATE MECHANISM	New	100.00	60.00
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR BUMPER ,END PANEL AND SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,000.00	800.00
4	TO RESPRAY REAR TAILGATE ,REAR END PANEL,SPARE TYRE PANEL AND REAR BUMPER	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,220.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >