

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18018885/GDA3Q2-1

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800067407

Claimant
Vehicle No : SME4381T **Insured Vehicle No :** SLX833U

Date of Loss: 03/10/2018 Nature of Claim: TP Claim No: 0217327001SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME4381T		
Make & Model:	HONDA FIT, 1.5 HYBRID (A)	Engine No:	LEB1432366
Reg. Date:	28/09/2018 (Man. Year: 2018)	Chassis No:	GP51327596
Colour:	Blue	Odometer:	609 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,597.00	612.00	985.00	61.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	400.00	280.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,277.00	1,012.00	1,265.00	55.56
+ GST 7.00/7.00% (\$\$)	159.39	70.84	88.55	55.56
Nett Amount (\$\$)	2,436.39	1,082.84	1,353.55	55.56
+ Loss of Use (2.0 x S\$50.00/day) (\$\$)		100.00		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		1,190.33		

INSPECTION

Date of Assignment: 16/10/2018

Date Inspected: 18/10/2018 Inspected At:

30 UBI RD 4

Repairer: BW Workshop Services Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Damaged	1,300.00 F	*727.50 FL
2	10		*FRT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
3	1		*FRT BUMPER SEAL	Not Necessary	65.00 F	* - FL
4	1		*FRT BUMPER FOG LAMP GARNISH	Not Necessary	111.00 F	* - FL
5	2		*FRT BUMPER SIDE HOLDER	Not Necessary	76.00 F	* - FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,597.00	757.50
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	145.50

Total Parts (\$)	1,597.00	612.00
-------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	680.00	400.00
Gross Labour Cost (S\$)			680.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >