

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005657/KGA3Q2
Date: 26/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100351681
Claimant Vehicle No :	SJQ5146Y	Insured Vehicle No :	SCX8855K
Date of Loss:	14/04/2020	Nature of Claim:	TP
		Claim No:	0745039618SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ5146Y		
Make & Model:	MITSUBISHI LANCER, 2.0 L MIVEC GLS6-CVT (A)	Engine No:	4B11CL9226
Reg. Date:	15/05/2009 (Man. Year: 2008)	Chassis No:	JMYSTCY4A9U001614
Colour:	Metallic Red	Odometer:	373179 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,890.18	3,241.58	2,648.60	44.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	970.00	1,010.00	51.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,870.18	4,211.58	3,658.60	46.49
Approved Total (Overridden) (S\$)		3,350.00		

(S\$)	7,870.18	3,350.00	4,520.18	57.43
+ GST 7.00/7.00% (S\$)	550.91	234.50	316.41	57.43
Nett Amount (S\$)	8,421.09	3,584.50	4,836.59	57.43
+ Car Rental (7.0 x S\$128.40/day) (S\$)		898.80		
(S\$)		4,483.30		
Liabe Amount (50.00%) (S\$)		2,241.65		

INSPECTION

Date of Assignment: 11/05/2020

Date Inspected: 11/05/2020

Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	896.00 FL	*801.00 FL
2	14		*FRONT BUMPER CLIPS	Necessary	56.00 FL	*56.00 FL
3	1		*FRONT BUMPER TOP RUBBER SEAL	Necessary	29.00 FL	*29.00 FL
4	1		*FRONT BUMPER TOP BEAM	Repair	75.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP RH	Cracked	458.00 FL	*430.00 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	39.00 FL	*39.00 FL
7	1		*FRONT BUMPER CORNER RETAINER RH	Distorted	14.20 FL	*14.20 FL
8	12		*FRONT BUMPER RIVETS	Necessary	108.00 FL	*108.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Repair	356.00 FL	*- FL
10	1		*FRONT HEADLAMP RH	Mtg Cracked	1,132.00 FL	*1,036.00 FL
11	1		*FRONT BUMPER LOWER PANEL RH	Repair	182.00 FL	*- FL
12	1		*FRONT FENDER RH	Bent	535.00 FL	*496.00 FL
13	1		*FRONT FENDER INNER SHIELD RH	Missing	115.00 FL	*115.00 FL
14	10		*FRONT FENDER INNER SHIELD CLIPS	Necessary	40.00 FL	*40.00 FL
15	1		*WIPER TANK	Dented	82.00 FL	*82.00 FL
16	1		*WIPER TANK MOTOR	Serviceable	82.00 FL	*- FL
17	1		*FRONT SHOCK ABSORBER RH	Serviceable	469.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM RH	Serviceable	326.00 FL	*- FL
19	1		*FRONT KNUCKLE ARM BEARING RH	Serviceable	150.00 FL	*- FL
20	1		*FRONT WHEEL HUB RH	Serviceable	235.00 FL	*- FL
21	1		*FRONT LOWER ARM RH	Serviceable	321.00 FL	*- FL
22	1		*FRONT SPORT RIM RH	Dented	480.00 FS	*320.00 FS
23	1		*FRONT TYRE RH	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,460.20	3,566.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	570.02	324.62
Total Parts (\$\$)	5,890.18	3,241.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CONDUCT FRONT ELECTRICAL CHECK LOCKING SYSTEM ADJUST FOCUS HEADLAMP ETC	New	40.00	20.00
2	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	80.00	30.00
3	TO DISMANTLE /REPLACE FRONT UNDER CARRIAGE	New	200.00	0.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	TO CONDUCT HIGH SPEED BALANCING	New	80.00	20.00
6	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FRONT FENDER INNER PANEL ,DOOR PILLAR ,AND PARTS REPLACEMENT	New	800.00	400.00
7	TO RESPRAY AFFECTED AREAS	New	700.00	440.00
Gross Labour Cost (S\$)			1,980.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >