

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20005664/R1BA3Q2

Date: 17/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100476809

Claimant
Vehicle No : SMR1201G **Insured Vehicle No :** SLE7318U

Date of Loss: 10/05/2020 Nature of Claim: TP Claim No: 6235063541SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1201G		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD886243
Reg. Date:	19/12/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF31L1011104
Colour:	Orange	Odometer:	1944 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,740.12	11,025.28	9,714.84	46.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,184.00	11,632.00	6,552.00	36.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	38,924.12	22,657.28	16,266.84	41.79
+ GST 7.00/7.00% (S\$)	2,724.69	1,586.01	1,138.68	41.79
Nett Amount (S\$)	41,648.81	24,243.29	17,405.52	41.79
+ Loss of Use (18.0 x S\$60.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		25,325.29		

INSPECTION

Date of Assignment: 12/05/2020

Date Inspected: 12/05/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 15.0 days

Adjuster: MOHD RASUL

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,946.00 FS	*1,556.00 FS
2	1		*FRONT BUMPER CLOSING ELEMENT -LH	Missing	55.00 FS	*43.84 FS
3	1		*FRONT BUMPER GRILLE -CENTRE	Serviceable	204.00 FS	*- FS
4	1		*FRONT BUMPER COVER	Serviceable	48.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE -LH	Serviceable	104.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	179.00 FS	*- FS
7	1		*FRONT BUMPER FRONT SPOILER	Cracked	361.00 FS	*288.80 FS
8	1		*FRONT BUMPER BRACKET	Serviceable	20.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Scratched	144.00 FS	*115.20 FS
10	1		*RADIATOR GRILLE	Serviceable	1,349.00 FS	*- FS
11	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	230.00 FS	*183.60 FS
12	1		*RADIATOR GRILLE BRACKET	Serviceable	39.00 FS	*- FS
13	1		*RADIATOR COVER CAP	Serviceable	42.00 FS	*- FS
14	1		*RADIATOR SECURING PLATE	Serviceable	31.00 FS	*- FS
15	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
16	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
17	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	96.00 FS	*- FS
18	1		*FRONT BUMPER CARRIER	Serviceable	793.00 FS	*- FS
19	1		*FRONT BUMPER COVER	Cracked	116.00 FS	*92.40 FS
20	1		*FRONT BUMPER GUIDE SECTION -LH	Cracked	36.00 FS	*28.64 FS
21	1		*FRONT PARKING AID SENSOR (NPA)	Serviceable	0.00 FS	*- FS
22	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
23	1		*SIGNAL HORN -LH HIGH TONE	Serviceable	129.00 FS	*- FS
24	1		*SPRING SHACKLE -LH	Serviceable	20.00 FS	*- FS
25	1		*FRONT FENDER -LH	Buckled	1,211.00 FS	*968.80 FS
26	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	59.00 FS	*- FS
27	1		*FRONT FENDER BRACE -LH	Bent	82.00 FS	*65.60 FS
28	1		*FRONT FENDER BRACKET -LH	Bent	30.00 FS	*23.28 FS
29	1		*FRONT FENDER CLOSING ELEMENT -LH	Deformed	31.00 FS	*24.56 FS
30	1		*FRONT FENDER INSULATION -LH	Cut	40.00 FS	*31.76 FS
31	1		*DAMPING -LH UPPER	Deformed	30.00 FS	*23.28 FS
32	1		*DAMPING SEAL	Necessary	34.00 FS	*26.96 FS
33	1		*FRONT WHEEL HOUSING LINER -LH	Torn	226.00 FS	*180.40 FS
34	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	95.00 FS	*- FS
35	1		*WHEEL HOUSING LINER COVER -LH	Cracked	15.00 FS	*11.44 FS
36	1		*LED HEADLIGHT -LH	Cracked	5,263.00 FS	*4,210.40 FS
37	1		*LED WITH HEAT SINK	Serviceable	735.00 FS	*- FS
38	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Working	714.00 FS	*571.20 FS
39	1		*HEADLIGHT HOSE -LH	Serviceable	23.00 FS	*- FS
40	1		*HEADLAMP HOUSING REPAIR KIT -LH	Cracked	124.00 FS	*99.20 FS
41	1		*LEFT CYLINDER -LH	Serviceable	198.00 FS	*- FS
42	1		*LEFT CYLINDER HOSE	Serviceable	75.00 FS	*- FS
43	1		*HEADLIGHT MOUNTING -LH	Cracked	112.00 FS	*89.20 FS
44	2		*FRONT WHEEL COVER -LH/RH	N/S Cracked / O/S Necessary	506.00 FS	*404.80 FS
45	1		*LOCK CARRIER	Cracked	1,198.00 FS	*958.40 FS
46	1		*READY MIX COOLANT	Necessary	169.00 FS	*134.72 FS
47	1		*FRONT ALUMINIUM RIM -LH	Scratched	893.00 FS	*714.00 FS
48	1		*TRACK CONTROL ARM	Serviceable	449.00 FS	*- FS
49	1		*WHEEL BEARING HOUSING -LH	Serviceable	638.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*WHEEL BEARING	Serviceable	457.00 FS	*- FS
51	1		*GUIDE JOINT -LH	Serviceable	135.00 FS	*- FS
52	1		*COUPLING ROD	Serviceable	90.00 FS	*- FS
53	1		*CAS SHOCK ABSORBER	Serviceable	287.00 FS	*- FS
54	1		*TRACK ROD	Serviceable	74.00 FS	*- FS
55	1		*TIE ROD END -LH	Serviceable	121.00 FS	*- FS
56	1		*STEERING GEAR CREESE	Not Necessary	41.00 FS	*- FS
57	1		*FRONT NO PLATE	Serviceable	60.00 FS	*- FS
58	1		*SUNDRIES	Necessary	400.00 FS	*14.08 FS
59	1		*HEADLIGHT SOCKET LHS	Cracked	11.60 FS	*11.60 FS
60	1		*A-PILLAR FENDER MOUNTING LHS	Missing	48.32 FS	*48.32 FS
61	1		*HEADLIGHT MOUNTING RHS	Cracked	89.20 FS	*89.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 20,740.12 11,025.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER,CHARGED AIR COOLER ,RADIATOR ,CHECK ELECTRICAL FANS AIR CONTROL UNIT ,PRESSURISE COOLING SYSTEM TO CARRT OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY	New	1,800.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER AND LHS HEADLIGHT ,TO REPAIR BONNET .TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION REORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	5,600.00	3,250.00
5	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER AND BONNET	New	3,200.00	2,200.00
6	TO CARRY OUT PRE-WHEEL ALIGNMENT AND POST-WHEEL ALIGNMENT TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	520.00	260.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	192.00
8	TO CUT OUT AND WELD BACK A-PILLAR FENDER MOUNTING LHS	New	1,000.00	500.00
9	TO RESPRAY A PILLAR FENDER MOUNTING LHS	New	1,000.00	550.00
10	TO REMOVE AND REINSTALL DASHBOARD TO FACILITATE A-PILLAR FENDER MOUNTING LHS RENEWAL	New	2,800.00	2,800.00
Gross Labour Cost (S\$)			18,184.00	11,632.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >