

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20005667/T1SF3E2

Date: 04/09/2020

REFERENCE

Insured/Claimant: NG YEW HUAT DARREN Policy No: DMPCSN30618419000
Date of Loss: 01/05/2020 Nature of Claim: OD Claim No: SNM20D201862

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN3805Y**
Make & Model: BMW 330I, 2.0 (A) Engine No: 1177A129B48B20B23A
Reg. Date: 28/03/2019 (Man. Year: 2018) Chassis No: WBA5R12070AE79946
Colour: Grey Odometer: 9690 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$190,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,794.85	22,716.85	5,078.00	18.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,502.25	13,057.25	2,445.00	15.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	43,297.10	35,774.10	7,523.00	17.38
- Excess (\$\$)	750.00	750.00	0.00	0.00
(\$\$)	42,547.10	35,024.10	7,523.00	17.68
+ GST 7.00/7.00% (\$\$)	2,978.30	2,451.69	526.61	17.68
Nett Amount (\$\$)	45,525.40	37,475.79	8,049.61	17.68

INSPECTION

Date of Assignment: 18/05/2020

Date Inspected: 12/05/2020 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2020)
Parts:	143	BMW 330I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN3805Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*(S/L) EXCHANGE SHORT ENGINE	Jammed	14,824.55 FS	*14,824.55 FS
2	1		*PRE FORMED SEAL	Necessary	16.45 FS	*16.45 FS
3	1		*EXHAUST MANIFOLD SEAL	Necessary	41.15 FS	*41.15 FS
4	1		*TURBO CHARGER	Jammed	5,078.00 FS	*4,065.80 FS
5	4		*SPARK PLUG HIGH POWER	Necessary	180.60 FS	*180.60 FS
6	1		*EXCHANGE STARTER MOTOR (VALEO)	Jammed	942.55 FS	*942.55 FS
7	4		*RP INJECTOR	Distorted	2,144.00 FS	*2,144.00 FS
8	1		*GASKET	Necessary	17.00 FS	*17.00 FS
9	1		*AIR FILTER ELEMENT	Necessary	82.30 FS	*82.30 FS
10	1		*GASKET RING	Necessary	30.45 FS	*30.45 FS
11	1		*V BAND CLAMP	Necessary	43.05 FS	*43.05 FS
12	1		*MUFFLER CLAMP D=80.0MM	Necessary	43.05 FS	*43.05 FS
13	1		*TURBOCHARGER ADDITIVE PETROL MSP (17	Necessary	43.60 FS	*43.60 FS
14	2		*(S/L) ANTI FREEZE 1.5 LITRES	Necessary	40.80 FS	*40.80 FS
15	2		*DOWEL PIN 4X16MM	Necessary	6.10 FS	*6.10 FS
16	1		*EXCH TURBOCHARGER W EXHAUST MANIFOL	Repeated	4,065.80 FS	*- FS
17	1		*SET OF SMALL PARTS	Necessary	21.65 FS	*21.65 FS
18	1		*GASKET RING	Necessary	23.75 FS	*23.75 FS
19	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
Total Parts (S\$)					27,794.85	22,716.85

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
2	TO SEND VEHICLE WITH NEW SHORT ENGINE TO LTA FOR INSPECTION	New	191.00	191.00
3	TO REPLACE NEW SHORT ENGINE INCLUDING ADJUST ENGINE TIMING IN ACCORDANCE WITH BMW SPECIFICATION	New	8,496.00	7,221.00
4	TO REMOVE AND INSTALL RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING TO CONDUCT PRESSURE TEST, BLEED COOLING SYSTEM AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES)	New	673.00	572.00
5	TO REMOVE AND INSTALL AIR CON CONDENSER AND PIPING INCLUDING VACUUM SYSTEM, TOP UP FREON GAS AND CHECKS FOR LEAK. (FOR ALL MODELS EXCEPT FOR 7 SERIES)	New	814.00	691.00
6	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	0.00
7	TO CHECK AND INSPECT THE VEHICLE TO CONFIRM FAULTY PARTS	New	1,700.00	1,445.00
8	TO CONDUCT COMPRESSION TEST	New	531.00	451.00
9	TO CLEAN AND DRY CARPET	New	531.00	451.00
10	TO REMOVE AND RECONNECT ALL ELECTRICAL COMPONENTS, CONTROL UNITS, WIRINGS SYSTEMS AT THE ENGINE BAY AND CONDUCT TESTS FOR PROPER FUNCTION	New	451.00	451.00
11	TO REPLACE EXCH TURBO CHARGER INCLUDING CONDUCT CHECK FOR LEAK AND PROPER FUNCTION	New	765.00	765.00
12	TO REPLACE STARTER MOTOR INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	451.00	451.00
13	TO SUPPLY BMW ENGINE OIL - 5.25 LITRES	New	173.25	173.25
Gross Labour Cost (S\$)			15,502.25	13,057.25

Report was unsubmitted during this print-out.

< END OF ESTIMATES >