

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ben Tang

Date: 27 Aug 2020

**Preliminary Advice**

Vehicle No	: SMN3805Y	Accident Date	: 01/05/2020
Make	: BMW 330I	Policy No.	: DMPCSN30618419000
Assignment Date	: 18/05/2020	Excess	: S\$750.00
Date of Inspection	: 12/05/2020	Est. Duration of Repair	: 10 days
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

**Point of Impact / General Description of Damages**

The vehicle recovered from flood. Many electrical & mechanism parts found damaged and contaminated by flood water at the time of inspection.

Repairer's Estimate (Gross)	:S\$	43,297.10 (inclusive supp \$ 6,107.55)
Revised Amount	:S\$	35,774.10 (inclusive supp)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	35,774.10

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	82,142.00
Salvage Value	:S\$	
Margin for Repair	:S\$	107,858.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Kindly approve on supplementary.