

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 May 2020 17:37 Sendback Est	11 May 2020 18:08 \$28,768.85	12 May 2020 09:28 Edit Adj Rpt	\$18,000.00 Edit Estimates	\$18,000.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	10 Jun 2020 10:37	10 Jun 2020 10:54 \$3,120.00	10 Jun 2020 10:54			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SHANGHAI TUNNEL ENGINEERING CO (SINGAPORE) PTE LTD, Co. Reg. No.: YP620E		
Vehicle Reg. No.:	YP620E	Date of Loss:	08/05/2020 08:00 - :59 [52 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 20/20/20/VC05/023338	Policy/Cover Note No.:	Z20VCD5004764 (Comprehensive)
		Excess:	\$700.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/05/2020]		
Driver/Custodian:	MARAN GOKULA RAMANA (50 / Male) , NRIC: G7754719W, Tel: +6582737427 Email: NOEMAIL		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- LONPAC_HQ (19/06/2020): **Alert - Adj Mandate Approved (\$18000.00) - YP620E - Claim Handler: Ong Li Li**
- LONPAC_HQ (17/06/2020): **Alert - Adj Mandate Approved (\$18000.00) - YP620E - Claim Handler: Ong Li Li**
- LONPAC_HQ (13/05/2020): **Alert - Adj Mandate Approved (\$13850.00) - YP620E - Claim Handler: Ong Li Li**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

YP620E (20/20/20/VC05/023338)

OD

May 8 2020 8:00AM

**[SHANGHAI TUNNEL ENGINEERING CO (SINGAPORE) PTE LTD]
S & H Motor Pte Ltd**

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	Lonpac Insurance Bhd (HQ)		Thumbnail Print
1	12/05/20 11:36	OD Letter		Load HTM
Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	11/05/20 18:08	Repairer Estimates		Load HTM
2	10/06/20 10:54	Repairer Estimates Suppl. #1		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/05/20 12:45	Adjuster Immediate Advice		Load HTM
2	16/06/20 17:59	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	13/05/20 09:44	Odometer Reading		Load JPG ☒
2	13/05/20 09:44	Chassis Number		Load JPG ☒
3	13/05/20 09:45	General View		Load JPG ☒
4	13/05/20 09:45	General View		Load JPG ☒
5	13/05/20 09:45	General View		Load JPG ☒
6	13/05/20 09:45	General View		Load JPG ☒
7	13/05/20 09:45	General View		Load JPG ☒
8	13/05/20 09:45	General View		Load JPG ☒
9	13/05/20 09:45	General View		Load JPG ☒
10	13/05/20 09:45	General View		Load JPG ☒
11	13/05/20 09:45	General View		Load JPG ☒
12	13/05/20 09:45	General View		Load JPG ☒
13	13/05/20 09:45	General View		Load JPG ☒
14	13/05/20 09:45	General View		Load JPG ☒
15	13/05/20 09:45	General View		Load JPG ☒
16	13/05/20 09:45	General View		Load JPG ☒
17	13/05/20 09:45	General View		Load JPG ☒
18	13/05/20 09:45	General View		Load JPG ☒
19	13/05/20 09:45	General View		Load JPG ☒
20	13/05/20 09:45	General View		Load JPG ☒
21	13/05/20 09:45	General View		Load JPG ☒
22	13/05/20 09:45	General View		Load JPG ☒
23	13/05/20 09:45	General View		Load JPG ☒
24	13/05/20 09:45	General View		Load JPG ☒
25	13/05/20 09:45	General View		Load JPG ☒
26	13/05/20 09:45	General View		Load JPG ☒
27	13/05/20 09:45	General View		Load JPG ☒
28	13/05/20 09:45	General View		Load JPG ☒
29	13/05/20 09:45	General View		Load JPG ☒
30	13/05/20 09:45	General View		Load JPG ☒
31	13/05/20 09:45	General View		Load JPG ☒
32	13/05/20 09:45	General View		Load JPG ☒

Letters/Correspondences				1 per page	☒
No	Finalized On	Lonpac Insurance Bhd (HQ)		Thumbnail	Print
33	13/05/20 09:45	General View		Load JPG	☒
34	13/05/20 09:45	General View		Load JPG	☒
35	13/05/20 09:45	General View		Load JPG	☒
36	13/05/20 09:45	General View		Load JPG	☒
37	13/05/20 09:45	General View		Load JPG	☒
38	13/05/20 09:45	General View		Load JPG	☒
39	13/05/20 09:45	General View		Load JPG	☒
40	13/05/20 09:45	General View		Load JPG	☒
41	13/05/20 09:45	General View		Load JPG	☒
42	13/05/20 09:45	General View		Load JPG	☒
43	13/05/20 09:45	General View		Load JPG	☒
44	13/05/20 09:45	General View		Load JPG	☒
45	13/05/20 09:45	General View		Load JPG	☒
46	13/05/20 09:45	General View		Load JPG	☒
47	13/05/20 09:45	General View		Load JPG	☒
48	13/05/20 09:45	General View		Load JPG	☒
49	13/05/20 09:45	General View		Load JPG	☒
50	13/05/20 09:45	General View		Load JPG	☒
51	13/05/20 09:45	General View		Load JPG	☒
52	13/05/20 09:45	General View		Load JPG	☒
53	13/05/20 09:45	General View		Load JPG	☒
54	13/05/20 09:45	General View		Load JPG	☒
55	13/05/20 09:45	General View		Load JPG	☒
56	13/05/20 09:45	General View		Load JPG	☒
57	13/05/20 09:45	General View		Load JPG	☒
58	13/05/20 09:45	General View		Load JPG	☒
59	13/05/20 09:45	General View		Load JPG	☒
60	13/05/20 09:45	General View		Load JPG	☒
61	13/05/20 09:45	General View		Load JPG	☒
62	13/05/20 09:45	General View		Load JPG	☒
63	13/05/20 09:45	General View		Load JPG	☒
64	13/05/20 09:45	General View		Load JPG	☒
65	13/05/20 09:45	General View		Load JPG	☒
66	13/05/20 09:45	General View		Load JPG	☒
67	13/05/20 09:45	General View		Load JPG	☒
68	13/05/20 09:45	General View		Load JPG	☒
69	13/05/20 09:45	General View		Load JPG	☒
70	13/05/20 09:45	General View		Load JPG	☒
71	13/05/20 09:45	General View		Load JPG	☒
72	13/05/20 09:46	General View		Load JPG	☒
73	13/05/20 09:46	General View		Load JPG	☒
74	13/05/20 09:46	General View		Load JPG	☒
75	13/05/20 09:46	General View		Load JPG	☒
76	13/05/20 09:46	General View		Load JPG	☒
77	13/05/20 09:46	General View		Load JPG	☒
78	13/05/20 09:46	General View		Load JPG	☒
79	21/05/20 11:27	Dismantled Parts		Load JPG	☒
80	21/05/20 11:28	Dismantled Parts		Load JPG	☒
81	21/05/20 11:28	Dismantled Parts		Load JPG	☒
82	21/05/20 11:28	Dismantled Parts		Load JPG	☒
83	21/05/20 11:28	Dismantled Parts		Load JPG	☒
84	21/05/20 11:28	Dismantled Parts		Load JPG	☒
85	21/05/20 11:28	Dismantled Parts		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	Lonpac Insurance Bhd (HQ)		Thumbnail	Print
86	21/05/20 11:28	Dismantled Parts		Load JPG	☒
87	21/05/20 11:28	Dismantled Parts		Load JPG	☒
88	21/05/20 11:28	Dismantled Parts		Load JPG	☒
89	21/05/20 11:28	Dismantled Parts		Load JPG	☒
90	21/05/20 11:28	Dismantled Parts		Load JPG	☒
91	21/05/20 11:28	Dismantled Parts		Load JPG	☒
92	21/05/20 11:28	Dismantled Parts		Load JPG	☒
93	21/05/20 11:28	Dismantled Parts		Load JPG	☒
94	21/05/20 11:28	Dismantled Parts		Load JPG	☒
95	21/05/20 11:28	Dismantled Parts		Load JPG	☒
96	21/05/20 11:28	Dismantled Parts		Load JPG	☒
97	21/05/20 11:28	Dismantled Parts		Load JPG	☒
98	21/05/20 11:28	Dismantled Parts		Load JPG	☒
99	21/05/20 11:28	Dismantled Parts		Load JPG	☒
100	21/05/20 11:28	Dismantled Parts		Load JPG	☒
101	21/05/20 11:28	Dismantled Parts		Load JPG	☒
102	21/05/20 11:28	Dismantled Parts		Load JPG	☒
103	21/05/20 11:28	Dismantled Parts		Load JPG	☒
104	21/05/20 11:28	Dismantled Parts		Load JPG	☒
105	21/05/20 11:28	Dismantled Parts		Load JPG	☒
106	21/05/20 11:28	Dismantled Parts		Load JPG	☒
107	21/05/20 11:28	Dismantled Parts		Load JPG	☒
108	21/05/20 11:28	Dismantled Parts		Load JPG	☒
109	21/05/20 11:28	Dismantled Parts		Load JPG	☒
110	21/05/20 11:28	Dismantled Parts		Load JPG	☒
111	21/05/20 11:28	Dismantled Parts		Load JPG	☒
112	21/05/20 11:28	Dismantled Parts		Load JPG	☒
113	21/05/20 11:28	Dismantled Parts		Load JPG	☒
114	21/05/20 11:28	Dismantled Parts		Load JPG	☒
115	21/05/20 11:28	Dismantled Parts		Load JPG	☒
116	21/05/20 11:28	Dismantled Parts		Load JPG	☒
117	21/05/20 11:28	Dismantled Parts		Load JPG	☒
118	21/05/20 11:28	Dismantled Parts		Load JPG	☒
119	21/05/20 11:28	Dismantled Parts		Load JPG	☒
120	21/05/20 11:28	Dismantled Parts		Load JPG	☒
121	21/05/20 11:28	Dismantled Parts		Load JPG	☒
122	21/05/20 11:28	Dismantled Parts		Load JPG	☒
123	21/05/20 11:28	Dismantled Parts		Load JPG	☒
124	21/05/20 11:28	Dismantled Parts		Load JPG	☒
125	21/05/20 11:28	Dismantled Parts		Load JPG	☒
126	21/05/20 11:28	Dismantled Parts		Load JPG	☒
127	21/05/20 11:28	Dismantled Parts		Load JPG	☒
128	21/05/20 11:28	Dismantled Parts		Load JPG	☒
129	21/05/20 11:28	Dismantled Parts		Load JPG	☒
130	21/05/20 11:28	Dismantled Parts		Load JPG	☒
131	21/05/20 11:28	Dismantled Parts		Load JPG	☒
132	21/05/20 11:28	Dismantled Parts		Load JPG	☒
133	21/05/20 11:28	Dismantled Parts		Load JPG	☒
134	21/05/20 11:28	Dismantled Parts		Load JPG	☒
135	21/05/20 11:28	Dismantled Parts		Load JPG	☒
136	21/05/20 11:28	Dismantled Parts		Load JPG	☒
137	21/05/20 11:28	Dismantled Parts		Load JPG	☒
138	21/05/20 11:28	Dismantled Parts		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	Lonpac Insurance Bhd (HQ)		Thumbnail	Print
139	21/05/20 11:28	Dismantled Parts		Load JPG	☒
140	21/05/20 11:28	Dismantled Parts		Load JPG	☒
141	21/05/20 11:28	Dismantled Parts		Load JPG	☒
142	19/06/20 13:46	After Repair Photo		Load JPG	☒
143	19/06/20 13:46	After Repair Photo		Load JPG	☒
144	19/06/20 13:46	After Repair Photo		Load JPG	☒
145	19/06/20 13:46	After Repair Photo		Load JPG	☒
146	19/06/20 13:46	After Repair Photo		Load JPG	☒
147	19/06/20 13:46	After Repair Photo		Load JPG	☒
148	19/06/20 13:46	After Repair Photo		Load JPG	☒
149	19/06/20 13:46	After Repair Photo		Load JPG	☒
150	19/06/20 13:46	After Repair Photo		Load JPG	☒
151	19/06/20 13:46	After Repair Photo		Load JPG	☒
152	19/06/20 13:46	After Repair Photo		Load JPG	☒
153	19/06/20 13:46	After Repair Photo		Load JPG	☒
154	19/06/20 13:46	After Repair Photo		Load JPG	☒
155	19/06/20 13:46	After Repair Photo		Load JPG	☒
156	19/06/20 13:46	After Repair Photo		Load JPG	☒
157	19/06/20 13:46	After Repair Photo		Load JPG	☒
158	19/06/20 13:46	After Repair Photo		Load JPG	☒
159	19/06/20 13:46	After Repair Photo		Load JPG	☒
160	19/06/20 13:46	After Repair Photo		Load JPG	☒
161	19/06/20 13:46	After Repair Photo		Load JPG	☒
162	19/06/20 13:46	After Repair Photo		Load JPG	☒
163	19/06/20 13:46	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/05/20 10:57	estiamte		Load PDF	
2	13/05/20 10:57	labour estimate		Load JPG	☒
3	16/06/20 17:26	SUPPLEMENTARY		Load PDF	

Linked Accident Report Documents

Assessment Reports				View	View in Browser	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	09/05/20 10:08	Accident Statement		Load HTM		
Photos/Images				3 per page		☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	09/05/20 10:05	Accident Photo		Load JPG	☒	
2	09/05/20 10:05	Accident Photo		Load JPG	☒	
3	09/05/20 10:05	Accident Photo		Load JPG	☒	
4	09/05/20 10:05	Accident Photo		Load JPG	☒	
5	09/05/20 10:05	Accident Photo		Load JPG	☒	
6	09/05/20 10:05	Accident Photo		Load JPG	☒	
7	09/05/20 10:05	Accident Photo		Load JPG	☒	
8	09/05/20 10:05	Accident Photo		Load JPG	☒	
9	09/05/20 10:05	Accident Photo		Load JPG	☒	
10	09/05/20 10:05	Accident Photo		Load JPG	☒	
11	09/05/20 10:05	Accident Photo		Load JPG	☒	
12	09/05/20 10:05	Accident Photo		Load JPG	☒	
13	09/05/20 10:05	Accident Photo		Load JPG	☒	

Assessment Reports				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
14	09/05/20 10:05	Accident Photo		Load JPG	☒
15	09/05/20 10:05	Accident Photo		Load JPG	☒
16	09/05/20 10:05	Accident Photo		Load JPG	☒
17	09/05/20 10:05	Accident Photo		Load JPG	☒
18	09/05/20 10:05	Accident Photo		Load JPG	☒
19	09/05/20 10:05	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	09/05/20 10:07	Accident Sketch Plan		Load TIF	
2	09/05/20 10:07	Accident Sketch Plan		Load TIF	
3	09/05/20 10:07	POLICE REPORT		Load TIF	
4	09/05/20 10:07	POLICE REPORT		Load TIF	
5	09/05/20 10:07	POLICE REPORT		Load TIF	
6	09/05/20 10:07	Identification Card DL		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20005674/GTF3S2**Date:** 29/06/2020**REFERENCE**Insured/Claimant: SHANGHAI TUNNEL ENGINEERING CO
(SINGAPORE) PTE LTD

Policy No: Z20VCD5004764

Date of Loss: 08/05/2020

Nature of Claim: OD Claim No: 20/20/20/VC05/023338

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YP620E**

Make & Model: ISUZU NJR85AUE6W, 3.0 D (M)

Engine No: 4JJ12F2914

Reg. Date: 23/12/2015 (Man. Year: 2015)

Chassis No: JAANJR85EF7100041

Colour: White

Odometer: 29862 km

Engine Capacity: 2999 cc

Market Value/New Car Price: S\$46,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 195/75 R15 (D)

Front Left Side: Dunlop 5 mm

Rear Left Side: Yokohama 5/5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,418.85	11,404.55	1,014.30	8.17
Miscellaneous Items	13,810.00	10,345.00	3,465.00	25.09
Labour	5,660.00	3,790.00	1,870.00	33.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,888.85	25,539.55	6,349.30	19.91
Approved Total (Overridden) (S\$)		18,000.00		
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	31,888.85	17,300.00	14,588.85	45.75
+ GST 7.00/7.00% (S\$)	2,232.22	1,211.00	1,021.22	45.75
Nett Amount (S\$)	34,121.07	18,511.00	15,610.07	45.75

INSPECTION

Date of Assignment: 12/05/2020 Present Location: S & H Motor Pte Ltd (Sin Ming)
S & H Motor Pte Ltd (Sin Ming)
Date Inspected: 12/05/2020 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 14.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Jun 2020)	
Parts:	N/A	ISUZU NJR85AUE6W 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP620E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front windscreen (WCP)	Cracked	850.00 F	*850.00 F
2	1		*Front windscreen moulding (WCP)	Necessary	190.00 F	*190.00 F
3	1		*Front panel "ISUZU" emblem" (WCP)	Cut	155.00 F	*155.00 F
4	1		*Front grille assembly (WCP)	Distorted	350.00 F	*350.00 F
5	1		*RH head lamp (WCP)	Distorted	385.00 F	*385.00 F
6	1		*LH head lamp (WCP)	Distorted	385.00 F	*385.00 F
7	1		*RH signal lamp (WCP)	Distorted	195.00 F	*195.00 F
8	1		*LH signal lamp (WCP)	Distorted	195.00 F	*195.00 F
9	1		*Front bumper (WCP)	Bent	450.00 F	*450.00 F
10	1		*LH front bumper lamp (WCP)	Distorted	115.00 F	*115.00 F
11	1		*Front bumper bottom dust panel (WCP)	Cracked	140.00 F	*140.00 F
12	1		*RH front door window glass (WCP)	Distorted	240.00 F	*240.00 F
13	1		*RH front door window glass outer moulding (WCP)	Deformed	180.00 F	*180.00 F
14	1		*RH front door window glass inner moulding (WCP)	Deformed	165.00 F	*165.00 F
15	1		*RH front door front black garnish (WCP)	Scratched	220.00 F	*220.00 F
16	1		*RH front door bottom garnish (WCP)	Deformed	125.00 F	*125.00 F
17	1		*LH front door signal lamp (WCP)	Cracked	135.00 F	*135.00 F
18	1		*LH front door window glass (WCP)	Scratched	240.00 F	*240.00 F
19	1		*LH front door window glass outer moulding (WCP)	Scratched	180.00 F	*180.00 F
20	1		*LH front door window glass inner moulding (WCP)	Scratched	165.00 F	*165.00 F
21	1		*LH front door front black garnish (WCP)	Repeated	180.00 F	*- F
22	1		*LH front door front black garnish (WCP)	Scratched	220.00 F	*220.00 F
23	1		*LH front door bottom garnish (WCP)	Scratched	125.00 F	*125.00 F
24	1		*RH front wheel cowling (WCP)	Deformed	160.00 F	*160.00 F
25	1		*RH front wheel cowling clips (1 set) (WCP)	Necessary	22.00 F	*22.00 F
26	1		*LH front wheel cowling (WCP)	Not Necessary	160.00 F	*- F
27	1		*LH front wheel cowling clips (1 set) (WCP)	Not Necessary	22.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*LH rear wheel cowling (WCP)	Deformed	125.00 F	*125.00 F
29	1		*RH front wheel bearing (WCP)	Jammed	160.00 F	*160.00 F
30	1		*LH front wheel bearing (WCP)	Jammed	160.00 F	*160.00 F
31	1		*Front stabilizer bar (WCP)	Not Necessary	240.00 F	*- F
32	1		*RH front stabilizer bar (WCP)	Not Necessary	140.00 F	*- F
33	1		*LH front stabilizer bar (WCP)	Not Necessary	140.00 F	*- F
34	1		*RH front shock absorber (WCP)	Bent	140.00 F	*140.00 F
35	1		*LH front shock absorber (WCP)	Bent	140.00 F	*140.00 F
36	1		*RH steering tie rod (WCP)	Bent	180.00 F	*180.00 F
37	1		*LH steering tie rod (WCP)	Bent	180.00 F	*180.00 F
38	1		*RH steering tie rod end (WCP)	Bent	95.00 F	*95.00 F
39	1		*LH steering tie rod end (WCP)	Bent	95.00 F	*95.00 F
40	1		*Air con condensor (WCP)	Distorted	480.00 F	*480.00 F
41	1		*Air con condensor support bracket (WCP)	Bent	140.00 F	*140.00 F
42	1		*Air con condensor auto fan (WCP)	Cracked	450.00 F	*450.00 F
43	1		*RH rear wheel bearing (WCP)	Jammed	90.00 F	*90.00 F
44	1		*LH front sun visor (WCP)	Deformed	115.00 F	*115.00 F
45	1		*Engine air cleaner box (WCP)	Cut	380.00 F	*380.00 F
<u>Supplementary #1</u>						
46	1		*Front engine right & left mounting @\$120.00 (WCP)	Torn	240.00 F	*240.00 F
47	1		*Inter Cooler (WCP)	Bent	430.00 F	*430.00 F
48	1		*Cooling coil (WCP)	Cracked	280.00 F	*280.00 F
49	1		*Dashboard (WCP)	Cracked	450.00 F	*450.00 F

F=Franchise part.

Sub Total (\$\$)	10,799.00	9,917.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	1,619.85	1,487.55
Total Parts (\$\$)	12,418.85	11,404.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Engine coolant (NECESSARY)	40.00	40.00
2	1	Front number plate (BENT)	45.00	15.00
3	1	Front windscreen inner rubber seal (NECESSARY)	95.00	40.00
4	1	Front windscreen sealant (NECESARY)	80.00	20.00
5	1	LH front tyre (PUNCTURED)	180.00	60.00
6	1	RH front tyre (PUNCTURED)	180.00	60.00
7	1	RH rear outer tyre (CUT)	180.00	60.00
8	1	Towing (to flip lorry upright and tow to workshop) (NOT NECESSARY)	350.00	0.00
9	1	Used front cabin (DISTORTED)	8,000.00	6,000.00
10	1	Used LH front control arm (BENT)	600.00	600.00
11	1	Used LH front knuckle arm (BENT)	300.00	300.00
12	1	Used LH front upper arm (BENT)	250.00	250.00
13	1	Used LH front wheel rim (BENT)	200.00	80.00
14	1	Used RH drive shaft (NOT NECESARY)	250.00	0.00
15	1	Used RH front control arm (BENT)	600.00	600.00
16	1	Used RH front knuckle arm (BENT)	300.00	300.00
17	1	Used RH front upper arm (BENT)	250.00	250.00
18	1	Used RH front wheel rim (CUT)	200.00	80.00
19	1	Used RH rear wheel rim (BENT)	200.00	80.00
Supplementary #1				
20	1	Acce bracket (BENT)	250.00	250.00
21	1	Brake booster (BENT)	380.00	380.00
22	1	Steering Box (JAMMED)	450.00	450.00
23	1	Steering Column shaft (BENT)	250.00	250.00
24	1	Steering shaft (BENT)	180.00	180.00
Sub Total (\$\$)			13,810.00	10,345.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To remove and install dashboard and centre console, including instrument panel, radio, climate control module	New	280.00	200.00
2	To remove and reinstall air con blower box, air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	180.00	120.00
3	To remove and reinstall front windscreen and conduct water leak test	New	120.00	120.00
4	To repair and reshape LH side cargo aluminium roof top, and replace aluminium panel	New	380.00	0.00
5	To remove and install rear differential and RH rear drive shaft. To check for damage and replace damaged parts	New	380.00	200.00
6	To remove and check RH & LH front suspension system, front cross member and replace damaged parts	New	550.00	300.00
7	To perform computerised wheel alignment	New	80.00	60.00
8	To remove and install Roof lining, front seats, front door trims, and pillar trims	New	250.00	80.00
9	To remove and check engine, gearbox, radiator, engine & gearbox mountings, intake and exhaust manifold & for damage and reinstall components and check engine running functionality	New	320.00	80.00
10	To remove front damaged parts, to replace front cabin, and cut out damaged parts, to straighten out front chassis, to repair and reshape front chassis member, to remove and replace all front cabin parts and adjust body panel alignment	New	1,200.00	1,000.00
11	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	120.00	30.00
12	To spray paint affected front and rear and inner damaged portion inclusive of preparatory works and material	New	1,800.00	1,600.00
Gross Labour Cost (\$\$)			5,660.00	3,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >