

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 7689C

| Qty | Description of Parts                | Condition                       | Estimate By<br>Workshop (\$)) | Our Adjusted<br>(\$) |
|-----|-------------------------------------|---------------------------------|-------------------------------|----------------------|
|     | REPLACEMENT OF PARTS                |                                 |                               |                      |
| 1   | FRONT BUMPER                        | BENT                            | 1,044.96                      | 986.00               |
| 2   | FRONT BUMPER BRACKET RH/LH          | N/S BENT / O/S<br>NOT NECESSARY | 332.82                        | 166.81               |
| 1   | FRONT CORNER SIDE PANEL LH          | DENTED                          | 329.57                        | 329.57               |
| 1   | FRONT CORNER SIDE PANEL LH          | FRACTURED                       | 82.05                         | 82.05                |
| 1   | FRONT GRILLE                        | FRACTURED                       | 485.50                        | 485.50               |
| 1   | FRONT GRILLE EMBLEM "FUSO"          | NECESSARY                       | 127.23                        | 127.23               |
| 1   | FRONT GRILLE LOGO "MITSUBISHI"      | NECESSARY                       | 67.77                         | 67.77                |
| 1   | FRONT GRILLE BRACKET                | BENT                            | 130.00                        | 130.00               |
| 8   | FRONT GRILLE CLIP                   | NECESSARY                       | 52.00                         | 52.00                |
| 1   | FRONT PANEL                         | BUCKLED                         | 1,580.67                      | 1,580.67             |
| 1   | FRONT HEADLAMP LH                   | NO DAMAGE<br>PHOTO              | 768.05                        | -                    |
| 4   | FRONT HEADLAMP CLIP LH              | NO DAMAGE<br>PHOTO              | 26.00                         | -                    |
| 1   | FRONT HEADLAMP LOWER RUBBER SEAL LH | NO DAMAGE<br>PHOTO              | 18.15                         | -                    |
| 1   | FRONT HEADLAMP PANEL LH             | TO REPAIR SEE<br>LABOUR         | 139.15                        | -                    |
| 1   | FRONT MIRROR ARM GARNISH LH         | FRACTURED                       | 70.43                         | 70.43                |
| 1   | FRONT ROUND MIRROR LH               | ABRADED                         | 65.83                         | 65.83                |
| 1   | FRONT SIDE MIRROR LH                | NO DAMAGE<br>PHOTO              | 113.90                        | -                    |
| 1   | FRONT SIDE MIRROR ARM LH            | NO DAMAGE<br>PHOTO              | 484.96                        | -                    |
| 1   | FRONT SIDE MIRROR ARM COVER LH      | NO DAMAGE<br>PHOTO              | 14.52                         | -                    |
| 1   | FRONT SIDE MIRROR BACK COVER LH     | NO DAMAGE<br>PHOTO              | 21.54                         | -                    |
| 1   | FRONT MIRROR ARM GARNISH CLIP LH    | NO DAMAGE<br>PHOTO              | 6.50                          | -                    |
| 1   | FRONT SIDE LAMP LH                  | NO DAMAGE<br>PHOTO              | 159.75                        | -                    |
| 3   | FRONT SIDE LAMP CLIP LH             | NO DAMAGE<br>PHOTO              | 19.50                         | -                    |

Report Ref No. CS1/LPC20005675/T1vf3s2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts  | Condition     | Estimate By<br>Workshop (\$)) | Our Adjusted<br>(\$) |
|-----|---|---------------|-------------------------------|----------------------|
| 1   | FRONT SIGNAL LAMP LH  | FRACTURED     | 227.65                        | 227.65               |
| 4   | FRONT SIGNAL LAMP CLIP LH   | NECESSARY     | 26.00                         | 26.00                |
| 1   | FRONT WINDSCREEN RUBBER MOULDING  | NECESSARY     | 412.18                        | 412.18               |
|     | LESS 10% DISCOUNT   |               | -                             | -480.97              |
|     |   |               | 6,806.68                      | 4,328.72             |
|     | SPECIAL NETT ITEMS  |               |                               |                      |
| 1   | FRONT NUMBER PLATE (SN)   | SERVICEABLE   | 25.00                         | -                    |
| 1   | FRONT WINDSCREEN SEALANT (SN)   | NECESSARY     | 100.00                        | 100.00               |
|     |   |               | 125.00                        | 100.00               |
|     | <u>LABOUR</u>   |               |                               |                      |
|     | TO STRAIGHTEN AND PANEL BEATING FRONT DOOR PILLAR LH, FRONT PANEL INNER PANEL AND FRONT LH FRAME MEMBERS. TO CUT AND WELD FRONT OUTER PANEL. TO REMOVE AND REFIT ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT HEADLAMP PANEL LH. |               | 1,500.00                      | 1,000.00             |
|     | TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.  |               | 1,500.00                      | 700.00               |
|     | TO REMOVE AND REFIT AIRCON SYSTEM AND RECHARGE GAS TO ASSIST REPAIR.  |               | 200.00                        | 150.00               |
|     | TO REMOVE AND REFIT FRONT WINDSCREEN.   |               | 200.00                        | 120.00               |
|     | TO REMOVE AND REFIT FRONT DASHBOARD.  | NOT NECESSARY | 300.00                        | -                    |
|     | TO CHECK AND RECTIFY WIRING SYSTEM.   |               | 80.00                         | 30.00                |
|     | TO RUST PROOF AFFECTED AREAS.   |               | 120.00                        | 30.00                |
|     |   |               | 3,900.00                      | 2,030.00             |
|     | GRAND TOTAL   |               | 10,831.68                     | 6,458.72             |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 5,150.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |          |

Report Ref No. CS1/LPC20005675/T1vf3s2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A
Automotive Assessor

**ADRIAN LING WAI PING** 

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.