Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005681/KEA3Q2

86141 km

**Date:** 11/12/2020

Odometer:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070011750

Claimant
Vehicle No: SLX993R

Insured Vehicle No: SJN1307S

Date of Loss: 06/05/2020 Nature of Claim: TP Claim No: 4548915028SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLX993R

 Make & Model:
 MERCEDES-BENZ CLA200, 1.6 (R18) (A)
 Engine No:
 27091030294181

 Reg. Date:
 30/12/2013 (Man. Year: 2013)
 Chassis No:
 WDD1173432N051713

Colour: Metallic Silver

Engine Capacity: 1595 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/40 R20 Rear Tyre Size: 225/40 R20
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm
Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,903.50	1,852.20	51.30	2.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	680.00	230.00	25.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,813.50	2,532.20	281.30	10.00
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	2,813.50	2,000.00	813.50	28.91
+ GST 7.00/7.00% (S\$)	196.95	140.00	56.95	28.92
Nett Amount (S\$)	3,010.45	2,140.00	870.45	28.91
+ Loss of Use (2.0 x S\$80.00/day) (S\$) + Doc/Search Fee (S\$)		160.00		
		8.00		
Ne	tt Liability (S\$)	2,308.00		

**INSPECTION** 

Date of Assignment: 12/05/2020

Date Inspected: 18/05/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun

Industrial Park A Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	DenteD / Mtg Cracked	1,625.00 FN	*1,625.00 FN	
2	1		*REAR BUMPER RH SIDE INNER GARNISH	Serviceable	57.00 FN	*- FN	
3	1		*REAR BUMPER RH REVERSE SENSOR	Shorted	188.00 FN	*188.00 FN	
4	1		*REAR BUMPER CENTRE LOWER SKIRT	Dented	245.00 FN	*245.00 FN	
F=Fra	nchise	part. N=Net	tltemDisc.				
Sub Total (S\$)					2,115.00	2,058.00	
- Nett Item Discount on N Items 10.00/10.00% (S\$)					211.50	205.80	
				Total Parts (S\$)	1,903.50	1,852.20	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	REMOVE & REFIX REAR BUMPER ASSY ,KNOCK & REPAIR REAR BUMPER REINFORCEMENT & REALIGN THE SAME	New	380.00	280.00				
2	PUTTY & RESPRAY ON REAR BUMPER ,REAR REINFRCEMENT	New	480.00	350.00				
3	REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM	New	50.00	50.00				
	Gross Labour Cost (S\$)		910.00	680.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >