

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005682/QYF3E2

Date: 18/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070050663
Claimant Vehicle No : FBE8104G	Insured Vehicle No :	GBE8119P
Date of Loss: 04/05/2020	Nature of Claim: TP	Claim No: 6124238984SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE8104G	Engine No:	5YP012453
Make & Model:	YAMAHA 135LC, 134cc ES	Chassis No:	5YP012453
Reg. Date:	14/09/2010 (Man. Year: 2010)	Odometer:	70999 km
Colour:	Black		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	12/05/2020	
Date Inspected:	12/05/2020 Inspected At:	Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road Singapore 368182
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT HEADLAMP FAIRING	Scratched	0.00 F	*- F
3	1		*FRONT WING MIRROR	Scratched	0.00 F	*- F
4	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
5	1		*HANDLE BAR GRIP	Cut	0.00 F	*- F
6	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
7	2		*SIDE FAIRING LH / RH	Scratched	0.00 F	*- F
8	1		*CENTER FAIRING FRONT	Scratched	0.00 F	*- F
9	1		*FOOT BRAKE RH	Scratched	0.00 F	*- F
10	1		*FRONT FOOT REST RH	Cut	0.00 F	*- F
11	1		*REAR BOX	Scratched	0.00 F	*- F
12	1		*FRONT MUD GUARD	Repair	0.00 F	*- F
13	1		*FRONT BASKET	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >