

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI20005691/GYF3E2

**Date:** 14/07/2020

#### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	ML000245
Claimant Vehicle No : SHC2567H	Insured Vehicle No :	GBK863U
Date of Loss: 08/05/2020	Nature of Claim:	TP Claim No: M2002676

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2567H	Engine No:	G4LEJU191966
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU141497
Reg. Date:	12/03/2019 (Man. Year: 2018)	Odometer:	86477 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 8 mm	Rear Left Side:	Davanti 9 mm
Front Right Side:	Davanti 8 mm	Rear Right Side:	Davanti 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,389.72	7,434.16	4,955.56	40.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	3,270.00	1,900.00	1,370.00	41.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,670.72</b>	<b>9,345.16</b>	<b>6,325.56</b>	<b>40.37</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,096.95	654.16	442.79	40.37
<b>Nett Amount (S\$)</b>	<b>16,767.67</b>	<b>9,999.32</b>	<b>6,768.35</b>	<b>40.37</b>

#### INSPECTION

Date of Assignment:	19/05/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	19/05/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Jul 2020)	
<b>Parts:</b>	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC2567H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		<b>*BOOT LID</b>	Dented	2,480.40 FL	-	*2,480.40 FL
2	1		<b>*BOOT LID RUBBER</b>	Not Necessary	187.40 FL	-	*- FL
3	2		<b>*BOOT LID HINGE LH/RH</b>	Not Necessary	142.60 FL	-	*- FL
4	2		<b>*BOOT LID ABSORBER LH/RH</b>	Not Necessary	173.40 FL	-	*- FL
5	1		<b>*BOOT LID EMBLEM</b>	Not Necessary	28.00 FL	-	*- FL
6	1		<b>*BOOT LID EMBLEM- HYB</b>	Necessary	24.30 FL	-	*24.30 FL
7	1		<b>*BOOT LID EMBLE- IONIQ</b>	Necessary	31.30 FL	-	*31.30 FL
8	1		<b>*BOOTLID HANDLE</b>	Not Necessary	31.80 FL	-	*- FL
9	1		<b>*BOOTLID LAMP LH/RH</b>	N/S Scratched/ N/SNotNecessary	1,588.80 FL	-	*794.40 FL
10	1		<b>*BOOTLID TRIMBOARD</b>	Not Necessary	259.70 FL	-	*- FL
11	10		<b>*BOOTLID TRIMBOARD CLIP 10PCS</b>	Not Necessary	11.00 FL	-	*- FL
12	1		<b>*BOOTLID GLASS UPPER,MOULDING</b>	Not Necessary	186.30 FL	-	*- FL
13	1		<b>*REAR BUMPER</b>	Missing	459.40 FL	-	*459.40 FL
14	1		<b>*REAR BUMPER REINFORCEMENT</b>	Cracked	394.60 FL	-	*394.60 FL
15	2		<b>*REAR BUMPER REINFORCEMENT BRACKET LH/RH</b>	Dented	376.20 FL	-	*276.20 FL
16	1		<b>*REAR BUMPER CENTRE MOULDING ASSY</b>	Cracked	451.25 FL	-	*451.25 FL
17	1		<b>*REAR BUMPER LOWER CENTRE MOULDING ASSY</b>	Scratched	47.50 FL	-	*47.50 FL
18	1		<b>*REAR BUMPER RETAINER</b>	Necessary	85.80 FL	-	*85.80 FL
19	10		<b>*REAR BUMPER CLIPS</b>	Necessary	22.00 FL	-	*22.00 FL
20	1		<b>*REAR BUMPER CENTRE UNDER COVER</b>	Not Necessary	123.85 FL	-	*- FL
21	1		<b>*REAR BUMPER REAR TOW COVER</b>	Missing	98.80 FL	-	*98.80 FL
22	2		<b>*REAR BUMPER REFLECTOR LAMP LH/RH</b>	Missing	165.80 FL	-	*165.80 FL
23	1		<b>*REAR BUMPER REVERSE LIGHT</b>	Missing	328.60 FL	-	*328.60 FL
24	2		<b>*REAR LICENCE LAMP LH/RH</b>	Missing	170.60 FL	-	*170.60 FL
25	1		<b>*TAIL LAMP LH/RH</b>	N/S Scratched/ N/SNotNecessary	1,740.80 FL	-	*870.40 FL
26	1		<b>*REAR PANEL</b>	Buckled	532.00 FL	-	*532.00 FL
27	1		<b>*REAR PANEL GARNISH</b>	Not Necessary	346.80 FL	-	*- FL
28	1		<b>*REAR SPARE TYRE PANEL</b>	Not Necessary	892.50 FL	-	*- FL
29	1		<b>*REAR TRAY TOOL BOX RH</b>	Not Necessary	675.30 FL	-	*- FL
30	1		<b>*REAR TRAY TOOL BOX LH</b>	Not Necessary	693.20 FL	-	*- FL
31	1		<b>*REAR EXHAUST SILENCER</b>	Dented	943.60 FL	-	*943.60 FL
32	1		<b>*REAR EXHAUST PIPE CENTRE</b>	Not Necessary	573.60 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
33	1		*REAR EXHAUST PIPE HANGER	Not Necessary	29.20 FL	-	*- FL
34	1		*BOOTLID COMFORT LOGO & TEL NO STICKER	Necessary	35.00 FS	-	*35.00 FS
35	1		*BOOTLID COMFORT CABLINK TEL NO STICKER	Necessary	30.00 FS	-	*30.00 FS
36	1		*REAR NO PLATE & HOLDER	Not Necessary	60.00 FS	-	*- FS
37	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	-	*50.00 FS
38	1		*REAR BUMPER REVERSE SENSOR	Missing	180.00 FS	-	*180.00 FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	-	*46.00 FS
<b>Supplementary #1</b>							
40	1		*ANTENNA ASSY -SMART	Dented	689.50 FL	-	*689.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>15,386.90</b>	<b>9,207.45</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	2,997.18	1,773.29
<b>Total Parts (S\$)</b>	<b>12,389.72</b>	<b>7,434.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>	<b>11.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,300.00	960.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	WIRING	New	90.00	50.00
4	TUFF KOTE	New	120.00	60.00
5	TOWING FEE	New	60.00	0.00
6	REMOVE/REFIX REAR WINDSCREEN	New	120.00	100.00
7	REMOVE/REFIX REAR EXHAUST PIPE SYST	New	90.00	70.00
8	REMOVE/REFIX REAR REVERSE SENAOR	New	90.00	60.00
9	DIAGNOSTIC & RESST TO ERASE FAULT CODE	New	400.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,270.00</b>	<b>1,900.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**