

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20005692/AGTF3E2
Date: 05/06/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001161138
Claimant Vehicle No : SGM4281C	Insured Vehicle No :	GBG7898U
Date of Loss: 11/05/2020	Nature of Claim:	TP Claim No: 243861

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM4281C	Engine No:	1ZZ2688407
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100324586
Reg. Date:	17/10/2006 (Man. Year: 2006)	Odometer:	152201 km
Colour:	Grey		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,459.10	3,937.62	7,521.48	65.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,730.00	2,200.00	55.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,389.10	5,667.62	9,721.48	63.17
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	15,389.10	4,500.00	10,889.10	70.76
+ GST 7.00/7.00% (S\$)	1,077.24	315.00	762.24	70.76
Nett Amount (S\$)	16,466.34	4,815.00	11,651.34	70.76

INSPECTION

Date of Assignment:	12/05/2020	
Date Inspected:	13/05/2020 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jun 2020)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGM4281C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,315.20 F	*1,248.00 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	282.80 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	743.60 F	*- FL
4	1		*REAR BOOT LID EMBLEM LOGO	Necessary	51.10 F	*51.10 FL
5	1		*REAR BOOT LID WISH CHROME MOULDING	Deformed	274.40 F	*274.40 FL
6	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
7	1		*REAR BOOT LID INNER LOCK	Damaged	374.40 F	*374.40 FL
8	1		*REAR BOOT LID INNER RUBBER	Not Necessary	381.90 F	*- FL
9	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	781.40 F	*485.00 FL
10	1		*REAR BOOT LID INNER CENTER TRIM COVER	Not Necessary	282.60 F	*- FL
11	2		*REAR BOOT LID INNER SIDE TRIM COVER	Not Necessary	245.60 F	*- FL
12	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	125.00 F	*125.00 FL
13	2		*REAR BOOT LID WINDSCREEN MOULDING	Necessary	136.00 F	*136.00 FL
14	1		*REAR BOOT LID REVERSE CAMERA	Not Necessary	680.00 FS	*- FS
15	2		*REAR TAIL LAMP	Cut	774.80 F	*774.80 FL
16	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*10.00 FL
17	1		*REAR BUMPER	Deformed	625.20 F	*541.00 FL
18	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Necessary	264.20 F	*125.00 FL
20	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	282.80 F	*- FL
21	1		*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
22	1		*REAR END PANEL OUTER	Dented	519.80 F	*519.80 FL
23	1		*REAR END PANEL INNER	Repair	780.50 F	*- FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	375.40 F	*289.00 FL
25	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	942.80 F	*- FL
26	16		*REAR FENDER INNER TRIM BOARD CLIP	Not Necessary	104.00 F	*- FL
27	2		*REAR FENDER COWLING	Not Necessary	344.40 F	*- FL
28	12		*REAR FENDER COWLING CLIP	Not Necessary	78.00 F	*- FL
29	2		*REAR FENDER AIR DUCT	Not Necessary	179.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,459.10	5,183.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,245.88
Total Parts (\$\$)	11,459.10	3,937.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE & REFIT REVERSE CAMERA	New	180.00	50.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
5	GUM	New	50.00	50.00
6	TO CHECK WIRING	New	100.00	30.00
7	TUFF KOTE	New	150.00	50.00
8	TOWING FEE	New	150.00	0.00
9	PANEL BEATING	New	1,400.00	700.00
10	SPRAY PAINTING	New	1,400.00	600.00
Gross Labour Cost (S\$)			3,930.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >