Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA16011913/KBA3Q2-1

Date: 09/03/2021

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520

Claimant Vehicle No: SHD9086C Insured Vehicle No: SHB7523G

Date of Loss: 23/06/2016 Nature of Claim: TP Claim No: C0389526

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9086C

Make & Model: TOYOTA WISH, 1.8 (A) Engine No: HIDDEN

Reg. Date: 01/04/2011 (Man. Year: 2011) Chassis No: JTDGJ20W105003343

Colour: Red/White Odometer: 544572 km

Engine Capacity: 1987 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm
Front Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,191.37	3,219.67	6,971.70	68.41
siscellaneous Items abour aintwork Labour owing Calculated Gross Total (S\$) Approved Total (Overridden) (S\$) (S\$)	0.00	0.00	0.00	
Labour	6,200.00	1,180.00	5,020.00	80.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,391.37	4,399.67	11,991.70	73.16
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	16,391.37	3,500.00	12,891.37	78.65
+ GST 7.00/7.00% (S\$)	1,147.40	245.00	902.40	78.65
Nett Amount (S\$)	17,538.77	3,745.00	13,793.77	78.65
+ Car Rental (4.0 x S\$	96.30/day) (S\$)	385.20		_
	(S\$)	4,130.20		
Liable Amoun	t (50.00%) (S\$)	2,065.10		
Global Sum S	Settlement (S\$)	2,000.00		

INSPECTION

Date of Assignment: 28/06/2016

Date Inspected: 24/06/2016 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Reference					
Part Source:		(Last Synchronised: 14 Dec 2017)			
Parts:	N/A	TOYOTA WISH 1.8 (A) (Model not available in database)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted, no print-code for SHD9086C)				
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page					
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Cracked 585.36 FL		*585.36 FL
2	1		*FRONT BUMPER LOWER ABSORBER (CONSISTENT)	Serviceable	130.00 FL	*- Fl
3	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Repair	318.11 FL	*- FI
4	1		*FRONT BUMPER SIDE SUPPORT LH (CONSISTENT)	Serviceable	76.20 FL	*- FI
5	1		*FRONT BUMPER SIDE SUPPORT RH (CONSISTENT)	Serviceable	76.20 FL	*- FI
6	1		*FRONT BUMPER RETAINER RH (CONSISTENT)	Distorted	102.00 FL	*102.00 FI
7	1		*FRONT BUMPER BRACKET RH (CONSISTENT)	Repair	108.00 FL	*- FI
3	1		*FRONT BUMPER BRACKET LH (CONSISTENT)	Repair	108.00 FL	*- F
9	1		*FRONT BUMPER FOG LAMP RH (CONSISTENT)	Serviceable	208.00 FL	*- FI
10	1		*FRONT BUMPER FOG LAMP OUTER CHROME RH (CONSISTENT)	Missing	190.00 FL	*190.00 FI
11	1		*FRONT BUMPER FOG LAMP GRILLE RH (CONSISTENT)	Missing	150.00 FL	*150.00 Fl
12	1		*FRONT BUMPER FOG LAMP LH (CONSISTENT)	Missing	208.00 FL	*208.00 FI
13	1		*FRONT BUMPER FOG LAMP OUTER CHROME LH (CONSISTENT)	Missing	190.00 FL	*190.00 Fl
14	1		*FRONT BUMPER FOG LAMP GRILLE LH (CONSISTENT)	Missing	150.00 FL	*150.00 Fl
15	1		*FRONT HEADLAMP RH (CONSISTENT)	Broken	672.00 FL	*672.00 FI
16	1		*FRONT HEADLAMP LH (CONSISTENT)	Serviceable	672.00 FL	*- FI
17	1		*FRONT SUPPORT PANEL ASSY (CONSISTENT)	Repair	1,222.32 FL	*- F
18	1		*FRONT BRACE PANEL (CONSISTENT)	Repair	95.49 FL	*- FI
19	1		*BONNET (CONSISTENT)	Bent	1,019.16 FL	*1,019.16 FI
20	1		*BONNET UNDER WEATHERSTRIP SEAL (CONSISTENT)	Serviceable	71.99 FL	*- FI
21	1		*BONNET CENTRE TOYOTA LOGO BADGE (CONSISTENT)	Necessary	115.44 FL	*115.44 FI
22	1		*FRONT FENDER LH (CONSISTENT)	Repair	837.60 FL	*-FI
23	1		*FRONT FENDER LINER LH (CONSISTENT)	Serviceable	369.14 FL	*- FI
24	1		*FRONT FENDER RH (CONSISTENT)	Buckled	837.60 FL	*837.60 FI
25	1		*FRONT FENDER LINER RH (CONSISTENT)	Serviceable	369.14 FL	*- FI
26	1		*RADIATOR ASSEMBLY (CONSISTENT)	Serviceable	2,268.24 FL	*- FI
27	1		*RADIATOR GRILLE (CONSISTENT)	Serviceable	462.48 FL	*- FI
28	1		*RADIATOR GRILLE COWLING (CONSISTENT)	Serviceable	221.73 FL	*-Fl
29	1		*AIRCON CONDENSER (CONSISTENT)	Serviceable	1,375.50 FL	*-Fl
30	1		*SET FRONT BUMPER FASTENER CLIP (CONSISTENT)	Necessary	40.00 FS	*40.00 F\$
31	1		*CNG STICKER (CONSISTENT)	Necessary	30.00 FS	*15.00 FS
32	1		*SET FRONT FENDER LINER CLIP LH (CONSISTENT)	Not Necessary	30.00 FS	*-F\$
33	1		*SET FRONT FENDER LINER CLIP RH (CONSISTENT)	Not Necessary	30.00 FS	*- F\$
	2		*BONNET STOPPER (CONSISTENT)	Serviceable	9.60 FS	*-F

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars C	Condition	Repairer's	Amount
35	1			lot lecessary	18.00 FS	*-FS
36	1		*FRONT LICENCE PLATE (CONSISTENT) S	Serviceable	50.00 FS	*-FS
37 F=Fra	1 nchise	part. S=S	*ONT BUMPER RETAINER LH (CONSISTENT) SpcNett. L=ListItemDisc.	Serviceable	102.00 FL	*- FL
			Su	ub Total (S\$)	13,519.30	4,274.56
	- List Item Discount on L Items 25.00/25.00% (S\$			/25.00% (S\$)	3,327.93	1,054.89
			Tota	al Parts (S\$)	10,191.37	3,219.67
			Report was unsubmitted during this print-or	ut.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	500.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	120.00	20.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	200.00	60.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,700.00	600.00
5	TO CHECK ABS BRAKE EFFCIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
	Gross Labour Cost (S		6,200.00	1,180.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.