



1021  
ASS. REC. BY:

REF: AKW

3333 / ksm 3

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trans Cab

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: **Yes** or **No**

GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes** or **No**

Est. Repairs: 02 days Res.: **Yes** or **No**

Lum Sum: 1.31 % 3 Val.: **Yes** or **No**

**CA / REV / REP. / 24 HRS**

Vehicle: **IN / OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: S14B 98400 Yr Regn: 08, 13

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or \_\_\_\_\_

Make: Renault Latitude c.c. 1995

Colour N. white/Red A/C: **Insured / Std / NI / NA**

Sp. Reading 178328 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: VFI ABC 15 AUC 2733 F3

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or \_\_\_\_\_

Brake: **Inorder / Jammed / Leaked / Burnt** or \_\_\_\_\_

Modi: **Nil / S/Rim / STD A/Rim** or \_\_\_\_\_

Tyre Size: **F:** GY 215/60R16

**R:** Falken

**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**

**TOYO / YOKO** or \_\_\_\_\_

Front 7 mm Rear 6 mm

R/Bal. 7 mm L/Bal. 7 mm

L/Bal. 7 mm D.O.A. 21/2/15

D.O.A. 24/2/15 Survey held at ✓

Des. of Damages: **Fr / Rear / O/S / N/S / U/C / Rooftop** or

N/S Fr body

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
<u>15/9/15</u>	<u>2348-02</u> <u>Cons Form Jasmine C272X 132-08</u>
	<u>West for injury claim</u>
	<u>Global Rep @ 1530k</u>
	<u>RED (\$9,513.11/80%)</u>

Date/Time, File Pass to?  : **Prel. Report**  
 : **Final Report**

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
\$ + RS. St	_____
Photos	_____
Others	_____

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.466-468 Tagore Industrial Avenue Singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHB 9840C - AXA****ROEL***Not Authorized  
11B1  
82348.02*

Vehicle No.: **SHB 9840C - ROEL**  
 Chassis No.: VF1ABL15AUC273373  
 Vehicle Make: RENAULT  
 Vehicle Model: LATITUDE  
 Date of Accident : 21.02.15  
 Third Party Insurer : **AXA**

PART		LIST
1	1 FENDER PANEL FRT LH	\$ 502.46 ✓
2	1 FENDER WHEELARCH FRT LH	\$ 89.44 X
3	1 DOOR MIRROR LH	\$ 950.90 ✓
4	1 DOOR PANEL FRT LH	\$ 1,823.50 X
5	1 DOOR SEAL FRT LH	\$ 46.68 X
6	1 DOOR HINGE UPPER LH	\$ 175.96 X
7	1 DOOR HINGE LOWER	\$ 192.66 X
8	1 DOOR CHECK FRT LH	\$ 124.86 X
9	1 DOOR LOCK FRT LH	\$ 582.53 X
10	1 DOOR CATCH FRT LH	\$ 84.12 X
11	1 DOOR HANDLE OUTER FRT LH	\$ 165.46 X
12	1 DOOR HANDLE COVER FRT LH	\$ 8.48 X
13	1 DOOR HANDLE MODULE FRT LH	\$ 85.64 X
14	1 ROCKER PANEL OUTER LH	\$ 633.01 X

<b>TOTAL</b>	<b>\$</b>	<b>5,465.70</b>
<b>10%</b>	<b>\$</b>	<b>546.57</b>
	<b>\$</b>	<b>4,919.13</b>

**Special Nett**

1SET	WHEELARCH CLIP LH	\$ 66.00 X
1SET	REAR BUMPER CLIP	\$ 66.00 X
1	DOOR STICKER "Trans-cab"	\$ 80.00 <i>born</i>
1	DOOR STICKER "Classic"	\$ 30.00 ✓

<b>TOTAL</b>	<b>\$</b>	<b>242.00</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>5,161.13</b>
--------------------	-----------	-----------------

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.466-468 Tagore Industrial Avenue Singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHB 9840C - AXA****ROEL**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	<i>4000</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
Putty and spray painting of the affected portion.	\$	3,000.00	<i>4400</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>600</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To rust-proofing of the affected areas.	\$	170.00	<i>300</i>
<b>TOTAL</b>	<b>\$</b>	<b>6,700.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>11,861.13</b>	

**(PARTS BY PARTS) Repair Days****10 DAYS***2 days*



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Our Ref: CC3/AXA15003333/Kjm3**  
**Policy Number: P1529610**

3<sup>rd</sup> August 2015

**ALSCO PTE LTD**  
9 SECOND CHIN BEE ROAD  
SINGAPORE 618776

**ATTN: RONALD GOH**  
**KOH SEE SUI**

Dear Sir/Madam,

**ACCIDENT INVOLVING GBA 7481U AND SHB 9840C ON 21/02/2015**

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by **13/08/2015**, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved. However, if you are making a claim against third party and successful with 80% in your favor, our principal will re-instate your NCD.

Please call us if you have further queries.

Yours faithfully,

Kenneth Tan

Case Handler

DID: 6841 2132

FAX: 6741 4108

Email: [kennethtan@lkkauto.com](mailto:kennethtan@lkkauto.com)

c.c. AXA Insurance Singapore Pte Ltd (AXA)  
(Motor Claims Dept)

## Joy Irene (LKK Auto)

---

**From:** Joy Irene (LKK Auto)  
**Sent:** Friday, 13 May, 2016 11:38 AM  
**To:** 'Tan Kwee May'  
**Cc:** CS A Team; Admin A  
**Subject:** RE: C0333433 RE: WP / Trans-Cab Auto / P1529610 / OD GBA7481U / TP SHB9840C / 21.02.15 / EST \$11,861.13 / KM

Dear Kwee May,

We refer to the subject above.

We have surveyed third-party vehicle at the premise of M/s Trans-Cab Auto Services Pte Ltd on 21.02.2015.

We made several reminders and follow-ups through call to third-party repairer since survey to confirm finalization and for their letter of demand for negotiation settlement however, they did not revert despite their promise.

Now, over 12 months had passed and there is still no further action initiated by third-party repairer for their claim.

In view of non-development from the third-party and the waiting for their LOD is indefinite, we will proceed to temporarily close this more than one (1) year outstanding claim file and submit our wp report (no settlement) to your good-office.

In future, if there are any new developments from the claimant, we will inform you for our further handling.

Thank you.

Best Regards,

**Joy Irene** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

**From:** Joy Irene (LKK Auto)  
**Sent:** Thursday, 12 November, 2015 6:53 PM  
**To:** 'Tan Kwee May' <kweemay.tan@axa.com.sg>  
**Cc:** CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** RE: C0333433 RE: WP / Trans-Cab Auto / P1529610 / OD GBA7481U / TP SHB9840C / 21.02.15 / EST \$11,861.13 / KM

Dear Kwee May,

We just receive PIR from TP. Attached for your reference.

PIR is charging OID for inconsiderate driving as such, we settle TP claim at best.

We are still waiting for their LOD.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE SINGAPORE PTE LTD

Ref : CC3/AXA15003333/Kja3q2

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 18-05-2016



ATTN:TAN KWEE MAY

Code : AXA2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 7481U	Veh. Inspected	SHB 9840C
Policy No.	P1529610	Coverage (\$)	0.00
Claim No.	C0333433	Excess (\$)	0.00
Assign From		Assign Date	24/02/2015

### 2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273373	Colour	METALLIC WHITE/RED
Odometer	178328	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GOODYEAR	7 mm
L/H Front Tyre	215/60 R16	GOODYEAR	7 mm
R/H Rear Tyre	215/60 R16	FALKEN	6 mm
L/H Rear Tyre	215/60 R16	FALKEN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	21/02/2015	Inspection Date	24/02/2015
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9840C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FENDER PANEL FRT LH (CONSISTENT)	BENT	502.46	502.46
1	FENDER WHEELARCH FRT LH (CONSISTENT)	SERVICEABLE	89.44	-
1	DOOR MIRROR LH (CONSISTENT)	CRACKED	950.90	950.90
1	DOOR PANEL FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,823.50	-
1	DOOR SEAL FRT LH (CONSISTENT)	SERVICEABLE	46.68	-
1	DOOR HINGE UPPER LH (CONSISTENT)	TO REPAIR SEE LABOUR	175.96	-
1	DOOR HINGE LOWER (CONSISTENT)	TO REPAIR SEE LABOUR	192.66	-
1	DOOR CHECK FRT LH (CONSISTENT)	SERVICEABLE	124.86	-
1	DOOR LOCK FRT LH (CONSISTENT)	TO REPAIR SEE LABOUR	582.53	-
1	DOOR CATCH FRT LH (CONSISTENT)	SERVICEABLE	84.12	-
1	DOOR HANDLE OUTER FRT LH (CONSISTENT)	SERVICEABLE	165.46	-
1	DOOR HANDLE COVER FRT LH (CONSISTENT)	SERVICEABLE	8.48	-
1	DOOR HANDLE MODULE FRT LH (CONSISTENT)	SERVICEABLE	85.64	-
1	ROCKER PANEL OUTER LH (CONSISTENT)	SERVICEABLE	633.01	-
	LESS 10% DISCOUNT		-546.57	-145.34
			4,919.13	1,308.02
<b>SPECIAL NETT ITEMS</b>				
1	SET WHEELARCH CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR STICKER 'CLASSIC' (SN) (CONSISTENT)	NECESSARY	30.00	30.00
			242.00	90.00
<b>LABOUR</b>				
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT LH,DOOR HINGE UPPER LH,DOOR HINGE LOWER AND DOOR LOCK FRT LH.		2,800.00	400.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
			6,700.00	950.00
	<b>GRAND TOTAL</b>		<b>11,861.13</b>	<b>2,348.02</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,348.02</b>

Report Ref No. CC3/AXA15003333/Kja3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.