

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20005697/USF3E2

**Date:** 19/05/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001272475

**Claimant Vehicle No :** SMJ4723P

**Insured Vehicle No :** SKZ1082P

Date of Loss: 09/05/2020

Nature of Claim: TP

Claim No: 243830

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ4723P**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A)

Engine No: LEB7104469

Reg. Date: 06/03/2019 (Man. Year: 2018)

Chassis No: GP72003423

Colour: Black

Odometer: 63082 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Roadstone 7 mm

Rear Left Side: Roadstone 7 mm

Front Right Side: Roadstone 7 mm

Rear Right Side: Roadstone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,308.96	1,024.56	284.40	21.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	650.00	730.00	52.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,688.96</b>	<b>1,674.56</b>	<b>1,014.40</b>	<b>37.72</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	2,688.96	1,300.00	1,388.96	51.65
<b>+ GST 7.00/7.00% (S\$)</b>	188.23	91.00	97.23	51.65
<b>Nett Amount (S\$)</b>	<b>2,877.19</b>	<b>1,391.00</b>	<b>1,486.19</b>	<b>51.65</b>

### INSPECTION

Date of Assignment: 12/05/2020

Date Inspected: 13/05/2020 Inspected At:

Focus Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #02-48/50 Autobay

Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 May 2020)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ4723P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Badly Dented	892.50 FL	*795.20 FL
2	1		*FRONT DOOR RUBBER - LH	Not Necessary	214.20 FL	*- FL
3	1		*SIDE SKIRTING - LH	Deformed / Torn	485.50 FL	*485.50 FL
4	8		*SIDE SKIRTING CLIPS - LH	Not Necessary	44.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>1,636.20</b>	<b>1,280.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	327.24	256.14
<b>Total Parts (S\$)</b>	<b>1,308.96</b>	<b>1,024.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING }	New	650.00	150.00
2	TO REMOVE & REFIT DOOR ASSY }	New	80.00	0.00
3	SPRAY PAINT	New	650.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>1,380.00</b>	<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >