

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005701/UPA3Q2

Date: 11/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800005556

Claimant
Vehicle No : FBN3609C **Insured Vehicle No :** SLV9080B

Date of Loss: 12/04/2020 Nature of Claim: TP Claim No: 8728147777SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN3609C		
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Engine No:	H336E0038759
Reg. Date:	14/09/2018 (Man. Year: 2018)	Chassis No:	MH3SH0842JK004843
Colour:	Grey	Odometer:	0 km
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120-20-15	Rear Tyre Size:	150-70-14
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,296.40	8,374.10	1,922.30	18.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	885.00	875.00	49.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,056.40	9,259.10	2,797.30	23.20
Approved Total (Overridden) (S\$)		7,400.00		
Nett Amount (S\$)	12,056.40	7,400.00	4,656.40	38.62
+ Loss of Use (7.0 x S\$25.00/day) (S\$)		175.00		
Nett Liability (S\$)		7,575.00		

INSPECTION

Date of Assignment: 13/05/2020

Date Inspected: 13/05/2020 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Bent / Twisted	980.00 FL	*980.00 FL
2	1		*FORK UNDER BRACKET COVER	Bent	190.00 FL	*165.00 FL
3	1		*FRONT SPORT RIM	Warped / Bent	550.00 FL	*520.00 FL
4	1		*FRONT BRAKE DISC	Bent	180.00 FL	*180.00 FL
5	1		*FRONT RIM SHAFT	Cut	52.00 FL	*52.00 FL
6	1		*WINDSHIELD	Broken	248.00 FL	*248.00 FL
7	1		*HEADLAMP	Cracked	550.00 FL	*550.00 FL
8	1		*SIDE MIRROR	Cut	120.00 FL	*120.00 FL
9	1		*HANDLE -BAR	Bent	135.00 FL	*135.00 FL
10	1		*SET HANDLE -BAR BALANCER	Scratched	80.00 FL	*80.00 FL
11	1		*SET HAND GRIP	Necessary	60.00 FL	*60.00 FL
12	1		*BRAKE LEVERS (N/S)	Cracked	104.00 FL	*104.00 FL
13	1		*FRONT COWLING INNER PANEL	Cracked	150.00 FL	*150.00 FL
14	2		*FRONT SIGNALS	Cracked	150.00 FL	*150.00 FL
15	1		*LAMP STAY	Bent	225.00 FL	*225.00 FL
16	1		*LOWER BELLY PANEL	Distorted	250.00 FL	*250.00 FL
17	1		*LOWER COWLING CENTRE GRILLE	Distorted	95.00 FL	*95.00 FL
18	1		*RADIATOR	Dented / Punctured	485.00 FL	*450.00 FL
19	1		*RADIATOR SPARE TANK	Deformed	155.00 FL	*155.00 FL
20	2		*FOOTSTEP PANELS	Distorted	310.00 FL	*310.00 FL
21	1		*REAR HANDLE -L/H	Cut	85.00 FL	*85.00 FL
22	1		*REAR TAILLAMP	Not Necessary	285.00 FL	*- FL
23	1		*ENGINE MOUNTING BRACKET	Bent	280.00 FL	*280.00 FL
24	1		*ENGINE COVER	Cut	350.00 FL	*350.00 FL
25	1		*AIR FULTER BOX COVER	Cut	150.00 FL	*150.00 FL
26	1		*MAIN STAND	Cut	145.00 FL	*145.00 FL
27	1		*SIDE STAND	Cut	95.00 FL	*95.00 FL
28	1		*REAR MUDGUARD	Not Necessary	148.00 FL	*- FL
29	1		*UNDER SEAT PANEL	Distorted	130.00 FL	*130.00 FL
30	1		*C.D.I UNIT	Cracked	320.00 FL	*320.00 FL
31	1		*MASTER KEY SET ASSY	Repair	1,389.00 FL	*- FL
32	1		*SET FAIRING COVER	Broken	1,150.00 FL	*1,150.00 FL
33	1		*METER ASSY	Cracked	850.00 FL	*785.00 FL
34	1		*FRONT BRAKE CALIPER	Bent / Jammed	325.00 FL	*325.00 FL
35	1		*BATTERY TRAY	Distorted	185.00 FL	*185.00 FL
36	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
37	1		*FORK OIL SEAL	Necessary	28.00 FS	*28.00 FS
38	1		*SET STEERING CONE	Necessary	120.00 FS	*120.00 FS
39	1		*HELMET	Repair	100.00 FS	*- FS
40	1		*X MAX EMBLEM	Necessary	60.00 FS	*60.00 FS
41	1		*BATTERY (50%)	Damaged	80.00 FS	*40.00 FS
42	1		*COOLANT	Necessary	18.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,392.00	9,272.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,095.60	897.90
Total Parts (\$\$)	10,296.40	8,374.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	350.00
4	TO RESPRAY PAINTING	New	800.00	500.00
5	TO REPAIR BODY FRAME	New	450.00	0.00
Gross Labour Cost (\$\$)			1,760.00	885.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >