

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2007456

INV Date 09/11/2020

Reference CC4/FCI20005703/Eka3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLC 586T

Insured Veh. SH 9287M

Claim No. D20002100MFSH/1

Policy No. D-20094922MFSH

Accident Date 09/05/2020

Inspection Date 14/05/2020

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 500.00 |
| Subtotal | 500.00 |
| GST (7%) | 35.00 |
| Grand Total | 535.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | | | |
|---|---|--------------------------------|--------------------|------------|--|--|--|--|
| MS F | IS FIRST CAPITAL INSURANCE LTD Ref: CC4/FCl20005703/Eka3q2 | | | | | | | |
| 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877 | | Date: 09-11-2020 Code: FCI2 | | | | | | |
| 1. | 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | | |
| | Insured Veh. | SH 9287M | Veh. Inspected | SLC 586T | | | | |
| | Policy No. | D-20094922MFSH | Coverage (\$) | 0.00 | | | | |
| | Claim No. | D20002100MFSH/1 | Excess (\$) | 0.00 | | | | |
| | Assign From | JOANNE YONG | Assign Date | 13/05/2020 | | | | |
| 2. | | Vehicle Partic | culars & Condition | | | | | |
| | Make & Model | NISSAN QASHQAI | c.c | 1197 | | | | |
| | Engine No. | HIDDEN | Year of Reg. | 2016 | | | | |
| | Chassis No. | SJNFEAJ11U1637033 | Colour | RED | | | | |
| | Odometer | - | Steering | IN ORDER | | | | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | | | | |
| | General | GOOD | | | | | | |
| 3. | | Condition | ons of Tyres | | | | | |
| | | Size | Make | Balance | | | | |
| | R/H Front Tyre | 215/60 R17 | CONTINENTAL | 6 mm | | | | |
| | L/H Front Tyre | 215/60 R17 | CONTINENTAL | 6 mm | | | | |
| | R/H Rear Tyre | 215/60 R17 | CONTINENTAL | 6 mm | | | | |
| | L/H Rear Tyre | 215/60 R17 | CONTINENTAL | 6 mm | | | | |
| 4. | | Description | on of Damages | | | | | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE REA | AR PORTION. | | | | | |
| | DAMAGES SEE D | ETAILS. | | | | | | |
| 5. | | General | Information | | | | | |
| | Accident Date | 09/05/2020 | Inspection Date | 14/05/2020 | | | | |
| | Survey held at MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 | | | | | | | |
| | | | | | | | | |
| 5a. | | Re | emarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 586T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--------------------------------------|---------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | DENTED | 755.50 | 755.50 |
| 1 | REAR BUMPER REINFORCEMENT | BENT | 674.00 | 619.00 |
| 1 | REAR BUMPER BRACKET LH | BENT | 133.80 | 133.80 |
| 1 | REAR BUMPER BRACKET RH | BENT | 133.80 | 133.80 |
| 1 | REAR BUMPER SIDE RETAINER LH | BROKEN | 47.80 | 47.80 |
| 1 | REAR BUMPER SIDE RETAINER RH | BROKEN | 47.80 | 47.80 |
| 1 | REAR END PANEL | DENTED | 540.90 | 482.00 |
| 1 | REAR END PANEL TOP GARNISH | CRUSHED | 65.00 | 65.00 |
| 1 | REAR BOOT WEATHER STRIPE | NOT NECESSARY | 135.90 | - |
| 1 | REAR TAILLAMP RH | NOT NECESSARY | 737.20 | - |
| 1 | REAR TAILLAMP LH | NOT NECESSARY | 737.20 | - |
| 1 | REAR TAILGATE | DENTED | 3,542.60 | 2,938.00 |
| 1 | REAR TAILGATE LOCK | BENT | 121.80 | 121.80 |
| 1 | REAR TAILGATE LOCK CATCH | NOT NECESSARY | 31.80 | - |
| 1 | REAR TAILGATE EMBLEM LOGO | NOT NECESSARY | 52.50 | - |
| 1 | REAR TAILGATE EMBLEM QASHQAI | NECESSARY | 76.40 | 76.40 |
| 1 | REAR TAILGATE INNER TRIM BOARD | NOT NECESSARY | 331.10 | - |
| 1 | REAR TAILGATE LAMP LH | NOT NECESSARY | 571.20 | - |
| 1 | REAR TAILGATE LAMP RH | NOT NECESSARY | 571.20 | - |
| 1 | REAR BUMPER INNER SPONGE | BROKEN | 126.40 | 126.40 |
| | LESS 10% DISCOUNT | | -943.39 | -554.73 |
| | | | 8,490.51 | 4,992.57 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET REVERSE SENSOR (SN) | SHORTED | 250.00 | 200.00 |
| | SET REAR REVERSE CAMERA (SN) | NOT NECESSARY | 300.00 | - |
| | SET REAR BUMPER CLIP (SN) | NECESSARY | 80.00 | 30.00 |
| | SET REAR END PANEL GARNISH CLIP (SN) | NECESSARY | 60.00 | 20.00 |
| | FLOOR PANEL SEALANT (SN) | NOT NECESSARY | 50.00 | _ |
| | END PANEL SEALANT (SN) | NECESSARY | 50.00 | 30.00 |

Report Ref No. CC4/FCI20005703/Eka3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

5,500.00

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|----------------------------|-------------------|
| 1 | MISCELLANEOUS (SN) | NOT NECESSARY | 200.00 | - |
| | | | 990.00 | 280.00 |
| | LABOUR | | | |
| | TO CHECK ELECTRICAL WIRING . | | 80.00 | 30.00 |
| | TO REMOVE AND REFIT REVERSE SENSOR /CAMERA. | | 200.00 | 50.00 |
| | REMOVE AND REFIX REAR UPHOLSTERY . | NOT NECESSARY | 200.00 | - |
| | REPAIR AND STRAIGHTEN EXHAUST PIPE . | NOT NECESSARY | 250.00 | - |
| | REMOVE AND TRANSFER ALL REAR TAILGATE FITTING. | | 200.00 | 80.00 |
| | REMOVE AND REFIX REAR WINDSCREEN GLASS . | | 150.00 | 120.00 |
| | CHECK AND RESET FAULT CODE LIGHT ON . | NOT NECESSARY | 200.00 | - |
| | TO RESPRAY UNDERCOATING. | NOT NECESSARY | 150.00 | - |
| | APPLY ANTI RUST ON AFFECTED AREAS. | | 200.00 | 30.00 |
| | SPRAY PAINTING ON AFFECTED AREAS. | | 800.00 | 600.00 |
| | PANEL BEATING ON AFFECTED AREAS. | | 1,200.00 | 700.00 |
| | | | 3,630.00 | 1,610.00 |
| | GRAND TOTAL | | 13,110.51 | 6,882.57 |

Report Ref No. CC4/FCI20005703/Eka3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

and the second

CHEN TSUE YEE

Automotive Assessor

Simonto

HO LEONG CHUAN

Automotive Assessor



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 586T



INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 586T



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 586T







