



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2006773
INV Date 01/10/2020
Reference CC4/EQI20005706/R1ea3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SMP 3573E
Insured Veh. PC 5541S
Claim No. DM20HO00809/JT
Policy No. DMCFHQ19-000106
Accident Date 09/05/2020
Inspection Date 22/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20005706/R1ea3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX SINGAPORE 069110

Date : 01-10-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 5541S	Veh. Inspected	SMP 3573E
Policy No.	DMCFHQ19-000106	Coverage (\$)	0.00
Claim No.	DM20HO00809/JT	Excess (\$)	0.00
Assign From		Assign Date	13/05/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W.X1 SDRIVE18I	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WBAJG120605N75254	Colour	GREY
Odometer	10710	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/05/2020	Inspection Date	22/06/2020
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 3573E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
4	BLIND RIVET NUT M6 (SN)	NECESSARY	10.80	10.80
1	BOOTLID (SN)	BENT	1,236.65	1,236.65
1	RR BUMPER CARRIER (SN)	SERVICEABLE	496.35	-
1	MOUNTING SMART OPENER (SN)	SERVICEABLE	45.55	-
1	RR BUMPER LH CORNER MOUNTING (SN)	SERVICEABLE	142.65	-
1	RR BUMPER RH CORNER MOUNTING (SN)	SERVICEABLE	142.65	-
1	REAR BUMPER PANEL PRIMED (SN)	DEFORMED	903.40	903.40
1	REAR BUMPER MIDDLE TRIM PANEL (PDC)(SN)	SCRATCHED	265.65	265.65
2	EMBLEM GROMMET (SN)	NECESSARY	1.70	1.70
1	BMW PLAQUE WITH ADHESIVE FILM (SN)	NECESSARY	71.60	71.60
1	LETTERING S DRIVE 18I (SN)	NECESSARY	96.65	96.65
1	LETTERING X1 (SN)	NECESSARY	64.45	64.45
1	LOCK TRUNK LID (SN)	SERVICEABLE	229.10	-
1	BOOT LID/TAILGATE PUSH BOTTON ICAM (SN)	SERVICEABLE	48.65	-
1	LOCK PLATE (SN)	SERVICEABLE	12.40	-
1	SENSOR WIRE FOR SMART OPENER TOP (SN)	SERVICEABLE	46.30	-
1	SENSOR WIRE FOR SMART OPENER BOTTOM (SN)	SERVICEABLE	50.90	-
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)(SN)	NECESSARY	263.10	263.10
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	EXPANDING NUT (ADDITIONAL)(SN)	NECESSARY	1.00	1.00
10	BUMP STOP (ADDITIONAL)(SN)	NECESSARY	37.50	37.50
10	EXPANDING RIVET BLACK (ADDITIONAL)(SN)	NECESSARY	14.00	14.00
1	(DG) CLEANER R1 (100ML) (ADDITIONAL)(SN)	NECESSARY	26.15	26.15
1	(DG/SL) ADHESIVE PRIMER VP206 (30ML) (ADDITIONAL) (SN)	NECESSARY	27.85	27.85
			4,385.05	3,100.50
<u>LABOUR</u>				
TO REPLACE BUMPER REAR COVER AND BOOT LID.			2,550.00	1,700.00
TO SPRAY PAINT BUMPER REAR COVER AND BOOT LID.			2,006.00	1,805.00
TO REMOVE AND INSTALL REAR WINDSCREEN GLASS.			574.00	574.00
TO CONDUCT WATER LEAK TESTS.			75.00	75.00

Report Ref No. CC4/EQI20005706/R1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE BOOTLID SMART OPENER CONTROL UNIT,TO AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.		661.00	561.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			6,338.00	5,115.00
GRAND TOTAL			10,723.05	8,215.50

RECOMMENDED COST OF REPAIRS				8,215.50
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/EQI20005706/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 3573E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 3573E

RE-INSPECTION

