Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005708/QEA3Q2

**Date:** 20/04/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994043

Claimant Vehicle No: SLE7243B Insured Vehicle No: SKE8358J

Date of Loss: 04/05/2020 Nature of Claim: TP Claim No: 6089235927SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLE7243B

Make & Model: TOYOTA SIENTA, 1.5 G CVT ABS D/AIRBAG 2WD Engine No: 2NR8600230

5DR (A)

Reg. Date: 29/07/2016 (Man. Year: 2016) Chassis No: NSP1707026602

Colour: White Odometer: 219916 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,457.87	7,173.57	4,284.30	37.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	2,230.00	870.00	28.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,557.87	9,403.57	5,154.30	35.41
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	14,557.87	7,500.00	7,057.87	48.48
+ GST 7.00/7.00% (S\$)	1,019.05	525.00	494.05	48.48
Nett Amount (S\$)	15,576.92	8,025.00	7,551.92	48.48
+ Loss of Use (10.0 x S\$6	+ Loss of Use (10.0 x S\$60.00/day) (S\$) + Doc/Search Fee (S\$)  Nett Liability (S\$)			
+ Doc/Se				
Net				
Global Sum S	8,630.00			

**INSPECTION** 

Date of Assignment: 13/05/2020

Date Inspected: 13/05/2020 Inspected At: Lion City Rentals Pte Ltd (HQ)

60 Jalan Lam Huat, #04-35/36 Carros

Centre

Singapore 737569

Estimated Period of Repair: 8.0 days

Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAILGATE	Dented	1,470.00 FL	*1,250.00 FL	
2	1		*REAR TAILGATE WEATHERSTRIP	Crumpled	360.00 FL	*360.00 FL	
3	1		*REAR TAILGATE LOCK ASSY	Jammed	504.00 FL	*372.00 FL	
4	1		*REAR TAILGATE LOCK CATCH	Serviceable	64.80 FL	*- FL	
5	1		*REAR TAILGATE LH DAMPER	Serviceable	352.80 FL	*- FL	
6	1		*REAR TAILGATE RH DAMPER	Serviceable	352.80 FL	*- FL	
7	1		*REAR TAILGATE BACK DOOR TRIMBOARD	Serviceable	580.00 FL	*- FL	
8	1		*REAR TRAY LUGGAGE COMPARTMENT	Crumpled	420.00 FL	*380.00 FL	
9	1		*REAR SPARE TYRE COMPARTMENT BOX	Serviceable	400.00 FL	*- FL	
10	1		*REAR SPARE TYRE PANEL	Dented	1,200.00 FL	*899.10 FL	
11	1		*REAR TAILGATE CENTER GARNISH HOLDER	Cracked	342.00 FL	*342.00 FL	
12	1		*REAR TAILGATE TOYOTA LOGO	Necessary	60.00 FL	*60.00 FL	
13	1		*REAR LICENCE LAMP	Serviceable	120.00 FL	*- FL	
14	1		*R/R TAILLAMP	Cracked	550.00 FL	*550.00 FL	
15	1		*R/L TAILLAMP	Crumpled	550.00 FL	*550.00 FL	
16	1		*R/L TAILGATE REFLECTOR	Crumpled	380.00 FL	*380.00 FL	
17	1		*R/R TAILGATE REFLECTOR	Crumpled	380.00 FL	*380.00 FL	
18	1		*REAR END PANEL	Dented	828.00 FL	*600.00 FL	
19	1		*REAR END PANEL LOWER	Serviceable	633.60 FL	*- FL	
20	1		*REAR END PANEL TOP GARNISH	Crumpled	250.00 FL	*180.00 FL	
21	1		*REAR BUMPER COVER	Crumpled	900.00 FL	*640.00 FL	
22	1		*REAR BUMPER LH SIDE BRACKET	Broken	105.00 FL	*105.00 FL	
23	1		*REAR BUMPER RH SIDE BRACKET	Serviceable	105.00 FL	*- FL	
24	1		*REAR BUMPER LH BRACKET	Broken	90.00 FL	*90.00 FL	
25	1		*REAR BUMPER RH BRACKET	Serviceable	90.00 FL	*- FL	
26	1		*REAR BUMPER RH SUPPORT	Serviceable	88.05 FL	*- FL	
27	1		*REAR BUMPER LH SUPPORT	Serviceable	88.05 FL	*- FL	
28	1		*REAR BUMPER LH EXTENSION SIDE PAD	Repair	216.00 FL	*- FL	
29	1		*REAR BUMPER RH EXTENSION SIDE PAD	Repair	216.00 FL	*- FL	
30	1		*REAR BUMPER CENTER BLACK PAD	Crumpled	288.00 FL	*288.00 FL	
31	1		*REAR BUMPER RH REFLECTOR	Serviceable	133.20 FL	*- FL	
32	1		*REAR BUMPER LH REFLECTOR	Serviceable	133.20 FL	*- FL	
33	1		*REAR BUMPER TOW COVER	Scratched	40.00 FL	*40.00 FL	
34	1		*KEYLESS SMART BUZZER ANTENA	Serviceable	120.00 FL	*- FL	
35	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS	
36	1		*SET REVERSE SENSOR	Necessary	260.00 FS	*200.00 FS	
37	1		*WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS	
38	1		*REAR NUMBER PLATE	Necessary	60.00 FS	*35.00 FS	
39	1		*REAR TAILGATE HANDGRIP	Crumpled	60.00 FL	*45.00 FL	
40	1		*REAR WIPER COVER	Cracked	25.00 FL	*25.00 FL	
41	1		*R/L FENDER INNER TRIM BOARD	Crumpled	780.00 FL	*650.00 FL	
42	1		*R/R FENDER INNER TRIM BOARD	Crumpled	780.00 FL	*650.00 FL	
43	1		*R/L FENDER OUTER GARNISH	Crumpled	555.00 FL	*322.00 FL	
		part. S=Spcl	Nett. L=ListItemDisc.		33333.2		
		•		Sub Total (S\$)	15,110.50	9,463.10	
			- List Item Discount on L Items 25	5.00/25.00% (S\$)	3,652.63	2,289.53	
				Total Parts (S\$)	11,457.87	7,173.57	
	Report was unsubmitted during this print-out.						

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 20/4/2021

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	120.00	120.00
2	TRANSFER TAILGATE MECHANISM	New	100.00	60.00
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR BUMPER ,END PANEL AND SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS ,ALSO INCLUDE STRAIGHTENNING OF BOTH REAR CHASSIS MEMBERS AND FLOOR PANEL	New	1,200.00	1,000.00
4	TO RESPRAY REAR TAILGATE ,REAR END PANEL,SPARE TYRE PANEL ,REAR BUMPER ,ROOF TOP AND BOTH REAR FENDERS	New	1,200.00	950.00
5	TO REMOVE UPHOLSTERY ,SEATS OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	180.00	100.00
6	TO CONDUCT STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENTS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
	Gross Labour	Cost (S\$)	3,100.00	2,230.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >