

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005709/EEA3Q2

Date: 11/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900018906

Claimant
Vehicle No : GBJ9040Z **Insured Vehicle No :** SMJ2586G

Date of Loss: 05/05/2020 **Nature of Claim:** TP **Claim No:** 2021745279SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ9040Z		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2868017
Reg. Date:	30/09/2019 (Man. Year: 2019)	Chassis No:	JTFHT02P300249467
Colour:	White	Odometer:	14347 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,765.25	1,771.50	1,993.75	52.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,070.00	1,960.00	64.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,795.25	2,841.50	3,953.75	58.18
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	6,795.25	2,200.00	4,595.25	67.62
+ GST 7.00/7.00% (S\$)	475.67	154.00	321.67	67.62
Nett Amount (S\$)	7,270.92	2,354.00	4,916.92	67.62
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,676.00		

INSPECTION

Date of Assignment: 13/05/2020

Date Inspected: 14/05/2020 Inspected At:

Efficient Motor & Engineering Works
Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang
Enterprise Building
Singapore 508775

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER R/H	Dented	1,862.00 FL	*1,862.00 FL
2	1		*REAR FENDER INNER PANEL R/H	Not Necessary	1,600.00 FL	*- FL
3	1		*REAR FENDER MUDGLAP R/H	Not Necessary	135.00 FL	*- FL
4	1		*REAR STEEL RIM R/H	Bent	360.00 FL	*360.00 FL
5	1		*REAR RIM HUB CAP R/H	Cut	140.00 FL	*140.00 FL
6	1		*SLIDING DOOR RAILING R/H	Not Necessary	460.00 FL	*- FL
7	1		*SLIDING DOOR GUIDE GARNISH R/H	Not Necessary	70.00 FL	*- FL
8	1		*REAR RIM TYRE R/H	Not Necessary	95.00 FS	*- FS
9	1		*REAR FENDER INNER TRIM BOARD R/H	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,922.00	2,362.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,156.75	590.50
Total Parts (\$)	3,765.25	1,771.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND REFIX DAMAGED REAR R/H PORTION ,AFFECTED DAMAGED PORTION	New	1,200.00	80.00
2	TO PANEL BEAT AND REALIGN REAR AND SIDE PORTION	New	800.00	600.00
3	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS	New	70.00	30.00
4	TO CHECK LIGHTING & WIRING	New	80.00	30.00
5	TO SPRAY PAINTING FOR REAR PORTIONS AFFECTED PARTS	New	800.00	300.00
6	TO CHECK WATER LEAKAGE FOR ACCIDENT PORTION	New	80.00	30.00
Gross Labour Cost (S\$)			3,030.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >