



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2004152
INV Date 27/05/2020
Reference CS/AGI20005710/Kvf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SLS 419J

Insured Veh. SLD 8477S

Claim No. C10006295

Policy No.

Accident Date 10/05/2020

Inspection Date 18/05/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20005710/Kvf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRES SINGAPORE

239924

Date : 27-05-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 8477S	Veh. Inspected	SLS 419J
Policy No.		Coverage (\$)	0.00
Claim No.	C10006295	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	13/05/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU103569498	Colour	METALLIC SILVER
Odometer	273857	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/05/2020	Inspection Date	18/05/2020
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 419J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT NUMBER PLATE GARNISH	CRACKED	129.00	129.00
1	FRONT BUMPER	BUCKLED / CRACKED	450.80	450.80
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER REINFORCEMENT-UPPER	TO REPAIR SEE LABOUR	711.50	-
1	FRONT BUMPER REINFORCEMENT-LOWER	TO REPAIR SEE LABOUR	245.30	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	107.20	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	107.20	-
1	FRONT BUMPER UPPER GRILLE	DISTORTED	321.90	321.90
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	148.60	-
1	FRONT BUMPER EMBLEM	NECESSARY	87.10	87.10
1	FRONT BUMPER TOW COVER RH	SERVICEABLE	25.70	-
1	FRONT BUMPER TOW COVER LH	SERVICEABLE	25.70	-
1	FRONT BUMPER SPONGE-UPPER	SERVICEABLE	89.81	-
1	FRONT BUMPER SPONGE-LOWER	SERVICEABLE	135.70	-
1	FOG LAMP RH	SERVICEABLE	910.70	-
1	ENGINE UNDER COVER	SERVICEABLE	198.30	-
10	ENGINE UNDER COVER CLIP	NOT NECESSARY	35.00	-
1	RH FRONT FENDER UNDERSHIELD	SERVICEABLE	185.64	-
10	RH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	25.00	-
	LESS 25% DISCOUNT		-995.04	-257.20
			2,985.11	771.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	45.00	45.00
			45.00	45.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER).INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT-UPPER AND FRONT BUMPER REINFORCEMENT-LOWER.		400.00	200.00

Report Ref No. CS/AGI20005710/Kvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER).	NOT NECESSARY	400.00	220.00
	TO TUFF COAT.		50.00	-
	TO CHECK WIRING.		50.00	15.00
			900.00	435.00
GRAND TOTAL			3,930.11	1,251.60
RECOMMENDED COST OF REPAIRS				1,251.60

Report Ref No. CS/AGI20005710/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 419J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 419J

RE-INSPECTION

