

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III20005711/ESF3E2

**Date:** 21/05/2020

### REFERENCE

Insured/Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD	Policy No:	D19MFL0005549
Date of Loss:	13/05/2020	Nature of Claim:	OD
		Claim No:	MFL2020D0000931

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG6835H		
Make & Model:	NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)	Engine No:	K9KC400D057340
Reg. Date:	29/09/2017 (Man. Year: 2017)	Chassis No:	VSKYBAM20Z0146069
Colour:	White	Odometer:	80941 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	S\$45,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	APLUS 5 mm	Rear Left Side:	APLUS 5 mm
Front Right Side:	APLUS 5 mm	Rear Right Side:	APLUS 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,513.10	1,293.10	220.00	14.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	1,070.00	250.00	18.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,833.10</b>	<b>2,363.10</b>	<b>470.00</b>	<b>16.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
<b>- Excess (S\$)</b>	1,500.00	1,500.00	0.00	0.00
<b>(S\$)</b>	1,333.10	400.00	933.10	69.99
<b>+ GST 7.00/7.00% (S\$)</b>	93.32	28.00	65.32	70.00
<b>Nett Amount (S\$)</b>	<b>1,426.42</b>	<b>428.00</b>	<b>998.42</b>	<b>69.99</b>

### INSPECTION

Date of Assignment: 13/05/2020  
Date Inspected: 13/05/2020 Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)  
56 Loyang Way #06-07, Loyang Enterprise

Building  
Singapore 508775

Estimated Period of Repair: 4.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 20 May 2020)	
<b>Parts:</b>	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG6835H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH (WCP)	Dented	600.00 F	*600.00 F
2	2		*FRONT DOOR HINGE RH (WCP)	Bent	70.00 F	*70.00 F
3	1		*FRONT DOOR CHECKER RH (WCP)	Bent	28.00 F	*28.00 F
4	1		*FRONT DOOR LOCK RH (WCP)	Bent	105.00 F	*105.00 F
5	1		*FRONT DOOR POWER WINDOW RH (WCP)	Bent	60.00 F	*60.00 F
6	1		*FRONT DOOR REGULATOR MOTOR RH (WCP)	Not Necessary	200.00 F	*- F
7	1		*FRONT DOOR WEATHERSTRIP (WCP)	Torn	48.00 F	*48.00 F
8	1		*FRONT FENDER RH (WCP)	Dented	210.00 F	*210.00 F
9	1		*FRONT DOOR RH CO.REG.ADDRESS STICKER	Necessary	30.00 FS	*30.00 FS
10	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>1,381.00</b>	<b>1,181.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	132.10	112.10
<b>Total Parts (S\$)</b>	<b>1,513.10</b>	<b>1,293.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO KNOCK AND STRAIGHTEN ON ACCIDENT AREA, TO REMOVE AND REPLACE DAMAGED PARTS	New	500.00	400.00
2	TO PUTTY & SPRAY PAINTING FRONT DOOR RH, FRONT FENDER RH AND OTHER AFFECTED AREAS	New	600.00	500.00
3	TO CHECK AND RECTIFY WIRING	New	50.00	30.00
4	TO TRANSFER DOOR COMPONENTS TO NEW DOOR	New	100.00	80.00
5	TOWING FEE	New	70.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>1,320.00</b>	<b>1,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >