

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005719/T1TF3E2

Date: 21/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800014836
Claimant Vehicle No : SMC4461G	Insured Vehicle No : SLW2091K
Date of Loss: 09/05/2020	Nature of Claim: TP Claim No: 5699842948SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC4461G		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5550947
Reg. Date:	30/06/2018 (Man. Year: 2018)	Chassis No:	RU11300932
Colour:	Black	Odometer:	51941 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/05/2020	
Date Inspected:	14/05/2020 Inspected At:	Ah Koon Motor (1960) Pte Ltd (HQ) BLK 1001 BUKIT MERAH LANE 3, #01-69 Singapore 159718
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER REVERSE SENSOR	Not Working	0.00 F	*- F
4	1		*TAILGATE	Bent	0.00 F	*- F
5	1		*TAILGATE LOCK	Bent	0.00 F	*- F
6	1		*TAILGATE HONDA EMBLEM	Necessary	0.00 F	*- F
7	1		*TAILGATE VEZEL EMBLEM	Necessary	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*TAILGATE WINDSCREEN SEALANT	Necessary	0.00 F	*- F
					Total Parts (\$\$)	0.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >