Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005720/R1QF3E2

Date: 29/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100428857

Claimant Vehicle FBM8136Y Insured Vehicle No: SKV4026D

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBM8136Y

Make & Model: HONDA RS150R MANUAL, 149cc Engine No: KC27E2103219

Reg. Date: 16/04/2018 (Man. Year: 2017) Chassis No: PMKKC27A0JB100987

Colour: Multi-colour Odometer: 28512 km

Engine Capacity: 149 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-17 Rear Tyre Size: 90/70-17
Front Left Side: Maxxis 3 mm Rear Left Side: Maxxis 3 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/05/2020

Date Inspected: 13/05/2020 Inspected At: Auto Boss (HQ)

1 Soon Lee Street #03 – 33 Pioneer

Center

Singapore 627605

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty P	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRONT RIM	Repair	0.00 F	*- F
3	1		*FRONT FENDER WHEEL GUARD	Scratched	0.00 F	*- F
1	1		*FRONT BRAKE DISC	Bent	0.00 F	*- F
5	1		*FRONT BRAKE CALIPER	Jammed	0.00 F	*- F
3	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
7	1		*FRONT FORK BRACKET	Bent	0.00 F	*- F
8	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
9	1		*FRONT HEADLAMP FAIRING	Cracked	0.00 F	*- F
10	1		*FRONT COVER	Cracked	0.00 F	*- F
11	2		*FRONT WING MIRROR	Scratched	0.00 F	*- F
12	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F
13	1		*STEERING STEM	Necessary	0.00 F	*- F
14	1		*STEERING CONE	Necessary	0.00 F	*- F
15	1		*HANDLE BAR	Bent	0.00 F	*- F
16	2		*HANDLE BAR GRIP	Cut	0.00 F	*- F
17	1		*HANDLE BAR BALANCER LH	Necessary	0.00 F	*- F
18	1		*HANDLE BAR BALANCER RH	Distorted	0.00 F	*- F
19	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
20	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
21	2		*SIDE FAIRING (FRONT)	Cracked	0.00 F	*- F
22	2		*REAR FAIRING	Cracked	0.00 F	*- F
23	1		*RADIATOR	Bent	0.00 F	*- F
24	1		*RADIATOR COVER	Bent	0.00 F	*- F
25	1		*FRONT FOOT REST BRACKET	Bent	0.00 F	*- F
26	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
27	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
28	1		*REAR SUB FRAME	Repair	0.00 F	*- F
29	1		*REAR BOX	Scratched	0.00 F	*- F
30	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
31	1		*EMBLEM	Necessary	0.00 F	*- F
32	1		*STICKER	Necessary	0.00 F	*- F
33	2		*HORN	Cracked	0.00 F	*- F
34	1		*BASKET	Cracked	0.00 F	*- F
35	2		*FRT SIDE LAMP	Cracked	0.00 F	*- F
==Fra	anchise pa	art.		_		
				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >