

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 INV No. AC2004071

INV Date 21/05/2020

Reference CS/FCI20005723/Kyf3n2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLR 6594B

Insured Veh. SHC 1959S

Claim No. D20002109MFSH

Policy No.

Accident Date 10/05/2020

Inspection Date 14/05/2020

Description	Total
Survey Inspection	321.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	321.00
GST (7%)	22.47
Grand Total	343.47

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile				
MS F	MS FIRST CAPITAL INSURANCE LTD Ref : CS/FCl20005723/Kyf3n2				
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 21-05-2020 Code: FCI2			
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SHC 1959S	Veh. Inspected	SLR 6594B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D20002109MFSH	Excess (\$)	0.00	
	Assign From	JASON TEA CHEE KIAT	Assign Date	14/05/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA C-HR (A)	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No. ZYX102014912 Colour ME		METALLIC GREY		
	Odometer	244100	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	215/60 R17	YOKOHAMA	8 mm	
	L/H Front Tyre	215/60 R17	YOKOHAMA	8 mm	
	R/H Rear Tyre	215/60 R17	YOKOHAMA	9 mm	
	L/H Rear Tyre	215/60 R17	YOKOHAMA	9 mm	
4.		Description	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	BODY.		
	DAMAGES SEE D	ETAILS.			
5.		General	Information		
	Accident Date	10/05/2020	Inspection Date	14/05/2020	
	Survey held at	LIAN HER MOTORS			
	BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541.				
5a.		Re	emarks		
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6594B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT N/S DOOR ASSY	BENT	1,358.70	1,168.30
1	FRONT N/S DOOR PROTECTOR	DENTED	425.60	334.70
1	FRONT N/S DOOR FRAME BLACK STICKER	NECESSARY	85.10	85.10
1	FRONT N/S DOOR INNER LOCK	TO REPAIR SEE LABOUR	325.60	-
1	FRONT N/S DOOR WEATHERSTRIP	SERVICEABLE	197.20	-
1	FRONT N/S DOOR INNER TRIM BOARD	SERVICEABLE	487.10	-
1	FRONT N/S DOOR GLASS REGULATOR	TO REPAIR SEE LABOUR	255.60	-
1	FRONT N/S DOOR GLASS POWER WINDOW MOTOR	SERVICEABLE	425.60	-
1	REAR N/S DOOR ASSY	BENT	1,242.30	1,084.90
1	REAR N/S DOOR PROTECTOR	DENTED	385.70	322.50
1	REAR N/S DOOR FRAME BLACK STICKER	NECESSARY	75.10	75.10
1	REAR N/S DOOR INNER LOCK	TO REPAIR SEE LABOUR	305.10	-
1	REAR N/S DOOR WEATHERSTRIP	DISTORTED / CUT	175.20	175.20
1	REAR N/S DOOR INNER TRIM BOARD	MTG CRACKED	455.70	455.70
1	REAR N/S DOOR GLASS REGULATOR	DISTORTED	255.60	255.60
1	REAR N/S DOOR GLASS POWER WINDOW MOTOR	JAMMED	425.60	425.60
1	N/S ROCKER PANEL GARNISH	SERVICEABLE	546.70	-
	LESS 25% DISCOUNT		-1,856.88	-1,095.68
			5,570.62	3,287.02
	SPECIAL NETT ITEMS			
20	GARNISH CLIP @\$2.00 (SN)	NOT NECESSARY	40.00	-
			40.00	-
	LABOUR			
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF FRONT N/S DOOR INNER LOCK, FRONT N/S DOOR GLASS REGULATOR AND REAR N/S DOOR INNER LOCK.		1,000.00	500.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		1,000.00	440.00

Report Ref No. CS/FCI20005723/Kyf3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	CHECK/RECONNECT WIRING.		45.00	20.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.		120.00	60.00
	REMOVE/REFIT REAR N/S DOOR MECHANISM,GLASS TO NEW DOOR.		150.00	120.00
			2,315.00	1,140.00
	GRAND TOTAL		7,925.62	4,427.02

RECOMMENDED COST OF LUMP SUM REPAIRS		3,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI20005723/Kyf3n2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 6594B

INSPECTION

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 6594B

RE-INSPECTION











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 6594B

RE-INSPECTION





