

151 Chin Swee Road #10-03/05 Manhattan House Singapore 169876 T: +65 6955 8899 F: +65 6900 9899 E: enquiry@aplp.com.sg

We do not accept service of Court documents by fax

Our ref: AP/2020/002796/ar RECEIVED BY AIG Your ref: SMJ 5970K Claims Dept **NG CHIN KUAY** - 8 MAY 2020 I 14 Yishun Ave 9 #04-13 Singapore 768889 CL No. 214618233356003 AIG Asia Pacific Insurance Pte Ltd Insurer of SMJ 5970K AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #07-16 Singapore 079120 Attn: Motor Claim Departmen

WITHOUT PREJUDICE

**POST** 

{for your information only}

HAND

Secretary in charge: Ardiilah

Secretary's email: ardiilah@aplp.com.sg

Dear Sirs.

CLAIMANT: HSC PIPELINE ENGINEERING PTE LTD
CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 11 JANUARY 2020 AT ABOUT
10:50HRS INVOLVING MOTOR VEHICLES NO(S). SKU45E & SMJ5970K ALONG CTE ORCHARD
ROAD

We refer to the above matter.

(your ref: to be advised)

Date: 4 May 2020

We act for HSC PIPELINE ENGINEERING PTE LTD, the owner of SKU 45E.

We are instructed by our clients to claim damages against you in connection to the above-mentioned road traffic accident involving our clients' vehicle and your vehicle bearing registration number **SMJ5970K** 

We are instructed that the above-mentioned road traffic accident was caused by your negligence/ negligence of your authorised driver in the driving, management and/or control of your vehicle.

As a result of the abovementioned road traffic accident, our clients' vehicle was damaged and our clients has been put to loss and expense, particular of which are as follows:

Costs of repair

\$ 26,840.00

Loss of use

\$ 5,800.00

Pre-repair \$ 600.00 (3 days including intervening weekend x \$200.00 per day)

Loss of use/rental During repair works \$ 5,200.00 (26 days including intervening weekend x \$200.00 per day)

**Our Legal Costs** 

\$ 1,500.00



4 May 2020

Our ref: AP/2020/002796/ar

#### Disbursements (incurred to-date)

\$ 1,379.49

-	Survey report fees	\$ 1,243.00
-	GIA/LTA search/document fee	\$ 36.49
-	Other Incidentals	\$ 100.00

**Total** 

\$ 35,519.49

A copy each of the following supporting documents is enclosed:

- (a) Singapore Accident Statement of SKU 45E:
- (b) Repair bill from My Car Consultant Pte Ltd;
- (c) Loss of Rental Bill from Operating Lease Agreement;
- (d) Motor surveyor's report by WG Appraisal Services;
- (e) Survey report invoice;
- (f) GIA/LTA searches invoices;

In compliance with the pre-action protocol under the State Courts' Practice Direction 37, we had notified your insurer, **AIG ASIA PACIFIC INSURANCE PTE LTD**, of the above-mentioned road traffic accident and to the best of our knowledge, your insurer had arranged for the pre-repair inspection of our client's vehicle.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt to us within fourteen (14) days of your receipt of this letter, failing which, our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you a counterclaim against our client arising out of the above-mentioned accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

Yours faithfully,

Charles Hooh

#### PHOTOCOPY

# My Car Consultant Pte Ltd

53, Ubi Avenue 1, Paya Ubi Industrial Park, #01-33, Singapore 408934 HP: 9888 8885 (Jeremy) Email: Jeremy\_dav\_86@live.com

## INVOICE

Claimant: M/s. HSC Pipeline Engineering Pte Ltd

Date of Invoice: 24/02/2020

C/o. M/s. My Car Consultant Pte Ltd 53, Ubi Avenue 1 #01-33 Paya Ubi Industrial Park Singapore 408934

Claim Type

: Third Party

Vehicle Reg. No : SKU45E

Vehicle Make/Model : M/Benz CLA180

Date of Accident: 11/01/2020

Description

Amount (S\$)

Lump Sum Repairs As Per Recommendation.

\$ 26,840.00

**Total** 

\$ 26,840.00

Singapore Dollar: Twenty Six Thousand Eight Hundred Forty Dollars Only.



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

### INVOICE

M/s. HSC Pipeline Engineering Pte Ltd C/o. 53 Ubi Avenue 1 #01-33 Paya Ubi Industrial Park Singapore 408934

Invoice No.

: HA/2002-22

Date

: 21/02/2020

	Amount (SGD)			
Services rendere	ed for appraiser / inspection report :-			
Survey Fee				
Photographs				
Transport Fees				
Re-inspection Fe	es			
	Total:	SGD: \$ 1,243.0		
SGD Dollar :	One Thousand Two Hundred Forty Three Dollars Only.			
Our Reference	: PAS/TP/0240120			
Vehicle No.	: SKU45E			
Make & Model	: M/Benz CLA180			
Your Claim No.	: Third Party Claim			

#### Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD". Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



Business Reg. 201404434D

#### VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0240120

Date of Report

: 21/02/2020

To: M/s. HSC Pipeline Engineering Pte Ltd

Date of Assignment

: 14/01/2020

C/o. 53 Ubi Avenue 1 #01-33

Report requested by : M/s. HSC Pipeline Engineering

Paya Ubi Industrial Park

Date of Accident

: 11/01/2020

Singapore 408934

Date of Inspection

: 14/01/2020

Claim No.

: Third Party Claim

Policy No.

: -

#### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SKU45E

Engine Capacity (cc) : 1595cc

Make & Model

: M/Benz CLA180

Mileage (km)

: 107713km

Date of Registration

: 05/06/2015

Chassis / Frame No. : WDD1173422N214059

Colour

: Met. Grey

Engine No.

: 27091030661141

#### TYRE CONDITION

Front LH

Make

: 7 mm

Front RH

: 7 mm

: Pirelli

Make

: Pirelli

Rear LH Make

: 7 mm : Pirelli

Rear RH Make

: 7 mm : Pirelli

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

## PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Apparent Engine Modification

: Nil

#### PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. My Car Consultant Pte Ltd

53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934

#### ASSESSMENT

Repairer's Estimate

Revised Amount

: \$ 37,302.00 33,549.00

Less Excess

: \$

Recommended Reserve

: \$

: \$ 26,840.00 (Lump Sum)

Estimated Normal Period of Repairs

: 26 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Page 1 of 6

PAS

Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Ernail: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SKU45E

Report No.: PAS/TP/0240120

#### **GENERAL REMARKS**

WITHOUT PREJUDICE

#### THE ASSIGNMENT

The survey was conducted at M/s. My Car Consultant Pte Ltd, 53, Ubi Avenue 1, #01-33, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

#### POINT OF IMPACT

At the front and rear portions.

#### **DAMAGES**

The bonnet, front bumper, front support panel, front chassis members, front fenders, headlamps, front grilles, boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, center exhaust pipe, rear exhaust muffler, taillamps, seatbelts, etc.

Other parts were also found damaged. (See schedule for details)

#### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$33,549.00.

#### CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$26,840.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew/How

Automobile Appraiser

**MSAAA** 

Licensed Appraiser

# PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com Business Reg. 201404434D

Vehicle No: SKU45E

Report No.: PAS/TP/0240120

## APPRAISEMENT SCHEDULE

/No.	Qty	Parts Descriptions	Condition				pairer's imate (S\$)	Ass		Our ment (S\$)
1	2 ncs	Headlamp R/L	Loop Broken/Cracked \$		2,579.00	\$	5,158.00		\$	5,158.00
2	_	Frt grille emblem (Logo)	Broken/Dislodged/Missing		2,377.00	\$	134.00		\$	134.00
3	_	Frt grille emblem support	Dented/Cracked	5		\$	82.00		\$	82.00
4	_	Frt grille moulding	Dented/Cracked			\$	173.00		\$	173.00
5		Frt grille moulding chrome R/L	Necessary \$	2	79.00	\$	158.00		\$	158.0
6		Frt grille carrier	Dented/Broken	,	19.00	\$	681.00		\$	681.0
7	-	Frt bumper	Dented Dented			\$	1,393.00		\$	1,393.0
8	-	Frt bumper no.plate garnish	Dented/Deformed			\$	83.00		\$	83.0
9		Frt bumper parktronic sensor	Dented/Damaged \$	2	220.00	\$	880.00	Inco	\$	440.0
10	l pc	Frt bumper parktronic wireharness	Torn/Repair	,	220.00	- \$	482.00	2pcs		440.0
11		Frt bumper lower grille	Dented/Cracked						\$	167.0
12	1 pc	Frt bumper lower griffe	Dented/Broken			\$	157.00		\$	157.0
13	. *	Frt bumper absorber	Dented/Cracked			\$	341.00		\$	341.0
14	l pc	Frt bumper reinforcement	Dented/Bent			\$	142.00		\$	142.0
	l pc	Frt bumper reinfor. Bracket R/L			102.00	\$	334.00		\$	334.0
15 16	-	Frt air duct	LH Dented/Bent \$	)	182.00	\$	364.00		\$	182.0
	1 pc		Dented/Broken			\$	58.00		\$	58.0
17	1 pc	Frt support panel	Realign			\$	664.00		\$	1 (40.0
18	l pc	Boot lid	Dented			\$	1,648.00		\$	1,648.0
19	l pc	Boot emblem (Logo)	Necessary			\$	49.00		\$	49.0
20	l pc	Boot emblem (CLA180)	Cracked/Necessary			\$	90.00		\$	90.0
21	l pc	Boot emblem (C&C)	Necessary		0.4.00	\$	32.00		\$	32.0
22		Boot hinge R/L	Bent \$		84.00	\$	168.00		\$	168.0
23		Boot hinge cover R/L	Cracked \$	5	72.00	\$	144.00		\$	144.0
24		Boot inner lining	Torn/Deformed			\$	136.00		\$	136.0
25	l pc	Boot inner lining lower garnish	Cracked/Deformed			\$	77.00		\$	77.0
26	l pc	Boot lock control unit	Dented/Cracked			\$	585.00		\$	585.0
27	l pc	Boot lock assy	Dented/Jammed			\$	289.00		\$	289.0
28	_	Boot lock striker	Dented/Bent			\$	52.00		\$	52.0
29	_	Boot weatherstrip	Torn/Necessary			\$	211.00		\$	211.0
30	_	Taillamp R/L	Broken/Cracked \$		760.00	\$	1,520.00		\$	1,520.0
31		Taillamp panel R/L	Dented/Distorted \$	5	227.00	\$	454.00		\$	454.0
32	l pc	Rr bumper	Dented/Cracked			\$	1,179.00		\$	1,179.0
33		Rr bumper parktronic sensor	Dented/Damaged \$		220.00	\$	880.00	3pcs	\$	660.0
34		Rr bumper tow cover	Broken/Dislodged/Missing	_		\$	28.00		\$	28.0
35	1 pc	Rr bumper lower trim	Broken/Dislodged/Missing	_		\$	229.00		\$	229.0
36	1 pc	Rr bumper lower chrome trim	Broken/Dislodged/Missing	g		\$	441.00		\$	441.0
37	1 pc	Rr bumper center guide	Dented/Broken			\$	147.00		\$	147.0
38	_	Rr bumper side guide R/L	Broken/Necessary \$	3	31.00	\$	62.00		\$	62.0
39	2 pcs	Rr bumper side rail R/L	Dented/Broken \$	3	92.00	\$	184.00		\$	184.0
40	l pc	Rr bumper reinforcement	Dented			\$	605.00		\$	605.0
41	l pc	Rr fender panel LH	Dented/Distorted			\$	2,672.00		\$	2,672.0
42	2 pcs	Rr fender inner trim R/L	Tom/Deformed \$	5	229.00	\$	458.00		\$	458.0
43	1 pc	Rr fender air vent LH	Dented/Cracked			\$	42.00		\$	42.0
44	1 pc	Rr end panel	Dented			\$	924.00		\$	924.0
45	1 pc	Rr end panel inner garnish	Cracked/Deformed			\$	110.00		\$	110.0
						•	24,700.00		Ф	22,712.0



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers
Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicl	e No:	SKU45E					Report N		ГР/0240120	
S/No.	Qty	Parts Descriptions	Condition				epairer's	the second	Our	
D/110.	Q.G	1 arts Descriptions	Сопанаоп	Condition			stimate (S\$)		Assessment (S\$)	
							The second second second second	14 1 2014 11 201	and a second of the	
							24,700.00		22,712.00	
46	1 pc	Rr compartment cover lid	Dented/Distorted			\$	787.00	\$	787.00	
47	I pc	Rr floor panel trim	Torn/Deformed			\$	186.00	\$	186.00	
48	1 pc	Rr floor panel	Dented/Buckled			\$	1,473.00	\$	1,473.00	
49	l pc	Rr floor side panel LH	Dented/Distorted			\$	213.00	\$	213.00	
50	1 pc	Rr floor under cover	Broken			\$	287.00	\$	287.00	
51	1 pc	Rr exhaust muffler	Dented/Bent			\$	1,356.00	\$	1,356.00	
52	1 pc	Rr exhaust trim pipe LH	Dented			\$	350.00	\$	350.00	
53	l pc	Rr exhaust heat insulator	Dented			\$	118.00	\$	118.00	
54	2 pcs	Frt seat belt R/L	RH Jammed	\$	732.00	\$	1,464.00	\$	732.00	
55	2 pcs	Rr seat belt R/L	Jammed	\$	598.00	\$	1,196.00	\$	1,196.00	
56	1 pc	Bonnet	Dented/Repair			•	,		no. 5 & 6)	
57	2 pcs	Frt fender R/L	Dented/Repair						no. 5 & 6)	
58	1 pc	Frt support panel	Dented/Repair						0. 4, 5 & 6)	
59	1 pc	Rr fender panel RH	Dented/Repair						. ,	
60	-	Rr chassis member R/L	Dented/Repair			(	(Refer labour no. 11, 14 & 15) (Refer labour no. 11, 13, 14 & 15)			
						-	32,130.00		29,410.00	
				Less I	Discount: 10%		3,213.00	10% \$	2,941.00	
			Lis	st Parts Su		\$	28,917.00		26,469.00	
1	1 pc	Frt no.plate	Dented		S/N	ď	35.00			
2	1 set		Dented/Cracked		S/N	\$	35.00	\$	35.00	
3	1 pc	Rr windscreen sealant	Necessary		S/N	\$	50.00	\$	50.00	
4	l pc	Rr fender panel sealant LH	Necessary		S/N	\$	50.00	\$	40.00	
5	1 pc	Rr end panel sealant	Necessary			\$	50.00	\$	40.00	
6	1 pc	Rr floor panel sealant	Necessary		S/N	\$	50.00	\$	40.00	
Ü	. po	rd noor paner scarant		137 0	S/N	\$	50.00	\$	40.00	
			Specia	al Nett Su	b-Total:	\$	285.00	\$	245.00	
				Part	s Total :	\$	29,202.00	\$	26,714.00	



Vehicle No : SKU45E			Report No.: PAS/TP/0240120				
S/No.	Labour Descriptions	_	pairer's imate (S\$)		our nent (S\$)		
1	Towing.	\$	100.00	\$	85.00		
2	To remove and reinstall front electrical wiring system for necessary repairs. (Include repair front wireharness)	\$	100.00	\$	80.00		
3	To remove, replace and/or transfer front parktronic sensors to new bumper.	\$	40.00	\$	40.00		
4	To remove, reinstall intercooler radiator, a/c condenser and pipings for necessary repairs. (Include pressure test cooling system and vacuum, recharge a/c gas)	\$	220.00	\$	200.00		
5	To straighten, repair, realign on front affected area and replace damaged parts.	\$	1,000.00	\$	660.00		
6	To spray painting, blending on front affected and adjacent area.	\$	1,000.00	\$	800.00		
7	To remove and reinstall rear electrical wiring system for necessary repairs. (Include repair rear wireharness)	\$	100.00	\$	80.00		
8	To transfer boot component parts to new boot.	\$	120.00	\$	100.00		
9	To remove and reinstall rear windscreen for necessary repairs.	\$	120.00	\$	120.00		
10	To remove, replace and/or transfer rear parktronic sensors to new bumper.	\$	40.00	\$	40.00		
11	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. (Include remove roof lining & replace affected seat belts)	\$	320.00	\$	300.00		
12	To straighten, repair, realign center exhaust pipe and replace exhaust silencer.	\$	150.00	\$	120.00		
13	To conduct chassis alignments.	\$	320.00	\$	300.00		
14	To straighten, repair, realign on rear affected area and replace damaged parts.	\$	2,500.00	\$	2,200.00		
15	To spray painting, blending on rear affected and adjacent area.	\$	1,500.00	\$	1,300.00		
16	To spray anti-rust coating on new and affected panels.	\$	120.00	\$	90.00		
1 1	To inspection, diagnose, reset and perform coding programming on:- 7.1) Headlamp control unit & calibrate/focus headlamp. 7.2) Boot lock control system. 7.3) Front & rear parktronic control system.						
	7.3) Front & rear parktronic control system. 7.4) Seat belt / SRS control unit.	\$	350.00	\$	320.00		
	Labour Total:	\$	8,100.00	\$	6,835.00		

# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

Vehicle No: SKU45E

S/No.

Report No.: PAS/TP/0240120

**Labour Descriptions** 

Repairer's Estimate (S\$)

Our
Assessment (S\$)

Total (Parts & Labour):

\$ 37,302.00

\$ 33,549.00

#### For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 26,840.00

Under normal circumstances, the repairs should be completed within a reasonable period of 26 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

293 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.