			$\alpha$	LKK:	
	1 (00) /	14 AXA140 22154	1 Km m3	IDAC:	
15/5/2010	Cynthia Col CC 3 1	ASSIGNMEN'	Γ	st[11]	r×.
INS. CASE OWILES		DOI: 35 III IY	Assg Date	2/2/11/	11
V-0.000 (0.000 (2000)	Kenneth.	DOI:			
Surveyor:	Section 1				=_2
Pre-assign / CCU	ON 6277 P	Clain	n No.	314142	*
Insured Vehicle N	or The	Polic	y No		
Name of Insured	: Tan Seng Huaf	Mak	e / Model :	byota	In Local
Insured Tel No.	: HP:	1.1.1	e / Model :	long Orchar	d Houveara
~4	D.O.A;	>3/11/14 Plac	e of Accident		\$10 E
Excess Sec II :S		Accident:	0	- GIA D	EPORT VES/NO
Is driver the own	er i Lo	OI	GIA REPORT: YES	NO ; TP GIA P	EPORT YES/NO
resio Driver N	Jame / Age : TAV TWO	(V/L: YES / NO Ins	ured Liability:	% Final?	Yes / No
Driver T	el No.: 0754 1214	(V/L: (1137 110 11)	Participation of the second	12	
		·		IN IN	ISRS:
Idp ats	niene.	11 11	INSRS:	0 11	SP:
INSRS:	INSRS: WSP:	A M	WSP:	T T	el:
WSP: Trans	Cab Tel:	H D	Tel:	D L	jability:
Tel:	Liability:		Liability:	B	MKS:
Liability:	RMKS:		KIVING.		1 + 1
RMKS:			STA	GE	DATE / PIC
Date/ Time	FOR CSO ONLY:			isation:	
	s driver the owner? (YES	s / NO )		il AIG for OI GIA:	
TO N	If NO, Driver Name / Age :	Insurance Company	. Apt	letter to OI:	11.111
eathy	Driver's Own Vehicle Number:	Insurance company	Call	W.	12-14 Pashy 185
	CHOURT-NA HILDO	MAN EDITING D		er call ltr to OI:	
	- CC3[HIADO]	MASSIN KASA I		e Report	KCh
	SUN 6277P - CC3 AXA 1	CORROR KNIBEL	7.01	pare Invoice:	81
				ers: cumentation Check	List: Handler Typist
1 0 110	OLI ADMITTED FILTERING L	ANE BUT NOT THIR		Apt Ltr:	
04-12-14	OLI ADMITTED FILTERING L ON TIP'S DAMAGE SKETCH	GIVEN BY E/I SHED	T CHANGE A	thorisation To Act:	
	STILL WITHIN LANE - , IT	= INDIELY TOBE	RIAMED PLO IRE	elease Voucher:	
	LANE, THEKEFORE, WE'TH	-T LIABILITY IS NOT	IN HIS FAVOR. FI	nal Repair Bill:	
	CONFIRM WITH OF MOTH	DOUB THE FACTISTIE	WAS BEHIND, C	ar Rental Invoice:	
	(BE AWARE TIP TAXI GOT I ANY FILTERING LANE MUST BE	E SAFENOT TO CAUSE	DANGER TO L	TA / GIA :	
	VEHICLE BEHIND.	SOTHAT		Medical Bill:	
	Animor soulines			Approval Email:	m Form:
	coul of under vo	12 march		ayment Breakdow	
	The second of th	Tarror Introduction acceptance	10	Others:	
15/12/14	0 01-11 1110	to volve men	4		
15/12/14 20/12/14	0 01-11 1110	A VII & mare			r remsz
20/11/14	can of shill un	ne france		POP!	SENT
23-12-14	SENDIETER TO DI / +10			COPY	\$ <b>\$ \$ \$ \$ \$ \$ \$ \$ \$ \$</b>
20/11/14	can of shill un			CON	13/15/10/1
23-12-14	can of shill un	ne france		COM COM	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
23-12-14 23-12-14	SENDIETTER TO PI / for	ne franc		n re con	13/15/10/1
23-12-14 23-12-14	E SENDIETTER TO PI / for	ne trance orage.		n ne com	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
23-12-14 23-12-14	KIN FOR CTV FOR CTV FOR THE SUB	ne trane orage. MIT WP REPORT		n re com	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
23-12-14 23-12-14 U	KING FOR CTV F	ortage.  MIT WP REPORT	Vides .	ssed)	ptur ) o leie
23-12-14 23-12-14 U	KING FOR CTV F	otage.  MIT UP REPORT  Confirm with		ssed)	ptur ) o lie
23-12-19  23-12-19  4-10-  FINAL SETTLE  Repair Cost:	SEAD LETTER & P/I / HIS  KING FOR CITY FOR  CONTROL FUND IN IN  IS TO CLOSE FILE SUB  MENT Date:  SS A PE	orage.  MIT WP REPORT  Confirm with  Final Liability (7)  days)	Vides .	ssed)	ptur ) o lie BOLA S/N No.:
23-12-14 23-12-14 U	KING FOR CTV F	otage.  MIT UP REPORT  Confirm with	Vides .	ssed)	ptur ) o lie BOLA S/N No.:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		9607 198K GOTTING	ile			
Affi	liated to Federation Internal	tionale Des Experts En Automob	54/Krm3			
A INSURANCE SINGAPO	ORE PTE LTD	Date: 27-11-2014  Code: AXA2				
	Policy Particula	rs :- THIRD PARTY CLAIM	SHD 416T			
0.11	W 6277P	Veh. Inspected				
Insured Veh. SJ	VV 02771	Coverage (\$)	0.00			
Policy No.		Excess (\$)	0.00			
Claim No.		Assign Date	27/11/2014			
Assign From	Vehicle D	articulars & Condition				
	Venicie	c.c	0			
Make & Model		Year of Reg.				
Engine No.	IDDEN	Colour				
Chassis No.		Steering				
Odometer -		Modification				
Brakes						
General	C	onditions of Tyres				
3.		Make	Balance			
	Size		mm			
R/H Front Tyre			mm			
L/H Front Tyre			mm			
R/H Rear Tyre			mm			
L/H Rear Tyre	Des	scription of Damages				
4.	CONTROL OF THE PROPERTY OF THE					
	General Information					
5.		Inspection Date	27/11/2014			
Accident Date	23/11/2014 TRANS-CAB AUTO SE	100000000000000000000000000000000000000				
Survey held at	NO. 42 SUNGEI KADU SINGAPORE 729346	TST1				
		Remarks	DASIS			
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED O ICE TO YOUR INSTRUCT	ON A"WITHOUT PREJUDICE" TIONS, WE HAVE NOT AUTH	DRISED REPAIRS.			

#### Pei Lin

Tan Tiong Beng [tantiong.beng@axa.com.sg]

Friday, 28 November, 2014 9:41 AM admin-b@lkkauto.com; assignments@lkkauto.com; sur@lkkauto.com From: Sent:

Cynthia Loh; Kelvyna Ngian; Tan Chia Ling (PSC); Ong Eng Hong (PSC); To:

Cc:

Direct Settlement / Trans-Cab Auto / P1314142 / OD SJW6277P / TP SHD416T / 23.11.14 /

TP GIA & POLICE REPORT.pdf; TP ESTIMATE.pdf; Preliminary Advice.pdf; SJW6277P -Subject: Attachments:

231114.PDF

RISK 1 - P1314142

CLAIM RECEIVED: 27.11.14

SJW6277P (INSD) C/W SHD416T

VTP VAT

ASSESSOR - LKK 28.11.14

NCD - Y

CL 28.11.14

From: Pei Lin [mailto:Admin-a@lkkauto.com] Sent: Thursday, November 27, 2014 5:06 PM

To: Tan Tiong Beng; Winnie Ho Ping Ping; Jacy Goh Lay Ting

Cc: kathylai@lkkauto.com; vicalpeh@lkkauto.com; kklau@lkkauto.com

Subject: Direct Settlement - Acc Invl SJW 6277P (OI: AXA - TBA) & SHD 416T (TP: CC3/AXA14022154/Krm3) on

23/11/2014

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 416T at M/s Trans-Cab Auto Services Pte Ltd.

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary advice for your perusal.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Kathy and she can be contacted at DID: 6841 2928.

Thanks & Regards,

PEI LIN

LKK Auto Consultants Pte Ltd

DID: 6366 0055

Fax: 6741 4108

TRANS-CAB AUTO SERVICES PTE LTD NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 FAX NO.6366 8862 TEL NO.6287 6666 CO/GST REG NO.201019626G

SHD416T

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

ROEL Not Authorised 1 1Sm 81750/

SHD 416T - ROEL

JTDER12W503001159\*

TOYOTA

WISH 1.8 BI-FUEL

23.11.2014

\$

		Third Party Insurer:			
		PART			LIST
			¢		₹ 487.80 X
1	1	Front Bumper	\$	,	S 105.00 €
2	1	Front Bumper Lower Absorber			270.00 X
3	1	Front Bumper Reinforcement	\$		57.30
4	1	Front Bumper Side Retainer RH	9		5 ~ 672.00 X
5	1	Front Headlamp RH	9		B 698.00
6	1	Front Fender RH	9		07 307.62
7	1	Front Fender Liner RH		5	Br 79.83
8	1	Front Fender indicator lamp RH	5	5	1,295.00 X
9	1	Front Door RH	9	Þ	1,295.00 X
10	1	Front Door weatherstrip RH			
11	1	Front Side view mirror RH	5	5	16€ 722.50 X
			TOTAL S	\$	4,852.85
			25%		1,213.21
				\$	3,639.64
		Specical Nett			
	U govern	E Clip		\$	Na 35.00
	1 Se	t Front Bumper Fastener Clip		\$	20.00
		t Front Fender Liner Fastener Clip			80.00
	1	Front Door Sticker "TRANS-CAB"		\$	New 30.00 155N-
	1	CNG Sticker		\$ \$ \$	180.00 X
	1	Front tyre RH		\$	1 120.00 ×
	1	Front tyre rim RH		S	\$11/35.00
	1	Hub cap		S	SUR 250.00 /505NI
	1	Front Door Advertisement Sticker RH		Ψ.	
			TOTAL	\$	750.00
		TOT	AL PARTS	\$	4,389.64

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

1,400.00 300/

TRANS-CAB AUTO SERVICES PTE LTD NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346 TEL NO.6287 6666 FAX NO.6366 8862		ROEL	
CO/GST REG NO.201019626G SHD416T			
To Rust-Proofing Of The Affected Areas.	5	220.00	301
Putty And Spray Painting Of the Affected Portion.	\$	1,350.00	bock
	\$	120.00	15%
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	ルル 170.00	Х
TOTAL	\$	3,480.00	
Over All Total	\$	7,869.64	s S
Repair days	10 DAYS		



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Our Ref: CC3/AXA14022154/Krm3

Policy No: P1314142

08 January 2015

TAN SENG HUAT BLK 242 WESTWOOD AVENUE #09-52 Singapore 648365

Dear Sir/Madam,

# ACCIDENT INVOLVING SJW 6277P AND SHD 416T ON 23.11.2014

We refer to the above accident where we are acting for AXA Insurance Singapore Pte Ltd (AXA) to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by <a href="16/01/2015">16/01/2015</a> after we shall proceed with negotiation with Third Party claimant on the without prejudice basis and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Accordingly your No Claim Discount (NCD – if applicable) may not be preserved. However, if you are making a claim against third party and successful with 80% in your favor, our principal will re-instate your NCD.

Please call us if you have further queries.

Yours faithfully,

Kathy Lai

Case Handler

DID: 6841 2928 FAX: 6741 4108

EMAIL: kathylai@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (Motor Claims Dept)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Interna		
AXA INSURANCE SING	GAPORE PTE LTD	Ref : CC3/AXA14022	2154/Kna3s2
SHENTON WAY #27-	01SINGAPORE 068811	Date: 15-10-2015 Code: AXA2	
I.	Policy Particula	rs :- THIRD PARTY CLAI	M
Insured Veh.	SJW 6277P	Veh. Inspected	SHD 416T
Policy No.	VPA/P1314142	Coverage (\$)	0.00
Claim No.	C0323498	Excess (\$)	0.00
Assign From	00020100	Assign Date	27/11/2014
	Vehicle Pa	articulars & Condition	UESCHOOL SERVICE
2. Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTDER12W503001159	Colour	RED
Odometer	698537	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	7 mm
L/H Front Tyre	195/65 R15	FALKEN	7 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm
4.		iption of Damages	
THE VEHICLE SU	STAINED DAMAGES AT THE	O/S FRONT PORTION.	
5.		eral Information	
Accident Date	23/11/2014	Inspection Date	25/11/2014
Survey held at	TRANS-CAB AUTO SERVIO	CES PTE LTD	
100	NO. 42 SUNGEI KADUT ST SINGAPORE 729346	1	
5a.		Remarks	
A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A'CE TO YOUR INSTRUCTION	S, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.
5b.		ate Days of Repair	Mexical Party and Party
ESTIMATED NOR	RMAL PERIOD FOR REPAIR:	3 Working Da	iys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 416T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	487.80	14
1	FRONT BUMPER LOWER ABSORBER (CONSISTENT)	SERVICEABLE	105.00	-
	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	270.00	
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	DISTORTED	57.30	57.30
	FRONT HEADLAMP RH (CONSISTENT)	SERVICEABLE	672.00	-
	FRONT FENDER RH (CONSISTENT)	BENT	698.00	698.00
	FRONT FENDER LINER RH (CONSISTENT)	DISTORTED	307.62	307.62
1	FRONT FENDER INDICATOR LAMP RH (CONSISTENT)	BROKEN	79.83	79.83
1	FRONT DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,295.00	-
1	FRONT DOOR WEATHERSTRIP RH (CONSISTENT)	SERVICEABLE	157.80	
	FRONT SIDE VIEW MIRROR RH (CONSISTENT)	SERVICEABLE	722.50	
15	LESS 25% DISCOUNT		-1,213.21	-285.69
			3,639.64	857.06
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (SN) (CONSISTENT)	NECESSARY	35.00	
9	SET FRONT FENDER LINER FASTENER CLIP (SN) (CONSISTENT)	NECESSARY	20.00	
1	FRONT DOOR STICKER "TRANS-CAB" (SN) (CONSISTENT)	NECESSARY	80.00	150000
8	CNG STICKER (SN) (CONSISTENT)	NECESSARY	30.00	15.00
	FRONT TYRE RH (SN) (CONSISTENT)	SERVICEABLE	180.00	
	FRONT TYRE RIM RH (SN) (CONSISTENT)	SERVICEABLE	120.00	
	1 HUB CAP (SN) (CONSISTENT)	MISSING	35.0	
13	FRONT DOOR ADVERTISEMENT STICKER RH (SN)	SCRATCHED	250.0	150.0
	(CONSISTENT)		750.0	0 315.0



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
LABOUR			
PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND FRONT DOOR RH.		1,400.00	300.00
THE RUST-PROOFING OF THE AFFECTED AREAS.		220.00	30.00
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,350.00	600.00
TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	15.00
TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	•
and the second of the second of		3,480.00	1,005.00
GRAND TOTAL		7,869.64	2,177.06
RECOMMENDED COST OF LUMP SUM REPAIRS			1,750.00
	LABOUR  PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND FRONT DOOR RH.  THE RUST-PROOFING OF THE AFFECTED AREAS.  PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.  TO CHECK ELECTRICAL LIGHTING CONCERNED.  TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.  TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	LABOUR  PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND FRONT DOOR RH.  THE RUST-PROOFING OF THE AFFECTED AREAS.  PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.  TO CHECK ELECTRICAL LIGHTING CONCERNED.  TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.  TO TRANSFER OF TIRE, RIM AND ON WHEEL  BALANCING.  RECOMMENDED COST OF LUMP SUM REPAIRS	LABOUR  PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT BUMPER REINFORCEMENT AND FRONT DOOR RH.  THE RUST-PROOFING OF THE AFFECTED AREAS.  PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.  TO CHECK ELECTRICAL LIGHTING CONCERNED.  TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.  TO TRANSFER OF TIRE, RIM AND ON WHEEL NOT NECESSARY  BALANCING.  GRAND TOTAL  Workshop (\$))  1,400.00  1,

Report Ref No. CC3/AXA14022154/Kna3s2

KONG SENG CHEONG

Licensed Appraiser

KSZ

10

HO LEONG CHUAN

**Automotive Assessor**