

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005730/UGA3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994035

Claimant
Vehicle No : GBA6679Z **Insured Vehicle No :** SLR9130L

Date of Loss: 13/05/2020 Nature of Claim: TP Claim No: 1760627197SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA6679Z		
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Engine No:	1KD1700332
Reg. Date:	10/10/2007 (Man. Year: 2007)	Chassis No:	JTFHT02P300005964
Colour:	White	Odometer:	530641 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Condor 6 mm	Rear Left Side:	Kenda 6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Kenda 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,916.90	4,981.70	4,935.20	49.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,340.00	2,690.00	66.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,946.90	6,321.70	7,625.20	54.67
Approved Total (Overridden) (S\$)		5,050.00		
Nett Amount (S\$)	13,946.90	5,050.00	8,896.90	63.79
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,417.45		
Global Sum Settlement (S\$)		5,400.00		

INSPECTION

Date of Assignment: 14/05/2020

Date Inspected: 14/05/2020 Inspected At:

Asia Motorsports Solution Pte Ltd
(HQ)
37A Everitt
Singapore 428586

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	2,250.00 FL	*2,135.20 FL
2	1		*TAILGATE EDGE WEATHERSTRIP	Twisted	375.20 FL	*368.90 FL
3	1		*TAILGATE CENTRE GARNISH	Not Necessary	289.50 FL	*- FL
4	1		*TAILGATE LOCK (TOP)	Dented / Jammed	295.20 FL	*295.20 FL
5	1		*TAILGATE LOCK (LOWER) CATCH	Not Necessary	142.60 FL	*- FL
6	2		*TAILGATE DAMPER	Not Necessary	645.40 FL	*- FL
7	2		*TAILGATE HINGES	Not Necessary	197.00 FL	*- FL
8	1		*TAILGATE THIRD BRAKE LIGHT (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	250.00 FL	*- FL
10	2		*TAILGATE SIDE RUBBER	Not Necessary	96.00 FL	*- FL
11	1		*REAR WIPER WASHER NOZZLE (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*REAR WIPER BLADE (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR WIPER MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*REAR WINDSCREEN (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*REAR WINDSCREEN RUBBER	No such part	298.20 FL	*- FL
16	2		*REAR NUMBER PLATE LAMP	Not Necessary	116.00 FL	*- FL
17	1		*REAR BUMPER	Distorted	1,120.00 FL	*566.10 FL
18	2		*REAR BUMPER SIDE RETAINER	Not Necessary	196.80 FL	*- FL
19	2		*REAR RHS & LHS CORNER PANEL	Repair	779.00 FL	*- FL
20	1		*RHS & LHS TAILLAMP	N/S Cracked	1,391.60 FL	*408.20 FL
21	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
22	1		*REAR FLOOR PANEL TOP PROTECTOR PLATE	Not Necessary	198.00 FL	*- FL
23	1		*REAR END PANEL (INNER)	Badly Dented	982.00 FL	*981.00 FL
24	1		*REAR END PANEL (OUTER)	Badly Dented	965.20 FL	*881.00 FL
25	1		*SPARE TYRE HOLDER	Serviceable	285.50 FL	*- FL
26	1		*REAR EXHAUST SILENCER ASSEMBLY	Not Necessary	782.00 FL	*- FL
27	4		*REAR EXHAUST SILENCER PIPE MOUNTINGS	Not Necessary	98.00 FL	*- FL
28	1		*TOYOTA BADGE	Necessary	72.00 FS	*45.00 FS
29	1		*70KM/HR STICKER	Necessary	30.00 FS	*10.00 FS
30	1		*8PAX STICKER	Necessary	20.00 FS	*10.00 FS
31	1		*TAILGATE COMPANY STICKER (COMPLATE)	Necessary	450.00 FS	*400.00 FS
32	1		*SET REVERSE PARKING SENSORS	Shorted	280.00 FS	*200.00 FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
35	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,855.20	6,390.60
- List Item Discount on L Items 25.00/25.00% (S\$)	2,938.30	1,408.90
Total Parts (S\$)	9,916.90	4,981.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,600.00	600.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	500.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	250.00	30.00
4	TO REMOVE/REFIT INNER TRIMS ,FITTINGS ,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	250.00	60.00
5	TO REMOVE AND REFIX REAR WINDSCREEN	New	140.00	100.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND TEST FOR PROPER FUNCTION	New	100.00	50.00
7	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSEMBLY REALIGN TO FIT AND CHECK SYSTEM FUNCTION	New	250.00	0.00
8	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	240.00	0.00
Gross Labour Cost (\$\$)			4,030.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >