

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIG.20005730/U903

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: GBA 66792 Yr Regn: 10.07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Toyota hiace

c.c

2982

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

530641

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P300005964

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

kenda

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

condor

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/5/20

D.O.I.

14/5/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

net 9428

20/5/20 we 31-7-2027 LIA 24572
confirmed L/S \$5000 with AH long

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Not Authorized
 4/5 @ 1050

5 days.

VEHICLE NO. GBA 6679Z

TOYOTA HIACE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Tailgate 2125.20	Body	2250.00	/
1	Tailgate edge weatherstrip 368.90	Trim	375.20	/
1	Tailgate centre garnish	11	289.50	X
1	Tailgate lock (top)	20km	295.20	/
1	Tailgate lock (lower) catch	11	142.60	X
2	Tailgate damper @322.70	11	645.40	X
2	Tailgate hinges @ 98.50	11	197.00	X
1	Tailgate Third brake light	REFIX 11	0.00	X
1	Tailgate Inner trim board	11	250.00	X
2	Tailgate side rubber @48.00	11	96.00	X
1	Rear wiper washer nozzle	REFIX 11	0.00	X
1	Rear wiper blade	REFIX 11	0.00	X
1	Rear wiper motor	REFIX 11	0.00	X
1	Rear windscreen	REFIX 11	0.00	X
1	Rear windscreen rubber	NS	298.20	X
2	Rear number plate lamp @58.00	11	116.00	X
1	Rear bumper 566.10	205	1120.00	/
2	Rear bumper side retainer @98.40	11	196.80	X
2	Rear RHS & LHS Corner panel @389.50	11	779.00	X
2	RHS & LHS Taillamp @695.80 408.20	11	1391.60	IPC
1	Rear floor panel	REPAIR 11	0.00	X
1	Rear floor panel top protector plate	11	198.00	X
1	Rear end panel (inner) 981.00	Body	982.00	/
1	Rear end panel (outer) 881.00	Body	965.20	/
1	Spare tyre holder	SC	285.50	X
1	Rear exhaust silencer assembly	11	782.00	X
4	Rear exhaust silencer pipe mountings	11	98.00	X
			11753.20	
		less 25%	2938.30	25%
			8814.90	
	SPECIAL NETT ITEMS			S.N
1	Toyota Badge	net	72.00	45
1	70km/hr Sticker	net	30.00	10
1	8Pax sticker	net	20.00	10
1	Tailgate Company sticker (complete)	net	450.00	400
1	Reverse Parking Sensors 1set	short	280.00	200
1	Rear Windscreen Sealant	net	100.00	40
1	Rear end panel sealant	net	100.00	50
1	Rear Licence Plate	11	50.00	X
	TOTAL PARTS		9916.90	

P-5638.6
 25.2

24226.70

S.N 755.00

L-1340.00

6321.7
 5057

VEHICLE NO. GBA 6679Z TOYOTA HIACE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1600.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	500
3	To remove, refix wiring system at accident damaged areas and check for proper function	250.00	30
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	250.00	60
5	To remove and refix rear windscreen	140.00	100
6	To remove and replace reverse sensors and test for proper function	100.00	50
7	To remove and replace rear exhaust silencer assembly realign to fit and check system function	250.00	11X
8	To perform anti-rust treatment on affected areas	240.00	11X
	Labour Total :	4030.00	
	TOTAL (PARTS & LABOUR):	13946.90	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: