

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20005731/QYF3E2

Date: 11/08/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00011132004
Claimant Vehicle No :	SLA2344Y	Insured Vehicle No :	GBC9057M
Date of Loss:	30/04/2020	Nature of Claim:	TP
		Claim No:	SNM20D201882/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA2344Y	Engine No:	1ZRY208377
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X (A)	Chassis No:	MR053REH104538634
Reg. Date:	25/02/2016 (Man. Year: 2015)	Odometer:	344285 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,284.95	3,609.72	1,675.23	31.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,400.00	650.00	31.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,334.95	5,009.72	2,325.23	31.70
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	7,334.95	4,000.00	3,334.95	45.47
+ GST 7.00/7.00% (S\$)	513.45	280.00	233.45	45.47
Nett Amount (S\$)	7,848.40	4,280.00	3,568.40	45.47

INSPECTION

Date of Assignment:	07/08/2020	
Date Inspected:	14/05/2020 Inspected At:	60 Jalan Lam Huat, #04-35/36 Carros Centre
		Repairer : Lion City Rentals Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days	

Adjuster: OI SUN PIN**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2020)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA2344Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	600.30 FL	*600.30 FL
2	1		*REAR BOOT	Dented	920.30 FL	*720.00 FL
3	1		*REAR END PANEL	Dented	980.00 FL	*620.00 FL
4	1		*REAR BOOT WEATHERSTRIP	Crumpled	250.00 FL	*250.00 FL
5	1		*REAR BOOT TOYOTA LOGO	Necessary	88.00 FL	*88.00 FL
6	1		*REAR BOOT ALTIS EMBLEM	Necessary	68.00 FL	*68.00 FL
7	1		*REAR BOOT TOYOTA EMBLEM	Necessary	60.00 FL	*60.00 FL
8	1		*R/R TAILLAMP	Crumpled	880.00 FL	*480.00 FL
9	1		*R/R TAILLAMP REFLECTOR	Cracked	680.00 FL	*380.00 FL
10	1		*R/L TAILLAMP	Cracked	880.00 FL	*480.00 FL
11	1		*R/L TAILLAMP REFLECTOR	Cracked	680.00 FL	*380.00 FL
12	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
13	1		*REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS
14	1		*REAR BUMPER REINFORCEMENT	Bent	480.00 FL	*380.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,926.60	4,736.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,641.65	1,126.58
Total Parts (\$\$)	5,284.95	3,609.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING OUT REAR BOOT, END PANEL AND REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,000.00	800.00
2	TO RESPRAY REAR BOOT, REAR BUMPER AND END PANEL	New	1,000.00	600.00
3	TOWING FEE	New	50.00	0.00
Gross Labour Cost (S\$)			2,050.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >