

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20005733/AGA3Q2**Date:** 19/10/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900264619
Claimant
Vehicle No : SLL7137M **Insured Vehicle No :** SGE88M
Date of Loss: 12/05/2020 Nature of Claim: TP Claim No: 3322984285SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL7137M**
Make & Model: TOYOTA HARRIER, 2.0 Elegance (A) Engine No: 3ZRB862875
Reg. Date: 07/03/2017 (Man. Year: 2016) Chassis No: ZSU600087101
Colour: White Odometer: 85730 km
Engine Capacity: 1986 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65R17 Rear Tyre Size: 225/65R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,833.20	7,361.90	9,471.30	56.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	2,120.00	1,150.00	35.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,103.20	9,481.90	10,621.30	52.83
Approved Total (Overridden) (S\$)		7,500.00		
Nett Amount (S\$)	20,103.20	7,500.00	12,603.20	62.69
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,227.45		
Global Sum Settlement (S\$)		8,200.00		

INSPECTION

Date of Assignment: 14/05/2020
Date Inspected: 14/05/2020 Inspected At: Sin Fatt Diesel Motor (HQ)
BLK 3020A #01-33 UBI ROAD 1
Singapore 408714
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dislodged	2,228.80 F	*1,712.00 FL
2	1		*REAR BOOT LID INNER LOCK	Jammed	408.10 F	*408.10 FL
3	1		*BOOT LID INNER TRIM BOARD	Deformed	638.20 F	*460.00 FL
4	1		*BOOT LID LOCK COVER	Cracked	186.20 F	*25.00 FL
5	1		*BOOT LID CENTRE MOULDING	Cracked	325.10 F	*325.10 FL
6	1		*REAR BOOT LID INNER RUBBER	Cut	299.10 F	*299.10 FL
7	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
8	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	166.20 F	*- FL
9	1		*REAR BOOT LID TOYOTA LOGO	Necessary	80.00 F	*80.00 FL
10	1		*HARRIER LOGO	Necessary	65.00 F	*65.00 FL
11	1		*BOOT LID SIDE REFLECTOR	O/S Cracked	850.40 F	*425.20 FL
12	2		*REAR TAIL LAMP	Not Necessary	1,376.40 F	*- FL
13	4		*REAR TAIL LAMP CLIPS	Not Necessary	51.60 F	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	310.40 F	*310.40 FL
15	1		*REAR BUMPER REINFORCEMENT	Not Necessary	795.90 F	*- FL
16	2		*REAR BUMPER SIDE BRACKET	Not Necessary	224.20 F	*- FL
17	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
18	1		*REAR BUMPER INNER SPONGE	Cracked	269.90 F	*137.00 FL
19	1		*REAR BUMPER	Deformed	1,525.50 F	*1,343.00 FL
20	1		*REAR BUMPER LOWER COVER	Deformed	535.20 F	*535.20 FL
21	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	136.40 F	*- FL
22	1		*REAR END PANEL	Dented	628.00 F	*628.00 FL
23	1		*END PANEL TOP GARNISH	Deformed	285.10 F	*285.10 FL
24	1		*END PANEL LOWER GARNISH	Not Necessary	265.10 F	*- FL
25	1		*END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
26	1		*REAR SPARE TYRE PANEL	Repair	1,655.20 F	*- FL
27	1		*REAR FLOOR PANEL TOP SEALANT	Not Necessary	250.00 F	*- FL
28	1		*REAR FLOOR PANEL TOP COVER	Deformed	855.20 F	*509.00 FL
29	1		*REAR FLOOR PANEL TOP COVER INNER	Deformed	502.00 F	*502.00 FL
30	1		*SPARE TYRE LOCK SCREW	Bent	52.00 F	*52.00 FL
31	1		*REAR END PANEL ANTENNA	Cracked	158.00 F	*158.00 FL
32	1		*SPARE TYRE PANEL SIDE GARNISH LH	Deformed	186.00 F	*186.00 FL
33	1		*SPARE TYRE PANEL SIDE GARNISH RH	Deformed	209.00 F	*209.00 FL
34	1		*SPARE TYRE PANEL TRAY	Deformed	445.00 F	*445.00 FL
35	1		*SPARE TYRE PANEL SPONGE SIDE	Cracked	165.00 F	*165.00 FL
36	1		*SPARE TYRE PANEL SPONGE CENTRE	Cracked	205.00 F	*205.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,833.20	9,729.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,367.30
Total Parts (\$\$)	16,833.20	7,361.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN	New	150.00	120.00
2	GUM	New	50.00	50.00
3	TO CHECK WIRING SYSTEM	New	80.00	30.00
4	TO REMOVE & REFIX REAR CUSHION	New	120.00	80.00
5	REMOVE AND REFIX REAR REVERSE SENSOR	New	120.00	60.00
6	TUFF KOTE	New	150.00	80.00
7	PANEL BEATING	New	1,400.00	900.00
8	SPRAY PAINTING CHARGE	New	1,200.00	800.00
Gross Labour Cost (S\$)			3,270.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >