



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4140Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	BENT / DENTED	2,480.40	2,480.40
1	BOOT LID RUBBER	DEFORMED	187.40	187.40
2	BOOT LID HINGE (LH/RH) @\$71.30	NOT NECESSARY	142.60	-
2	BOOT LID ABSORBER (LH/RH) @\$86.70	NOT NECESSARY	173.40	-
1	BOOT LID LOCK UPPER	DAMAGED	224.00	224.00
1	BOOT LID 'H' EMBLEM	NECESSARY	28.00	28.00
1	EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	BOOT HANDLE	NOT NECESSARY	31.80	-
2	BOOT LID LAMP (LH/RH) @\$794.40	CRACKED	1,588.80	1,588.80
1	BOOT LID TRIMBOARD	NOT NECESSARY	259.70	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOT LID TRIMBOARD, CENTRE	NOT NECESSARY	159.60	-
2	BOOT LID TRIMBOARD SIDE (LH/RH) @\$92.50	NOT NECESSARY	185.00	-
1	BOOT LID TRIMBOARD REAR	NOT NECESSARY	124.80	-
2	REAR WINDSCREEN MOULDING @\$186.30	NECESSARY	372.60	372.60
1	REAR BUMPER	DENTED / TORN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	BROKEN	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$188.10	BENT / DENTED	376.20	376.20
1	ANTENNA ASSY-SMARTK	DENTED / MTG BROKEN	689.50	689.50
1	REAR BUMPER CENTRE MOULDING ASSY	DENTED / TORN	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	MTG BROKEN / CUT	47.50	47.50
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$85.80	SERVICEABLE	171.60	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	BENT / DEFORMED	123.85	123.85
2	REAR BUMPER SIDE UNDER (LH/RH) @\$123.10	CRACKED / TORN	246.20	246.20
1	REAR BUMPER REAR HOOK	NOT NECESSARY	94.60	-
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$82.90	NOT NECESSARY	165.80	-

Report Ref No. CC4/FCI20005741/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	SOCKET BROKEN	328.60	328.60
2	LICENCE LAMP (LH/RH) @\$85.30	NOT NECESSARY	170.60	-
1	LICENCE LAMP WIRE	NOT NECESSARY	135.80	-
2	TAIL LAMP (LH/RH) @\$870.40	MTG CRACKED	1,740.80	1,740.80
2	TAIL LAMP QUARTER PANEL (LH/RH) @\$208.90	NOT NECESSARY	417.80	-
1	REAR PANEL	BUCKLED	532.00	532.00
1	REAR PANEL GARNISH	BENT / DEFORMED	346.80	346.80
1	SPARE TYRE HOLDER	NOT NECESSARY	223.10	-
1	SPARE WHEEL LOCK NUT	CRACKED / BROKEN	89.50	89.50
1	SPARE TYRE PANEL	BUCKLED	892.50	892.50
1	MEMBER ASSY-REAR FLOOR CENTRE	NOT NECESSARY	863.50	-
2	PANEL ASSY-REAR FLOOR SIDE (LH/RH) @\$39.40	NOT NECESSARY	78.80	-
1	REAR FLOOR CHASSIS MEMBER (RH)	NOT NECESSARY	1,863.40	-
1	REAR TRAY TOOLS BOX RH	BENT / DEFORMED	675.30	675.30
1	REAR TRAY TOOLS BOX LH	BENT / DEFORMED	693.20	693.20
1	REAR TRAY LUGGS CENTER	BENT / DEFORMED	354.20	354.20
1	EXHAUST PIPE INSULATOR	BENT	235.00	235.00
1	EXHAUST SILENCER	DENTED	943.50	943.50
1	EXHAUST PIPE HANGER	NOT NECESSARY	29.20	-
1	REAR FENDER (RH)	DENTED	1,768.30	1,768.30
2	REAR FENDER SHIELD REAR PIECE (LH/RH)	NOT NECESSARY	173.60	-
1	REAR FENDER SHIELD FRT PIECE (RH)	NOT NECESSARY	165.50	-
1	REAR FENDER AIR-DUCT (RH)	NOT NECESSARY	87.30	-
1	REAR WIRING ASSY	NOT NECESSARY	1,521.50	-
1	BOOT LID GLASS, LOWER (ADDITIONAL)	CRACKED	584.90	584.90
	LESS 20% DISCOUNT		-4,883.80	-3,386.42
			19,535.20	13,545.68
	SPECIAL NETT ITEMS			
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	35.00	35.00
1	BOOT LID COMFORT CABLINK TEL NO. STICKER (SN)	NOT FITTED	30.00	-

Report Ref No. CC4/FCI20005741/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR NO. PLATE + TRIM COVER (SN)	DISLODGE	45.00	45.00
2	REAR WINDSCREEN SEALANT @\$46.00 (SN)	NECESSARY	92.00	92.00
1	REAR BUMPER RUBBER MAT (SN)	DEFORMED / NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	180.00	180.00
1	SPARE TYRE PANEL TOP COVER SILICON (SN)	NOT NECESSARY	250.00	-
1	REAR WINDSCREEN SEALANT (SN) (ADDITIONAL)	REPEATED	46.00	-
			728.00	402.00
	LABOUR			
	PANEL BEATING.		1,800.00	1,000.00
	SPRAY PAINTING CHARGE.		1,400.00	800.00
	WIRING CHARGE.		160.00	30.00
	TUFF KOTE.		160.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE / REFIX EXHAUST PIPE.		80.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
			4,700.00	2,130.00
GRAND TOTAL			24,963.20	16,077.68
RECOMMENDED COST OF REPAIRS				16,077.68

Report Ref No. CC4/FCI20005741/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.