



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20005745/Aba3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 01-10-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJB 9406A	Veh. Inspected	SJR 3651M
Policy No.	GA499191	Coverage (\$)	0.00
Claim No.	S0M02NT9	Excess (\$)	0.00
Assign From		Assign Date	14/05/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305113010	Colour	WHITE
Odometer	130221	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	SUMITOMO	6 mm
L/H Front Tyre	185/60 R15	SUMITOMO	6 mm
R/H Rear Tyre	185/60 R15	SUMITOMO	6 mm
L/H Rear Tyre	185/60 R15	SUMITOMO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/05/2020	Inspection Date	15/05/2020
Survey held at	CARWAY ENTERPRISE 53 UBI AVENUE 1 #03-01 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------