

# H L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440  
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783  
Reg No: 201000228E

## VEHICLE INSPECTION REPORT

To: Chen Sheng Xiang  
C/o: H L Cycle Pte Ltd  
No.1 Kaki Bukit Ave 6 #02-58/60  
AutoBay, Singapore 417883

Date : 1 November 2019  
Our ref : HLC/10/1901/TP

Accident Date : 28 September 2019  
Inspection Date : 02 October 2019  
Repairer Name : H L Cycle Pte Ltd  
No.1 Kaki Bukit Ave 6 #02-58/60  
AutoBay, Singapore 417883

Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No : FBC 6779 H  
Make / Model : Honda CB400  
Chassis No : NC421002158  
Engine No : NC42E1002166

Year / Capacity : 2008 / 399 cc  
Colour : Black  
Mileage : 88108

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	: Bridgestone	120/60 R17	5 mm	Sport
Rear	: Bridgestone	160/60 R17	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 78 copies

### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis  
and we have not given authorization and instruction to the repairer to proceed with the repair

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle  
and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 7,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 20 (Twenty) working days.