

SCL APPRAISER PTE LTD

Vehicle Registration No: FBC 6779 H

Our Ref No: HLC/10/1901/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front fender	Damage	\$ 196.00	\$ 196.00
1	Headlamp	Damage	\$ 380.00	\$ 380.00
1	Headlamp bracket	Damage	\$ 165.00	\$ 165.00
2	Fork inner tubes	Damage	\$ 620.00	\$ 620.00
2	Fork outer tubes	Damage	\$ 640.00	\$ 640.00
1	Fork under bracket	Damage	\$ 335.00	\$ 335.00
1	Fork upper bracket	Intact	\$ 235.00	
1	Front o/s brake disc	Damage	\$ 560.00	\$ 560.00
1	Front rim shaft	Damage	\$ 68.00	\$ 68.00
1	Front sport rim	Intact	\$ 1,100.00	
1	Meter assy	Damage	\$ 1,880.00	\$ 1,880.00
1	Handle-bar	Damage	\$ 145.00	\$ 145.00
1	Handle-bar end	Damage	\$ 30.00	\$ 30.00
1	Hand-grip (1 set)	Necessary	\$ 80.00	\$ 80.00
1	O/s side mirror	Damage	\$ 95.00	\$ 95.00
1	Brake lever	Damage	\$ 65.00	\$ 65.00
1	Front o/s signal	Damage	\$ 176.00	\$ 176.00
1	Front o/s footrest	Damage	\$ 75.00	\$ 75.00
1	Front o/s footrest bracket	Damage	\$ 245.00	\$ 245.00
1	Brake pedal	Damage	\$ 98.00	\$ 98.00
1	Rear o/s footrest	Damage	\$ 70.00	\$ 70.00
1	Exhaust pipe	Damage	\$ 1,600.00	\$ 1,600.00
1	Exhaust protector	Damage	\$ 45.00	\$ 45.00
			\$ 8,903.00	\$ 7,568.00
			<i>Less 10%</i>	<i>\$ 890.30</i>
Total Cost - List Items			\$ 8,012.70	\$ 6,811.20

SPECIAL NETT ITEMS

1	Front number plate	Damage	\$ 15.00	\$ 15.00
2	Fork oils	Necessary	\$ 30.00	\$ 30.00
2	Fork oil seals	Necessary	\$ 56.00	\$ 56.00
1	Steering cone (1 set)	Necessary	\$ 80.00	\$ 80.00
1	ERP IU	Damage	\$ 175.00	\$ 175.00
1	Rear box	Damage	\$ 950.00	\$ 950.00
1	Rear box bracket	Damage	\$ 100.00	\$ 100.00
1	Crash bar (1 set)	Damage	\$ 300.00	\$ 300.00
Total Cost - Special Nett items			\$ 1,706.00	\$ 1,706.00
Total cost of parts			\$ 9,718.70	\$ 8,517.20

Vehicle Registration No: FBC 6779 H

Our Ref No: HLC/10/1901/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 9,718.70	\$ 8,517.20

LABOUR

1	To provide towing service.	\$ 50.00	\$ 50.00
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00

GRAND TOTAL**\$ 10,328.70 \$ 9,017.20**

Vehicle Registration No: FBC 6779 H

Our Ref No: HLC/10/1901/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 7,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be void.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.



CL APPRAISER PTE LTD




Cheong K. H
Automotive Appraiser










L'APPRAISER P.T.























5. 15















2000









D
L
PRAISER
PT
&