



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBC 6779H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	SCRATCHED	196.00	196.00
1	HEADLAMP	SCRATCHED	380.00	380.00
1	HEADLAMP BRACKET	SCRATCHED	165.00	165.00
2	FORK INNER TUBES	NOT DAMAGED	620.00	-
2	FORK OUTER TUBES	NOT DAMAGED	640.00	-
1	FORK UNDER BRACKET	NOT DAMAGED	335.00	-
1	FORK UPPER BRACKET	TO REPAIR SEE LABOUR	235.00	-
1	FRONT O/S BRAKE DISC	NOT DAMAGED	560.00	-
1	FRONT RIM SHAFT	NOT DAMAGED	68.00	-
1	FRONT SPORT RIM	TO REPAIR SEE LABOUR	1,100.00	-
1	METER ASSY	CRACKED	1,880.00	1,400.00
1	HANDLE-BAR	BENT	145.00	90.00
1	HANDLE-BAR END	CUT	30.00	30.00
1	SET HANDLE-GRIP	NECESSARY	80.00	35.00
1	O/S SIDE MIRROR	BROKEN	95.00	45.00
1	BRAKE LEVER	SCRATCHED	65.00	35.00
1	FRONT O/S SIGNAL	CUT	176.00	120.00
1	FRONT O/S FOOTREST	SCRATCHED	75.00	42.00
1	FRONT O/S FOOTREST BRACKET	NOT DAMAGED	245.00	-
1	BRAKE PEDAL	CUT	98.00	98.00
1	REAR O/S FOOTREST	SCRATCHED	70.00	42.00
1	EXHAUST PIPE	SCRATCHED	1,600.00	1,200.00
1	EXHAUST PROTECTOR	SCRATCHED	45.00	45.00
	LESS 10% DISCOUNT		-890.30	-392.30
			8,012.70	3,530.70
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT DAMAGED	15.00	-
2	FORK OILS (SN)	NOT DAMAGED	30.00	-
2	FORK OIL SEALS (SN)	NOT DAMAGED	56.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET STEERING CONE (SN)	NECESSARY	80.00	80.00
1	ERP IU (SN)	CUT	175.00	175.00
1	REAR BOX (SN)	CUT	950.00	600.00
1	REAR BOX BRACKET (SN)	NOT DAMAGED	100.00	-
1	SET CRASH BAR (SN)	CUT	300.00	120.00
			1,706.00	975.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	50.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP.		80.00	50.00
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FORK UPPER BRACKET AND FRONT SPORT RIM.		480.00	320.00
			610.00	420.00
GRAND TOTAL			10,328.70	4,925.70

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,900.00
---	--	--	-----------------

Report Ref No. CS3/SMO19017325/Fvf3s2-1

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.