

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005750/AKA3Q2

Date: 06/11/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SMC3286C	Insured Vehicle No :	GBJ8960A
Date of Loss:	10/05/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001910

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC3286C	Engine No:	10XVA10939941
Make & Model:	OPEL CROSSLAND, 1.2 (A)	Chassis No:	W0V7H9ED9J4169845
Reg. Date:	29/06/2018 (Man. Year: 2018)	Odometer:	71811 km
Colour:	Blue		
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50R17	Rear Tyre Size:	215/50R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,801.60	2,813.40	9,988.20	78.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	1,815.00	2,045.00	52.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,661.60	4,628.40	12,033.20	72.22
+ GST 7.00/7.00% (S\$)	1,166.31	323.99	842.32	72.22
Nett Amount (S\$)	17,827.91	4,952.39	12,875.52	72.22
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,139.84		
Global Sum Settlement (S\$)		5,130.00		

INSPECTION

Date of Assignment:	15/05/2020		
Date Inspected:	16/06/2020	Inspected At:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Sep 2020)	
Parts:	N/A	OPEL CROSSLAND 1.2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC3286C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,580.00 FL	*- FL
2	1		*FRONT RADIATOR GRILLE	Cracked	270.00 FL	*270.00 FL
3	1		*FRONT GRILLE OPEL EMBLEM CHROME	Necessary	326.00 FL	*326.00 FL
4	1		*LH FRONT GRILLE CHROME	Necessary	212.00 FL	*212.00 FL
5	1		*RH FRONT GRILLE CHROME	Necessary	212.00 FL	*212.00 FL
6	1		*FRONT BUMPER UPPER	Repair	2,226.00 FL	*- FL
7	1		*FRONT BUMPER LOWER	Deformed	1,254.00 FL	*1,254.00 FL
8	1		*FRONT BUMPER LOWER SILL PLATE SILVER	Cut	582.00 FL	*582.00 FL
9	1		*LHF HEADLAMP	Not Necessary	2,950.00 FL	*- FL
10	1		*RHF HEADLAMP	Not Necessary	2,950.00 FL	*- FL
11	1		*FRONT BUMPER ABSORBER	Cracked	126.00 FL	*126.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Cracked	94.00 FL	*94.00 FL
13	1		*LHF BUMPER GUIDE	Not Necessary	66.00 FL	*- FL
14	1		*RHF BUMPER GUIDE	Not Necessary	66.00 FL	*- FL
15	2		*FRONT PARKING PILOT SENSOR	Not Necessary	276.00 FL	*- FL
16	2		*FRONT INNER CENTRE SENSOR	Not Necessary	246.00 FL	*- FL
17	2		*PARKING SENSOR	Not Necessary	364.00 FL	*- FL
18	2		*FRONT BUMPER OUTER SIDE	Not Necessary	350.00 FL	*- FL
19	4		*RING SENSOR	Not Necessary	24.00 FL	*- FL
20	1		*NUMBER PLATE WITH CASEMENT	Cut	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,219.00	3,121.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,417.40	307.60
Total Parts (\$\$)	12,801.60	2,813.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,950.00	650.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,650.00	1,100.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	130.00	0.00
4	TO REFOCUS HEADLAMP	New	65.00	0.00
5	TO REMOVE AND REFIT FRONT SENSOR	New	65.00	65.00
Gross Labour Cost (S\$)			3,860.00	1,815.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >