Qualified Loss Adjusters And Motor Appraisers Correspondence Address: 1 Simei St.3 #02-24 S(529890) Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0191219

Date of Report

: 28/12/2019

To: M/s. Altitude Car Leasing Pte Ltd

Date of Assignment : 10/12/2019

C/o. 48 Toh Guan Road East

Report requested by : M/s. Altitude Car Leasing Pte

#01-119 Enterprise Hub

Date of Accident

: 09/12/2019

Singapore 608586 Date of Inspection

: 10/12/2019

Claim No.

: Third Party Claim

Policy No.

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.

: SJN9817J

Engine Capacity (cc): 1794cc

Make & Model

: Toyota Wish

Mileage (km)

: 345968km Chassis / Frame No. : JTDER12W903002153

Date of Registration

: 09/03/2009

Colour

: White

Engine No.

: 1ZZ3232746

TYRE CONDITION

Front LH

: 7 mm

Front RH

: 7 mm

Make : Hifly

Make

: Hifly

Rear LH Make

: 7 mm : Hifly

Rear RH Make

: 7 mm : Hifly

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork

: Good

Paintwork

: Good

Handbrake

: Serviceable

Footbrake

: Serviceable

Steering

: Serviceable

Apparent Engine Modification

: Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location

M/s. Gold Autoworks Pte Ltd

48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586

ASSESSMENT

Repairer's Estimate

Revised Amount

12,546.30 11,105.50 \$

Less Excess

\$

Recommended Reserve

: \$

8,880.00 (Lump Sum)

Estimated Normal Period of Repairs

: 10 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited. Page 1 of 4

Business Reg. 201404434D

Vehicle No: SJN9817J

Report No. : PAS/TP/0191219

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Gold Autoworks Pte Ltd, 48, Toh Guan Road East, #01-119, Enterprise Hub, Singapore 608586.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the LHR portion.

DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, LHR chassis member, LHR fender, LHR fender inner panel, LHR wheel house, rear windscreen, LHR quarter glass, LH taillamp etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$11,105.50.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$8,880.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser