

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19018660/GQF3E2-1

Date: 20/05/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30440119011

Claimant Vehicle No : SFY1432C

Insured Vehicle No : SLB6875A

Date of Loss: 20/10/2019

Nature of Claim: TP

Claim No: SNM19D204989C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFY1432C**

Make & Model: FORD S-MAX, 2.0 (A)

Engine No: BP38701

Reg. Date: 23/03/2012 (Man. Year: 2012)

Chassis No: WF0SXXGBWSBP38701

Colour: Black

Odometer: 131478 km

Engine Capacity: 1999 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R18

Rear Tyre Size: 225/45Z R18

Front Left Side: Habilead 5 mm

Rear Left Side: Habilead 5 mm

Front Right Side: Habilead 5 mm

Rear Right Side: Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,495.10	2,995.36	27,499.74	90.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,220.00	1,580.00	56.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,295.10	4,215.36	29,079.74	87.34
Approved Total (Overridden) (S\$)		3,350.00		
Nett Amount (S\$)	33,295.10	3,350.00	29,945.10	89.94

INSPECTION

Date of Assignment: 22/10/2019

Date Inspected: 22/10/2019 Inspected At:

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @
KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 May 2020)

Parts: M1-MPV FORD S-MAX 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFY1432C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,171.00 F	*- FL
2	2		*TAILGATE HINGE	Serviceable	374.00 F	*- FL
3	2		*TAILGATE DAMPER	Serviceable	390.00 F	*- FL
4	1		*TAILGATE OUTER COVER	Serviceable	788.00 F	*- FL
5	1		*TAILGATE OUTER COVER CENTRE EMBLEM	Serviceable	54.00 F	*- FL
6	1		*TAILGATE OUTER COVER SIDE EMBLEM	Serviceable	65.00 F	*- FL
7	1		*TAILGATE FORD EMBLEM	Necessary	162.00 F	*138.00 FL
8	1		*TAILGATE OUTER GARNISH	Serviceable	458.00 F	*- FL
9	1		*TAILGATE OUTER GARNISH HANDLE	Serviceable	186.00 F	*- FL
10	2		*REAR NUMBER PLATE LAMPS	Serviceable	216.00 F	*- FL
11	1		*TAILGATE WEATHER STRIP	Serviceable	296.00 F	*- FL
12	1		*TAILGATE INNER LOCK ASSEMBLY	Serviceable	286.00 F	*- FL
13	1		*TAILGATE INNER LOCK STRIKER	Serviceable	154.00 F	*- FL
14	1		*TAILGATE INNER LOCK ASSEMBLY SWITCH	Serviceable	389.00 F	*- FL
15	1		*TAILGATE INNER LOCK ASSEMBLY SENSOR	Serviceable	354.00 F	*- FL
16	1		*TAILGATE INNER TRIM BOARD	Serviceable	1,873.10 F	*- FL
17	1		*TAILGATE WINDSCREEN GLASS MOULDING	Serviceable	321.00 F	*- FL
18	2		*TAILGATE LAMP	Serviceable	1,084.00 F	*- FL
19	2		*TAILLAMP	Serviceable	1,596.00 F	*- FL
20	2		*TAILLAMP PANEL	Serviceable	332.00 F	*- FL
21	1		*REAR BUMPER UPPER	Damaged	1,650.00 F	*950.00 FL
22	1		*REAR BUMPER LOWER	Serviceable	752.00 F	*- FL
23	1		*REAR BUMPER TOW COVER	Serviceable	85.00 F	*- FL
24	2		*REAR BUMPER SIDE RETAINER	Serviceable	170.00 F	*- FL
25	2		*REAR BUMPER REFLECTOR	Serviceable	372.00 F	*- FL
26	1		*REAR BUMPER LOWER MOULDING	Serviceable	551.00 F	*- FL
27	1		*REAR BUMPER INNER PAD	Serviceable	345.00 F	*- FL
28	1		*REAR BUMPER REINFORCEMENT	Serviceable	769.00 F	*- FL
29	2		*REAR BUMPER SIDE SUPPORT	Serviceable	308.00 F	*- FL
30	2		*REAR BUMPER CENTRE SUPPORT	Serviceable	294.00 F	*- FL
31	2		*REAR BUMPER SIDE COVER	Serviceable	968.00 F	*- FL
32	1		*END PANEL INNER	Serviceable	563.00 F	*- FL
33	1		*END PANEL OUTER	Serviceable	563.00 F	*- FL
34	1		*END PANEL TOP GARNISH	Serviceable	489.00 F	*- FL
35	1		*HEADLAMP O/S	Damaged	1,978.00 F	*950.00 FL
36	1		*HEADLAMP LOWER BRACKET O/S	Serviceable	178.00 F	*- FL
37	1		*FRONT FENDER O/S	Damaged	899.00 F	*538.20 FL
38	1		*FRONT SHOCK ABSORBER O/S	Serviceable	479.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*FRONT SHOCK ABSORBER TOP MOUNTING O/S	Serviceable	155.00 F	*- FL
40	1		*FRONT SHOCK ABSORBER TOP MOUNTING BEARING O/S	Serviceable	98.00 F	*- FL
41	1		*STEERING TIE ROD END O/S	Serviceable	253.00 F	*- FL
42	1		*SWAY BAR END LINK O/S	Serviceable	195.00 F	*- FL
43	1		*FRONT KNUCKLE O/S	Serviceable	592.00 F	*- FL
44	1		*FRONT WHEEL HUB O/S	Serviceable	356.00 F	*- FL
45	1		*FRONT LOWER ARM O/S	Serviceable	713.00 F	*- FL
46	1		*FRONT BUMPER	Damaged	1,037.00 F	*849.00 FL
47	1		*FRONT BUMPER SIDE RETAINER	N/S Serviceable / O/S Cracked	232.00 F	*58.00 FL
48	1		*DAY RUNNING LAMP O/S	Serviceable	349.00 F	*- FL
49	1		*DAY RUNNING LAMP GARNISH O/S	Serviceable	145.00 F	*- FL
50	1		*FRONT FENDER INNER COWLING O/S	Damaged	287.00 F	*148.50 FL
51	6		*END PANEL TOP GARNISH CLIPS	Serviceable	39.00 FS	*- FS
52	10		*REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
53	4		*REVERSE SENSOR	Serviceable	1,120.00 FS	*- FS
54	1		*REVERSE CAMERA	Serviceable	480.00 FS	*- FS
55	1		*END PANEL SEALANT	Serviceable	100.00 FS	*- FS
56	1		*REAR LICENCE PLATE & FRAME	Serviceable	55.00 FS	*- FS
57	1		*REAR WINDSCREEN SEALANT	Serviceable	100.00 FS	*- FS
58	10		*TAILGATE INNER TRIM CLIPS	Serviceable	65.00 FS	*- FS
59	1		*FRONT ALLOY WHEEL 18 O/S	Serviceable	550.00 FS	*- FS
60	1		*FRONT TYRE 225/45R18 O/S	Serviceable	380.00 FS	*- FS
61	8		*FRONT FENDER INNER COWLING CLIP O/S	Necessary	52.00 FS	*30.00 FS
62	10		*FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
63	1		*SUNDRIES	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 30,495.10 3,721.70
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 726.34

Total Parts (\$\$) 30,495.10 2,995.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION, TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,200.00	600.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE, REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE CHECK AND RE-ADJUST CLOSE GAP, ALIGNMENT AND WATER SEEPAGE	New	100.00	0.00
4	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK	New	150.00	0.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY REAR BUMPER, TAILGATE, END PANEL AND OTHER AFFECTED AREA / PANEL	New	1,200.00	600.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			2,800.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >