

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005764/DEA3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : FBE1840K	Insured Vehicle No :	SHA4525B
Date of Loss: 30/03/2020	Nature of Claim: TP	Claim No: MCT20030501

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE1840K		
Make & Model:	YAMAHA SPARK, 135cc	Engine No:	5YP301851
Reg. Date:	24/12/2009 (Man. Year: 2009)	Chassis No:	5YP301851
Colour:	Green	Odometer:	0 km
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	90/80 R17
Front Left Side:	Maxxis 2 mm	Rear Left Side:	Maxxis 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,721.00	1,550.00	171.00	9.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	150.00	250.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,121.00	1,700.00	421.00	19.85
Approved Total (Overridden) (S\$)		1,350.00		
Nett Amount (S\$)	2,121.00	1,350.00	771.00	36.35
+ Loss of Use (2.0 x S\$30.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,417.45		

INSPECTION

Date of Assignment:	14/05/2020	
Date Inspected:	15/05/2020 Inspected At:	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Feb 2021)	
Parts:	N/A	YAMAHA SPARK 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE1840K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP COVER	Cut	250.00 FL	*250.00 FL
2	1		*FRONT REST BRACKET	Serviceable	125.00 FL	*- FL
3	1		*FRONT REST RUBBER -LH	Serviceable	65.00 FL	*- FL
4	1		*YOSHIMURA FULL SYSTEM	Dented	1,200.00 FS	*1,200.00 FS
5	1		*REAR RH PILLION BRACKET (CHROME)	Cut	125.00 FS	*125.00 FS
					Sub Total (\$\$)	1,765.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	44.00
					Total Parts (\$\$)	1,721.00
						1,550.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO CHARGE & REPLACE PARTS ,EXHAUST SYSTEM	New	250.00	150.00
2	RECHROME	New	150.00	0.00
Gross Labour Cost (\$\$)			400.00	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >