

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

To : LKK

Attn : Bryan

Tel :

By Fax:

VEHICLE NO : FBE 1840K

Yamaha Spark LC 135

ACCIDENT DATE: 30th March 2020

Description	Qty	Quotation \$
1 Headlamp Cover <i>Cnt</i>	1	250.00 ✓
2 Front Rest Bracket <i>svc</i>	1	125.00 X
3 Front Rest Rubber - LH <i>svc</i>	1	65.00 X
4 Yoshimura Full System <i>Deamp</i>	1	1,200.00 ✓
5 Rear RH Pillion Bracket <i>chrome</i>	1	125.00 ✓

600/- SN
SN.

Sub-Total	1,765.00
Less 10%	176.50
Sub-Total	1,588.50

VEHICLE NO : FBE 1840K

Yamaha Spark LC 135

Nett items

- 1 Labour to Change & replace parts, Exhaust System
- 2 Rechrome

~~250.00~~ 150 | -

150.00 112

150-6

Sub-Total	400.00
-----------	--------

Nett Total	1.988,50
------------	----------

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

S9 TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15/05/2020 @ 17:00hrs

HA Andrew

2/sum 2 days.

nya

2KK Auto