

ASS. REC. BY:

CC4/III 20005764/Dec³

ASSIGNMENT

CDB Dec 2029

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBE 1840 K Yr Regn: Dec / 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Spark 135 c.c. 135Colour: Green A/C: Insured / Std / NI / NASp. Reading: N.A. T/Radio: Insured / Std / NI / NAEng/No: 5YP301851C/No: 5YP 301851 *Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 70/90 R17R: 90/80 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

Rear

R/Bal. 2 mm R/Bal. 2 mm

L/Bal. mm L/Bal. mm

D.O.A. 30/03/2020 D.O.I. 15/05/2020Survey held at SG 98 Mrtw AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear y n/s front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

III SHA 4525 B15/01/2021 pinch 1/3 1350 - with 2 days of rep

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

(\$)

(\$)

(\$)

(\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 669622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 18th May 2020

To : LKK

Attn: Bryan

Tel :

By Fax:

VEHICLE NO : FBE 1840K

Yamaha Spark LC 135

ACCIDENT DATE: 30th March 2020

Description	Qty	Quotation \$
1 Headlamp Cover <i>Cnt</i>	1	250.00 ✓
2 Front Rest Bracket <i>s/c</i>	1	125.00 X
3 Front Rest Rubber - LH <i>s/c</i>	1	65.00 X
4 Yoshimura Full System <i>Design</i>	1	1,200.00 ✓ 1200.00 SH.
5 Rear RH Pillion Bracket <i>chrome</i>	1	125.00 ✓ SN.

Sub-Total 1,765.00

Less 10% 176.50

Sub-Total 1,588.50

VEHICLE NO : FBE 1840K

Yamaha Spark LC 135

Nett items

- 1 Labour to Change & replace parts, Exhaust System
- 2 Rechrome

250.00 150/-

150.00 HW

Sub-Total

400.00

Nett Total

1,988.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

S9 TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15/05/2020 @ 1700hrs

NA Attached

2/sun 2 days.

ryan

LKK Auto