

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/6A120005766/4v43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

G3D5668X

at Workshop m/s

specialist

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

900

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$30500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

21/5/20

Date:

Person Contacted:

Vehicle: IN / OUT

body 3K.

Date / Time

Action / Instruction

ATA 2758 501 hrs. 7th. 10th 29/5

Veh No:

G3D5668X

Yr Regn:

29/11/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(41)

Make:

Nissan NV200

c.c 1461

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

149872

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAM 202 0090458

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/4/20

D.O.I.

20/5/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 21/5/20-Typist

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format: OD

Lump Sum I.B.I. (\$ 2900

TOTAL

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBD5668X/2005051

15th May 2020

The Manager
Motor Claim Department
Great American Insurance Company
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

Not Authorized
Lau
1/5 \$2900
Excess 700

Take photo Adher up -
5-dys.

Date of Accident : 30th April 2020
Location : Along Choa Chu Kang Crescent
Name of Policyholder : Artizen Pte Ltd
Policy No : MOMVC000008163-00-000
Vehicle No : GBD 5668 X Nissan NV200

Estimated Cost Plus/ Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	LH front door assy <i>R</i>	1	680.00	\$ 680.00 <i>X</i>
2	LH front door w/strip <i>u7</i>	1	75.00	\$ 75.00 <i>X</i>
3	LH front door tape <i>NP</i>	1	25.00	\$ 25.00 <i>X</i>
4	LH front door outer handle <i>SVC</i>	1	135.00	\$ 135.00 <i>X</i>
5	LH sliding door assy <i>Body</i>	1	750.00	\$ 750.00 <i>---</i>
6	LH sliding door outer handle <i>210</i>	1	85.00	\$ 85.00 <i>---</i>
7	LH sliding door lower roller hinge LH <i>SVC</i>	1	75.00	\$ 75.00 <i>X</i>
8	Door centre outer pillar <i>Body</i>	1	300.00	\$ 300.00 <i>---</i>
9	Rear bumper fascia <i>green</i>	1	400.00	\$ 400.00 <i>---</i>
10	Rear wheel cap <i>C47</i>	1	105.00	\$ 105.00 <i>---</i>
11	Rear bumper clips <i>u7</i>	1set	20.00	\$ 20.00 <i>---</i>
				\$ 2,650.00
Cost Plus			10%	\$ 265.00
				\$ 2,915.00
12	LH front door company sticker (s/nett) <i>u7</i>	1	28.00	\$ 28.00 <i>✓</i>
				\$ 2,943.00

1660
+ 100
2-1826
S.N-28
1-1800
3654
2923

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GBD5668X/2005051

15th May 2020

Balance b/f \$ 2,943.00

Labour Charges :-

Amounts

Cut out, renew, knocking, welding, straighten & re-align LH door centre outer pillar, LH running board panel, LH rear fender, all affected parts & etc

\$ 1,200.00 880

Remove & refix LH front door assy, door glass, glass regulator, power window motor assy, centre locking system, lock mechanism, door board & outer handle, left sliding door assy, locking mechanism, roller hinge, all affected parts & etc

\$ 280.00 100

Spray painting on damage parts

\$ 1,200.00 800

Check all wiring & lighting after repairs

\$ 35.00 20

Labour Charge

\$ 2,715.00

Total Amount

\$ 5,658.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: